



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO. : /20181122/0772	LOCATION OF FIRE:		
FIRE REPORTED ON : 22 November 2018	Along Tampines Expressway (TPE) towards Changi		
TIME OF CALL : 17:10:11 hrs	Before Exit 10, near lamp post no. 563		
STATION COVERAGE : Sengkang Fire Station	Singapore		
2. INCIDENT INFORMATION			
FIRE INVOLVED: The engine of a Toyota Estima car (SJZ2191M).			
METHOD OF EXTINGUISHMENT: By SCDF crew using a hose reel and a 38mm hose line jet from fire appliances.			
PROBABLE CAUSE OF FIRE: Accidental (Overheating at the engine compartment)			
DAMAGE SUSTAINED: As a result of the fire, the engine was damaged. The front part of the car, including the windscreen, was also damaged. The interior of the car sustained heat and smoke damage.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY:			
DANNIES ANG WEITONG for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

This is a computer generated Fire Report. No signature is required.