

來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

TAX INVOICE

EST No.: EST0020816
Tong Hock Chuan

GST Reg No: M2-0128609-3
Page: 1 of 2
Number: INV0020531
Your ref.: TP - SKB 2249X AXA
Job No.: 70016
Our ref: 18.11.36
Payment
Date: 24/11/2018

Attn

Vehicle No: SDP 3738D
Vehicle Model : Toyota Altis
Accident on ...: 21/11/2018

Not Notified
Resurvey B & paint

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Bonnet	1,028.00	25.00	<i>B1</i> 771.00 ✓
1.00	Pc	Front bonnet hinge LH	55.90	25.00	<i>R</i> 41.93 x
1.00	Pc	Front bonnet hinge RH	55.90	25.00	<i>DRY</i> 41.93 ✓
1.00	Pc	Front bumper	458.10	25.00	<i>CM</i> 343.58 ✓
1.00	Pc	Front bumper side holder RH	55.79	25.00	<i>CM</i> 41.84 ✓
1.00	Pc	Front bumper sponge	65.59	25.00	<i>CM</i> 49.19 ✓
1.00	Pc	Front fog lamp RH	248.20	25.00	186.15 ✓
1.00	Pc	Front fog lamp cover RH	119.14	25.00	<i>Red</i> 89.36 ✓
1.00	Pc	Front head lamp RH	<i>CM</i> 2,814.50	25.00	2,110.88 ✓
1.00	Pc	Front fender LH	<i>B1</i> 761.45	25.00	571.09 ✓
1.00	Pc	Front fender RH	<i>B1</i> 761.45	25.00	571.09 ✓
1.00	Pc	Front fender inner shield RH	<i>DRY</i> 137.62	25.00	103.22 ✓
1.00	Pc	Front bumper side clip RH	<i>Me</i> 3.00	25.00	2.25 ✓
16.00	Pcs	Front fender inner shield clips LH	<i>Me</i> 3.50	25.00	42.00 ✓
16.00	Pcs	Front fender inner shield clips RH	<i>Me</i> 3.50	25.00	42.00 ✓
1.00	Pc	Front washer tank	<i>Red</i> 170.38	25.00	127.79 ✓
1.00	Pc	Front support panel	<i>B1</i> 977.60	25.00	733.20 ✓
1.00	Pc	Front head lamp chrome moulding RH	<i>CM</i> 137.70	25.00	103.28 ✓
1.00	Pc	Dual VVT-i emblem LH	<i>Me</i> 39.43	25.00	29.57 ✓
1.00	Pc	Dual VVT-i emblem RH	<i>Me</i> 39.43	25.00	29.57 ✓
1.00	Pc	Front sport rim 17 inches (Original)	<i>Red</i> 1,644.50	25.00	1,233.38 ✓

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0020816
Tong Hock Chuan

Page 2 of 3
Your ref. TP - SKB 2249X AXA
Job No. 70016
Our ref 18.11.36
Payment
Date 27/11/2018

Attn

Vehicle No SDP 3738D
Vehicle Model : Toyota Altis
Accident on ... 21/11/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount	
1.00	Pc	Dual VVT-i emblem LH	39.43	25.00	29.57	✓
1.00	Pc	Dual VVT-i emblem RH	39.43	25.00	29.57	✓
1.00	Pc	Front sport rim 17 inches (Original)	1,644.50	25.00	1,233.38	✓
1.00	Pc	Front shock absorber RH	425.90	25.00	319.43	✓
1.00	Pc	Front shock absorber top mounting RH	169.82	25.00	127.37	✓
1.00	Pc	Front knuckle arm RH	441.90	25.00	331.43	✓
1.00	Pc	Front wheel bearing RH	119.43	25.00	89.57	✓
1.00	Pc	Front lower arm RH	459.43	25.00	344.57	✓
1.00	Pc	Front steering rack crossmember	1,925.30	25.00	1,443.98	✓
1.00	Pc	Front driveshaft RH	1,633.20	25.00	1,224.90	✓
Labour & Misc:						
1.00		Towing charge	70.00		70.00	✓
1.00		To check wheel alignment (computerised)	60.00		60.00	✓
1.00		To dismantle + renew steering rack cross member + transfer steering rack	300.00		300.00	✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给维修者给予快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
 GST No: M2-0128609-3
 UEN: 199407592C

ESTIMATE

EST. No EST0020816
 Tong Hock Chuan

Page 3 of 3
 Your ref. TP - SKB 2249X AXA
 Job No. 70016
 Our ref. 18.11.36
 Payment
 Date 27/11/2018

Attn

Vehicle No ... SDP 3738D
 Vehicle Model : Toyota Altis
 Accident on ... 21/11/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To dismantle + renew front suspension parts RH and drive shaft RH and press wheel bearing, etc	350.00		350.00 <i>200</i>
1.00		To straighten front body including cutting, welding; to knock dents on wheelhouse panel RH and renew above parts	900.00		900.00 <i>800</i>
1.00		To respray paint (including blending of front door RH)	1,000.00		1,000.00 <i>900</i>

Sub-Total 13,825.55
 GST 7.00% 967.79
 Total S\$ 14,793.34

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。
 除外，还有先进的 SAICO Deluxe 喷漆烘炉。
 "Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support
 dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICC
 Deluxe oven heater for re-spraying all motor vehicles."