

INSURANCE

INS. CASE OWNER:

CC6 / AIG1802

1705, K, 16/18

LKK

IDAC

Surveyor:

Kenneth

DOI:

ASSIGNMENT

17/11/18

Date / Time:

17/11/18

Registered in Merimen:

W/11/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

52N 1781P

Name of Insured:

WHITE AUTO P/L

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

17/11/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

um brenny 16/18

Driver Tel No.:

(V/L, YES / NO)

Claim No.:

616671126856

Policy No.:

CHHAAV57X

Make / Model:

W530

Place of Accident:

SPC 11/11/18

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Optima



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date / Time

17/11/18  
17/11/18

52N 1781P-X

52N 1781P-X

STAGE

DATE / PIC

Non-Reporting 1st (1st):

Non-Reporting 1st (2nd):

Non-Reporting 1st (Final):

Notification 1st (if non-pickup):

Call OI:

After call 1st to OI:

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

days Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

SS

1,926

Loss of Rental (LOR):

SS

days

Loss of Use (LOU):

SS

350

(560 x 6 days)

Loss of Income (LOI):

SS

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

7.45

Medical

SS

Disbursement:

SS

(e.g. Tow/Independent)

Legal Cost

SS

2,293.45

Total:

SS

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

2,293.45

Name 1:

OPTIMA WERKZ PPE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

X

Payee 3: (Strike if N.A.)

SS

Name 3:

X

REF: AL4

Surreyville

## ASSIGNMENT

From: Date: 23/11/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SL6 561T

at Workshop m/s:

of 9A Seungoun North Ave 5.

Insured

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Lily

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 04 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SL6 561T

Yr Regn:

09/16

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy <sup>N</sup> A900

C.C.

1496

Colour:

M. P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

178928

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NHP10

254064P

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim or

Tyre Size

Kia Forest

195/55R15

R. Kopen

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

6

mm

L/Bal.

7

mm

L/Bal.

6

mm

D.O.A.

22/11/18

D.O.I.

23/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear - all

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: Action / Instruction

26/11 File pass to Coroner

19-12-18 4/5 \$1,800/-

R(\$2,464.04/58%)

Date/Time: File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

1) \$ + RL 3)

1) Photo

1) Other

TOTAL

Report Format:

Lump Sum / L.B.I. (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18021305/Kjb3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 26-11-2018



Code : AIG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJN 1787P	Veh. Inspected	SLG 561T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	26/11/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	22/11/2018	Inspection Date	23/11/2018
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

# OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 22 NOVEMBER 2018

Third Party Insurer:

AIG

Vehicle No: SLG561T

Third Party Veh No:

SJN1787P

Model: TOYOTA AQUA

Date of Accident:

22/11/2018

Chassis: NHP102540649

## ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		By \$820.00
2	REAR TAILGATE WEATHERSTRIP	1		in \$291.80
3	REAR TAILGATE WINDSCREEN MOULDING	1		re \$35.00
4	REAR TAILGATE AQUA EMBLEM	1		re \$48.60
5	REAR TAILGATE HYBRID SYNERGY DRIVE EMBLEM	1		re \$35.00
6	REAR TAILGATE LOGO EMBLEM	1		re \$45.90
7	REAR TAILGATE OUTER GARNISH	1	map/mscat	\$201.60
8	REAR BUMPER	1		Bu \$408.31
9	REAR BUMPER REINFORCEMENT	1		R \$278.40
10	REAR BUMPER REINFORCEMENT BRACKET LH + RH	2	\$115.70	R \$231.40
11	REAR BUMPER CLIPS	1	\$5.78	re \$46.24
12	REAR END PANEL	1		R \$629.80
SUB TOTAL				\$3,072.05
LESS 25%				-\$768.01
PARTS TOTAL				\$2,304.04
NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
13	REAR BUMPER REVERSE SENSOR			NIP \$280.00
14	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER			re \$100.00
S/N TOTAL				\$380.00

### LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$600.00	400
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$600.00	400
TO TUFF KOTE / ANTI-RUST	\$60.00	301
TO CHECK WIRING & WATER LEAKAGE	\$80.00	201
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	re \$60.00	X
TO REMOVE & REINSTALL REAR WINDSCREEN AND PERFORM WATER LEAKAGE TEST AND CHECK WIRING	\$180.00	1201

LABOUR TOTAL \$1,580.00

AZMAN

TOTAL \$4,264.04

# OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 22 NOVEMBER 2018

Third Party Insurer:

AIG

Vehicle No: SLG561T

Third Party Veh No:

SJN1787P

Model: TOYOTA AQUA

Date of Accident:

22/11/2018

Chassis: NHP102540649

*Not Notified  
11/12/18*

## ESTIMATE

*4 days*

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>Bt</i> \$820.00 ✓
2	REAR TAILGATE WEATHERSTRIP	1		<i>in</i> \$291.80 X
3	REAR TAILGATE WINDSCREEN MOULDING	1		<i>in</i> \$35.00 —
4	REAR TAILGATE AQUA EMBLEM	1		<i>in</i> \$48.60 —
5	REAR TAILGATE HYBRID SYNERGY DRIVE EMBLEM	1		<i>in</i> \$35.00 ✓
6	REAR TAILGATE LOGO EMBLEM	1		<i>in</i> \$45.90 —
7	REAR TAILGATE OUTER GARNISH	1		\$201.60 7
8	REAR BUMPER	1		<i>Bu</i> \$408.31 ✓
9	REAR BUMPER REINFORCEMENT	1		\$278.40 7
10	REAR BUMPER REINFORCEMENT BRACKET LH + RH	2	\$115.70	<i>R</i> \$231.40 X
11	REAR BUMPER CLIPS	8	\$5.78	<i>in</i> \$46.24 —
12	REAR END PANEL	1		<i>R</i> \$629.80 X
SUB TOTAL				\$3,072.05
LESS 25%				-\$768.01
PARTS TOTAL				\$2,304.04

*LKK Auto Consultants hence notice the Repairer of the following:*  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
13	REAR BUMPER REVERSE SENSOR			<i>NIP</i> \$280.00 X
14	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER			<i>in</i> \$100.00 <i>405m</i>
S/N TOTAL				\$380.00

## LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$600.00	<i>400</i>
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$600.00	<i>400</i>
TO TUFF KOTE / ANTI-RUST	\$60.00	<i>30</i>
TO CHECK WIRING & WATER LEAKAGE	\$80.00	<i>20</i>
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	<i>nn</i> \$60.00	X
TO REMOVE & REINSTALL REAR WINDSCREEN AND PERFORM WATER LEAKAGE TEST AND CHECK WIRING	\$180.00	<i>120</i>

LABOUR TOTAL \$1,580.00

AZMAN

TOTAL \$4,264.04

Our Ref : SLG561T / TP#740  
Your Ref : SJN1787P

**WITHOUT PREJUDICE**

Date : 31 December 2018

**AIG ASIA PACIFIC INSURANCE PTE. LTD.**  
AIG BUILDING  
78 Shenton Way #07-16  
Singapore 079120

Attention: Motor Claims Department

**ACCIDENT INVOLVING SLG561T & SJN1787P ON 22/11/2018  
ALONG EXIT SPC AT HAVELOCK ROAD**

We refer to the above captioned.

We are claiming the below followings :

- Cost of Repair (incl. of GST )	S\$1,926.00
- Loss of Use	S\$600 (\$100.00 x 06 days)
- LTA/GIA Search Fee	S\$7.45

<b>Grand Total</b>	<b>S\$607.45</b>
--------------------	------------------

If you have any enquiries, please contact our representative, Ms. Sharon Ten & Ms. Lily at 64849919 or email [sharon@ow.sg](mailto:sharon@ow.sg) / [lily.loi@ow.sg](mailto:lily.loi@ow.sg)

All payment is to be issued direct to **Optima Werkz Pte Ltd.**

Your prompt attention is most grateful and look forward to your speedy settlement.

Yours faithfully

OPTIMA WERKZ PTE LTD  
Encl.

*This is a computer generated printout and no signature is required.*

**Joy Irene (LKKAuto)**

---

**From:** Joy Irene (LKKAuto)  
**Sent:** Saturday, 5 January 2019 3:14 PM  
**To:** 'unite.auto.sg@gmail.com'  
**Cc:** Admin A  
**Subject:** ACCIDENT INVOLVING SJN 1787P AND SLG 561T ON 22/11/2018

OUR REF: LKK: CC6/AIG18021305/Kjb3

**UNITE AUTO PTE LTD**

Policy Holder

Dear Sir,

**ACCIDENT INVOLVING SJN 1787P AND SLG 561T ON 22/11/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,  
Joy Irene | Case Handler  
LKK Auto Consultants Pte Ltd  
DID: 6841-2409 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | Fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

## AUTHORISATION TO ACT

I/We, Optima Werkz Pte Ltd ("the third party claimant") of  
9A Serangoon North Ave 5 (C) 554500 (address), owner of  
SLG 561T (vehicle no.) hereby authorize **OPTIMA WERKZ PTE LTD** ("the  
workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of  
use ("claim") for my vehicle no. SLG 561T that was damaged pursuant to the accident  
which occurred on 22/11/18 (date) along Exit SPC at Havelock Road  
\_\_\_\_\_ (location) involving vehicle no/s SJN 1787P ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they  
deem fit and the workshop is further authorized to receive payment further to settlement of  
my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a  
without prejudice and without admission of liability basis insofar as the driver/owner/insurers  
of the other vehicle/s is concerned.

Dated this 23 (day) of November (month) 20 18 (year)



Signed by "the third party claimant"  
(with chop if applicable)



Signed by "the workshop"  
(with chop)



**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, OPTIMA WERKZ PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$1,926.00 (Repair Cost), S\$360.00 (Loss of Use/Rental), S\$7.45 (Disbursement) for vehicle no. SLG 561T that was damaged pursuant to the accident which occurred on 22/11/2018 (date) along EXIT SPC AT HAVELOCK ROAD (location) involving vehicle no/s SJN 1787P. This is pursuant to the inspection conducted on 23/11/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner OPTIMA WERKZ PTE LTD ("the third party claimant") of vehicle no. SLG 561T make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLG 561T (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 27 (day) of January (month) 2019 (year)



896

Signed by appointed surveyor



Signed by "the workshop" (with chop)

# Optima Werkz Pte Ltd

9A Serangoon North Avenue 5, Singapore 554500

Tel (+65) 6484 9919 Fax: (+65) 6481 1011

Co Reg & GST No: 201212455W

## TAX INVOICE

To: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120

Tel 64191000  
Fax: 68357416

INV NO. : 121808200  
INVOICE DATE : 27/12/2018  
REF : TP#740  
VEH NO. : SLG561T  
MAKE : TOYOTA  
MODEL : SIENTA HYBRID 1.5G  
CURRENT MILEAGE:  
ADVISOR : AZMAN  
TERMS : COD

#	DESCRIPTION	QTY	UOM	U/P SGD	AMT SGD
1	LUMP SUM REPAIRS AS RECOMMENDED BY SURVEYOR	1		1,800.00	1,800.00

Remarks: DOA: 22/11/2018@ 0910HRS  
CLAIMANT: OPTIMA WERKZ P/L  
REG NO: 201212455W  
TP VEHICLE: SJN1787P

Singapore Dollars: One Thousand Nine Hundred Twenty-Six Only

Name: \_\_\_\_\_

NRIC No.: \_\_\_\_\_

Signature: \_\_\_\_\_

SUB TOTAL	SGD	1,800.00
GST 7.00%	SGD	126.00
<b>TOTAL</b>	<b>SGD</b>	<b>1,926.00</b>
Oustanding	SGD	1,926.00

I/We confirm that I/We incurred the repair costs herein and will observe my/our agreement with the repairs.  
I/We declare the repairs for above vehicle have been completed to my/our satisfaction.

- 1) New parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of one (1) year or mileage up to 30,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.
- 2) Recon Parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of six (6) months or mileage up to 10,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.
- 3) Goods sold are not refundable/returnable.

Original Invoice is only valid when the payment is acknowledge receipt by Optima Werkz Pte Ltd. Interest of 2% per month will be charged on any outstanding amount

For Optima Werkz Pte Ltd

AUTHORISED SIGNATURE(S)

&gt; Back to OneMotoring



Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701  
GST Registration No. : M4-0006529-2

Print Date/Time : 22 Nov 2018 / 11:50:06

Receipt Date/Time : 22 Nov 2018 / 11:50:06

**Tax Invoice/Receipt**

Receipt No. : ITNET-00000-181122-000900

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SJN1787P				
As at 22 Nov 2018/09:10:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SJN1787P Enquiry Fee 20181122114831930020	7.00	0.49	7.49
	<b>Sub-Total</b>	7.00	0.49	7.49
	<b>Total Before Rounding</b>	7.00	0.49	7.49
	<b>Rounding Difference</b>			0.04
	<b>Total Amount Payable</b>			7.45
Paid By				
	xxxxxxxxxxxx2799	Credit Card: Visa/MasterCard		7.45
	<b>Total</b>			7.45
	<b>Cash Change</b>			0.00
	<b>Tendered Amount</b>			7.45
	<b>Excess Refundable Amount</b>			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

**...CLAIM SUBFOLDER...(Pending for Survey Report)**























Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Nov 2018 <a href="#">Edit Reg</a>		23 Nov 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$1,800.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,800.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	UNITE AUTO PTE LTD, Co. Reg. No.: 201628892E								
Main Claimant:	OPTIMA WERKZ PTE LTD, Co. Reg. No.: 201212455W								
Vehicle Reg. No.:	SLG561T	Date of Loss:	22/11/2018 11:00 - :59 [26 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6166311268SG	Policy/Cover Note No.:	0999994597 (Third Party Only)						
Vehicle Reg. No. (Insured):	SJN1787P	Policy No. (Claimant):	SD18V017597/VPZ/R01						
		Excess:							
Repairer:	Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5, 554500 Serangoon - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by <b>MdNoor, Norsiah</b> ] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 05/12/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLG561T (6166311268SG)  
[SJN1787P]  
TP  
OPTIMA WERKZ PTE LTD  
Nov 22 2018 11:00AM  
[UNITE AUTO PTE LTD]  
Optima Werkz Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>   <a href="#">Upload Video</a>   <a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Letters/Correspondences</b>			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	 Edit	<input type="checkbox"/>
<b>Photos/Images</b>			3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/01/19 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
2	05/01/19 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
3	05/01/19 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
4	05/01/19 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
5	05/01/19 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
6	05/01/19 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
7	05/01/19 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
8	05/01/19 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
9	05/01/19 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
10	05/01/19 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
11	05/01/19 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
12	05/01/19 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
13	05/01/19 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/11/18 17:27	TP ESTIMATE- MARKED	 Load PDF	<input type="checkbox"/>
2	26/11/18 17:27	TP GIA REPORT	 Load PDF	<input type="checkbox"/>
3	30/01/19 10:18	WORKSHOP INVOICE	 Load PDF	<input type="checkbox"/>
4	30/01/19 10:18	AUTHORISATION TO ACT FORM	 Load PDF	<input type="checkbox"/>
5	30/01/19 10:18	Release Voucher	 Load PDF	<input type="checkbox"/>
6	30/01/19 10:18	LTA SEARCH	 Load PDF	<input type="checkbox"/>
7	30/01/19 10:18	LETTER TO OI	 Load PDF	<input type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	27/11/18 11:12	OI GIA REPORT	 Load PDF	<input type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>		<a href="#">Reset</a>   <a href="#">Save</a>   <a href="#">Print</a>
There are no document checklists configured.		
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>		

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJN1787P (Insd veh)	Model:	TOYOTA AQUA HYBRID 1.5
	SLG561T (TP veh)		E S CVT (A)
Date of Accident:	22/11/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	: \$	4,562.52		
Final Repair Cost	: \$	1,926.00		
Loss of Use	: \$	360.00		6.00 days at \$60.00 per day
Rental (if any)	: \$	0.00		days
LTA / GIA Search Fee	: \$	7.45		
Others:	: \$	0.00		
	: \$			
Final Settlement Sum	: \$	2,293.45		
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)				
A) For <b>Non GIA Registered Workshop</b> : Agreed Liability _____ 100 _____ (%)				
B) For <b>GIA Registered Workshop</b> : BOLA Applicable: Yes/ No BOLA Scenario No: _____				
BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)				
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Optima Werkz Pte Ltd	: \$	2,293.45
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

30 Jan  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18021305/KJB3Q2

Date: 30/01/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994597  
**Claimant Vehicle No :** SLG561T **Insured Vehicle No :** SJN1787P  
**Date of Loss:** 22/11/2018 **Nature of Claim:** TP **Claim No:** 6166311268SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SLG561T**  
 Make & Model: TOYOTA AQUA HYBRID, 1.5 E S CVT (A) Engine No: 1NZ7937238  
 Reg. Date: 20/09/2016 (Man. Year: 2016) Chassis No: NHP102540649  
 Colour: Metallic Pearl White Odometer: 178928 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15  
 Front Left Side: Kinforest 7 mm Rear Left Side: KAPSEN 4 mm  
 Front Right Side: Kinforest 7 mm Rear Right Side: KAPSEN 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,684.04	1,270.49	1,413.55	52.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,580.00	970.00	610.00	38.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,264.04</b>	<b>2,240.49</b>	<b>2,023.55</b>	<b>47.46</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,800.00</b>		
(S\$)	4,264.04	1,800.00	2,464.04	57.79
<b>+ GST 7.00/7.00% (S\$)</b>	<b>298.48</b>	<b>126.00</b>	<b>172.48</b>	<b>57.79</b>
<b>Nett Amount (S\$)</b>	<b>4,562.52</b>	<b>1,926.00</b>	<b>2,636.52</b>	<b>57.79</b>
<b>+ Loss of Use (6.0 x S\$60.00/day) (S\$)</b>		<b>360.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>7.45</b>		
<b>Nett Liability (S\$)</b>		<b>2,293.45</b>		

## INSPECTION

Date of Assignment: 23/11/2018  
 Date Inspected: 23/11/2018 Inspected At: Optima Werkz Pte Ltd (HQ)  
 9A Serangoon North Ave 5  
 Singapore 554500



Estimated Period of Repair: 4.0 days

---

**Adjuster:** KENNETH KONG

**Manager:** Joy Irene Bascao

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	820.00 FL	*820.00 FL
2	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	291.80 FL	*- FL
3	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	35.00 FL	*35.00 FL
4	1		*REAR TAILGATE AQUA EMBLEM	Necessary	48.60 FL	*48.60 FL
5	1		*REAR TAILGATE HYBRID SYNERGY DRIVE EMBLEM	Necessary	35.00 FL	*35.00 FL
6	1		*REAR TAILGATE LOGO EMBLEM	Necessary	45.90 FL	*45.90 FL
7	1		*REAR TAILGATE OUTER GARNISH	Warped / Mtg Cracked	201.60 FL	*201.60 FL
8	1		*REAR BUMPER	Buckled	408.31 FL	*408.31 FL
9	1		*REAR BUMPER REINFORCEMENT	Repair	278.40 FL	*- FL
10	2		*REAR BUMPER REINFORCEMENT BRACKET LH +RH	Repair	231.40 FL	*- FL
11	8		*REAR BUMPER CLIPS	Necessary	46.24 FL	*46.24 FL
12	1		*REAR END PANEL	Repair	629.80 FL	*- FL
13	1		*REAR BUMPER REVERSE SENSOR	No such part	280.00 FS	*- FS
14	1		*REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER	Necessary	100.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>3,452.05</b>	<b>1,680.65</b>
- List Item Discount on L Items 25.00/25.00% (S\$)	768.01	410.16

<b>Total Parts (S\$)</b>	<b>2,684.04</b>	<b>1,270.49</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	New	600.00	400.00
2	TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	New	600.00	400.00
3	TO TUFF KOTE/ANTI RUST	New	60.00	30.00
4	TO CHECK WIRING & WATER LEAKAGE	New	80.00	20.00
5	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	New	60.00	0.00
6	TO REMOVE & REINSTALL REAR WINDSCREEN AND PERFORM WATER LEAKAGE TEST AND CHECK WIRING	New	180.00	120.00
<b>Gross Labour Cost (S\$)</b>			<b>1,580.00</b>	<b>970.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >