

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 22 NOVEMBER 2018

Third Party Insurer:

AIG

Vehicle No: SLG561T

Third Party Veh No:

SJN1787P

Model: TOYOTA AQUA

Date of Accident:

22/11/2018

Chassis: NHP102540649

Not within 11 days 87

ESTIMATE

4 days

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	REAR TAILGATE	1		<i>Bt</i> \$820.00	<i>✓</i>
2	REAR TAILGATE WEATHERSTRIP	1		<i>Sm</i> \$291.80	<i>X</i>
3	REAR TAILGATE WINDSCREEN MOULDING	1		<i>me</i> \$35.00	<i>✓</i>
4	REAR TAILGATE AQUA EMBLEM	1		<i>me</i> \$48.60	<i>✓</i>
5	REAR TAILGATE HYBRID SYNERGY DRIVE EMBLEM	1		<i>me</i> \$35.00	<i>✓</i>
6	REAR TAILGATE LOGO EMBLEM	1		<i>me</i> \$45.90	<i>✓</i>
7	REAR TAILGATE OUTER GARNISH	1		\$201.60	<i>✓</i>
8	REAR BUMPER	1		<i>Bu</i> \$408.31	<i>✓</i>
9	REAR BUMPER REINFORCEMENT	1		\$278.40	<i>✓</i>
10	REAR BUMPER REINFORCEMENT BRACKET LH + RH	2	\$115.70	<i>n</i> \$231.40	<i>X</i>
11	REAR BUMPER CLIPS	8	\$5.78	<i>me</i> \$46.24	<i>✓</i>
12	REAR END PANEL	1		<i>n</i> \$629.80	<i>X</i>
				SUB TOTAL	\$3,072.05
				LESS 25%	-\$768.01
				PARTS TOTAL	\$2,304.04
				S/N TOTAL	\$380.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
13	REAR BUMPER REVERSE SENSOR			<i>nsp</i> \$280.00	<i>X</i>
14	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER			<i>me</i> \$100.00	<i>✓</i>
				S/N TOTAL	\$380.00

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$600.00	<i>4001</i>
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$600.00	<i>4001</i>
TO TUFF KOTE / ANTI-RUST	\$60.00	<i>301</i>
TO CHECK WIRING & WATER LEAKAGE	\$80.00	<i>201</i>
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	<i>nn</i> \$60.00	<i>X</i>
TO REMOVE & REINSTALL REAR WINDSCREEN AND PERFORM WATER LEAKAGE TEST AND CHECK WIRING	\$180.00	<i>1201</i>

LABOUR TOTAL \$1,580.00

AZMAN

TOTAL \$4,264.04