

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

26-Nov-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6473 T

1 pc	Bonnet ✓	\$	979.00
1 pc	Bonnet insulator X	\$	219.00
1 pc	Bonnet lock ✓	\$	36.00
1 pc	Bonnet lifter X	\$	70.00
1 pc	Bonnet hinge o/s & n/s @ \$23.00 ✓	\$	46.00
1 pc	Bonnet weatherstrip X	\$	58.00
1 pc	Bonnet cable long ✓	\$	25.00
1 pc	Bonnet cable short ✓	\$	15.00
1 pc	Bonnet strip seal centre X	\$	23.00
2 pcs	Bonnet strip seal n/s & o/s @ \$25.00 X	\$	50.00
1 pc	Bonnet grille ✓	\$	385.00
1 pc	Wiper top garnish ✓	\$	368.00
1 pc	Front windscreen ✓	\$	801.00
1 pc	Front windscreen moulding ✓	\$	87.00
1 pc	Support panel ✓	\$	645.00
1 pc	Support panel top cover ✓	\$	40.00
1 pc	Front bumper strip ✓	\$	28.00
1 pc	Front bumper ✓	\$	531.00
1 pc	Front bumper emblem ✓	\$	44.00
1 pc	Front bumper centre grille ✓	\$	174.00
1 pc	Front bumper lower stiffer ✓	\$	134.00
1 pc	Front bumper tow hook cover ✓	\$	14.00
1 pc	Front bumper lip ✓	\$	52.00
1 pc	Front bumper inner sponge ✓	\$	110.00
1 pc	Front bumper reinforcement ✓	\$	328.00
1 pc	Front bumper upper reinforcement ✓	\$	40.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 ✓	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 ✓	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00 ✓	\$	32.00
2 pcs	n/s & o/s headlamp @ \$1028.00 ✓	\$	2,056.00
2 pcs	Front bumper o/s & n/s fog lamp cover @ \$66.00 n/s X o/s ✓	\$	132.00
2 pcs	Front bumper o/s & n/s protector @ \$51.00 n/s X o/s ✓	\$	102.00
2 pcs	Horn @ \$65.00 ✓	\$	130.00

26-Nov-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6473 T

1 pc	Front O/s fender	\$	384.00
1 pc	Front o/s fender inner shield	\$	120.00
1 pc	Front o/s wheel house	\$	484.00
1 pc	Front o/s chassis member	\$	734.00
1 pc	Air con condenser	\$	805.00
1 pc	Air con discharge hose	\$	129.00
1 pc	Air con liquid pipe	\$	215.00
1 pc	Suction and liquid tube	\$	619.00
1 pc	Radiator	\$	669.00
1 pc	Radiator top mounting @\$18.00	\$	36.00
1 pc	Intercooler	\$	800.00
1 pc	Blower assy	\$	596.00
1 pc	Washer tank motor	\$	48.00
1 pc	Washer tank	\$	47.00
1 pc	Radiator upp hose	\$	78.00
1 pc	Radiator Lower hose	\$	64.00
1 pc	Engine under cover- Front	\$	44.00
1 pc	Engine under cover- n/s	\$	144.00
1 pc	Engine under cover- o/s	\$	173.00
1 pc	Air cleaner box	\$	483.00
1 pc	Air duct	\$	210.00
1 pc	Wiring Assy	\$	3,672.00
1 pc	Front o/s lower arm	\$	439.00
1 pc	Front o/s shock absorber	\$	330.00
1 pc	Front o/s ball joint	\$	59.00
1 pc	Front o/s tie rod end	\$	61.00
1 pc	Front o/s knuckle bearing	\$	157.00
1 pc	Front o/s stabilizer link	\$	86.00
1 pc	Front o/s knuckle arm	\$	547.00
1 pc	Front o/s rim	\$	246.00
1 pc	Front o/s wheel cover	\$	116.00
1 pc	o/s rocker panel garnish	\$	286.00
1 pc	Front driver seat	\$	1,837.00
			\$ 22,536.00
Less 10%			\$ 2,253.60
			\$ 20,282.40

26-Nov-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6473 T

S/NETT

1 pc	Front no. plate with casing	\$	50.00
1 pc	Front bumper clips	\$	48.00
2 pcs	Front n/s & o/s head lamp lower clip @ \$6.00	\$	12.00
2 pcs	Front n/s & o/s head lamp side clip @ \$3.00	\$	6.00
1 set	Bonnet insulator clips	\$	52.00
1 set	Wiper garnish clips	\$	48.00
1 pc	Battery ?	\$	180.00
1 pc	Coolant 6L	\$	80.00
1 set	Front o/s fender inner shield clips	\$	24.00
1 pc	Front o/s fender stickers	\$	30.00
1 pc	Sealant	\$	50.00
1 set	o/s door stickers	\$	100.00
1 pc	Tyre	\$	200.00

Kia Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: *Kahle (K/K)*
Date: *26/11/18*

Towing Fee	\$	50.00
Sundry	\$	50.00
To check for wiring and to focus head lamps	\$	40.00
To dismantle and replace the front windscreen	\$	120.00
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00
To dismantle and refit the dashboard to facilitate repair on front o/s wheel house	\$	450.00
To dismantle and replace the front o/s undercarriage	\$	250.00
To lift engine to facilitate repair on the front o/s wheel house	\$	450.00
To labour charge for dismantle and renew the accident damaged parts. To cut/heat and weld on the front o/s wheel house. Including knock-out, straighten, repair, reshape and adjust of the front o/s door, front n/s fender, front n/s chassis etc	\$	2,000.00
To putty and spray painting on bonnet, bonnet grille, front bumper, front n/s & o/s fender, front o/s wheel house, front o/s door, front n/s & o/s chassis member	\$	1,800.00
To apply rustproofing on the repaired and replaced panels.	\$	300.00
	\$	<u>26,852.40</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)