

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

Not Authored
1.B-1
McLenny B&P print
5 days

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: **Third Party**

Date: **23.11.2018**

Accident Date : 22.11.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Mitsubishi Lancer" Reg. No. SLE8786U Claiming Against Your Insured Reg. No. SLU8315L			
1pc	Boot <i>Be-</i>		N
1pc	Boot Center Emblem <i>me-</i>		N
1pc	Boot Badge "Lancer" <i>me-</i>		N
1pc	Boot Badge "EX" <i>me-</i>		N
1pc	Boot Badge "C&C" <i>me-</i>		N
1pc	Boot Lock <i>nd</i>		N
1pc	Boot Lock Catch <i>Rx</i>		N
1pc	Boot Weatherstrip <i>01710d</i>		N
1pc	Boot Trim Board <i>Sw X</i>		N
7pcs	Boot Trim Board Clips <i>nm X</i>		- N
1pc	Boot Stopper LH <i>mt</i>		N
1pc	Rear Number Plate Lamp <i>?</i>		N
1pc	Rear Number Bracket <i>?</i>		N
1pc	Rear Bumper <i>Be-</i>		N
10pcs	Rear Bumper Clips <i>me</i>		- N
2pcs	Rear Bumper Brackets <i>?</i>		- N
1pc	Rear Bumper Reinforcement <i>Be-</i>		N
1pc	Rear Bumper Sponge <i>NSP X</i>		N
1pc	Rear Bumper Top Retainer <i>NSP X</i>		N
1pc	Rear Bumper Reflector LH <i>?</i>		N
1pc	Rear Bumper Tow Cover <i>nd</i>		N
1pc	Rear Bumper Inner Boot Auto Sensor <i>?</i>		N
2pcs	Rear Bumper Corner Holders <i>nt</i>		- N
1pc	End Panel <i>Be-</i>		N
1pc	End Panel Outer <i>NSP X</i>		N
1pc	End Panel Garnish <i>mg di</i>		N
4pcs	End Panel Garnish Clips <i>me</i>		N
1pc	Spare Tyre Top Board <i>cm</i>		N
2pcs	Rear Fender Trim Boards <i>Sw X</i>		- N
8pcs	Rear Fender Trim Board Clips <i>nm X</i>		- N
1pc	Rear Number Plate		45.00 SN ✓
1pc	Rear Bumper Reverse Sensor		280.00 SN <i>2000</i>
To Dismantle / Transfer Boot Fittings / Ancillary Accessories			100.00 <i>50</i>
To Conduct Rear Electrical Check, Replace Reverse Sensors, Module, Rewiring Etc			120.00 <i>50</i>
C/F			545.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

108

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 23.11.2018

Accident Date : 22.11.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Mitsubishi Lancer" Reg. No. SLE8786U Claiming Against Your Insured Reg. No. SLU8315L		
		B/F	545.00
	To Dismantle / Transfer Rear Spare Tyre Panel Inner Trims Boards / Garnish and Rear Fenders Inner Trims Boards / Garnish to Facilitate Repair		100.00 601
	To Supply End Panel Joint Sealant		60.00 301
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		100.00 601
	Labour Charge - Panel Beating, Repairing Of Rear Chassis Member, Inner Panel, Spare Tyre Panel, Boot Hinges, Rear Fenders, Cnt, Weld End Panel and Parts Replacement		1,200.00 6001
	To Respray Affected Areas		1,000.00 6001
		Total :	<u>3,005.00</u>