COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

: SHB4167X VEHICLE NO

: HYUNDAI

23. Nov. 2018 DATE:

MAKE EQ 23. Nov. 2018 DOA: : i40 MODEL **Unit Price** Amount Parts Description/Labour Type Qty \$2,201.10 1 Rear Door - RH \$341.10 1 Rocker Cover Garnish – RH \$544.50 XMON 1 Rear Bumper \$22.00 10 Rear Bumper Clips 🗶 \$2.20 \$107.10 10 Rear Wheel Cover - RH Peu Feude (RH) × Mp. 2 \$3,215.80 **SUB TOTAL** \$643.16 **LESS 20%** DISCOUNTED TOTAL \$2,572.64 \$80.00 Nett 1 Rear Door APP sticker \$80.00 Labour Charge 300 \$600.00 1 Panel Beating its hence no LKK Auto Consulta \$1,000.00 000 1 Spray Painting Charge the Repairer of the • To resurvey before/a 1 Tuff Kote invey To display damage 1 Remove/refix reverse sensor endice" basis · Parts prices are sul Third party survey No illegal modification goved and ance Company No liegal to Suppermentary in is subject to final a • Supplementary in TOTAL LABOUR epairer \$1,770.00 Larry NG \$4,422.64

> This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.