

COMFORT DELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB4167X

DATE: 23. Nov. 2018

MAKE : HYUNDAI

MODEL : i40

DOA: 23. Nov. 2018

EQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Door - RH <i>Paint</i>			\$2,201.10
1	Rocker Cover Garnish - RH <i>on</i>			\$341.10
1	Rear Bumper <i>x repair</i>			\$544.50
10	Rear Bumper Clips <i>x m</i>		\$2.20	\$22.00
10	Rear Wheel Cover - RH <i>brushed</i>			\$107.10
	<i>Rear Fender (RH) x repair</i>			
SUB TOTAL				\$3,215.80
LESS 20%				\$643.16
DISCOUNTED TOTAL				\$2,572.64
1	Rear Door APP sticker <i>on</i>			\$80.00
				Nett
				\$80.00
Labour Charge				
1	Panel Beating			300
1	Spray Painting Charge			\$600.00
1	Tuff Kote			\$1,000.00
1	Remove/refix reverse sensor			\$50.00
				\$120.00
TOTAL LABOUR				\$1,770.00
ESTIMATE TOTAL				\$4,422.64
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before repair painting
- To display damaged parts for survey
- Parts prices are based on "market price" basis
- Third party survey is allowed
- No illegal means, is allowed and
- Supplementary cost(s) must be approved and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kaiwei LKK

23/11/18 11:15 hrs.

3 Days

4/5

After Repair - photo

Larry Ng