

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

AIG

Owner : Ong Eng Chuan

Accident Date : 19-Nov-18

Vehicle No : FBM 1958 M

Vehicle Model : Yamaha Fino

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender	\$ 85.00
2	Fork inner tubes	\$ 160.00
2	Fork outer tubes	\$ 180.00
1	Fork under bracket	\$ 145.00
1	Front brake disc	\$ 115.00
1	Front rim shaft	\$ 38.00
1	Front rim	\$ 280.00
1	Headlamp	\$ 139.00
2	Front signals	\$ 140.00
1	Handle bar	\$ 138.00
1	Handle bar end	\$ 18.00
1	Brake lever (1 set)	\$ 68.00
1	Side mirror (1 set)	\$ 120.00
1	Front cowling	\$ 198.00
1	Front cowling inner panel	\$ 108.00
1	Centre inner cowling	\$ 79.00
1	Front lower cowling	\$ 80.00
1	Lower belly cowling	\$ 95.00
1	Front footstep panel	\$ 116.00
1	Passenger footrest (1 set)	\$ 98.00
1	Main stand	\$ 85.00
1	Side stand	\$ 70.00
1	Rear signal	\$ 65.00
1	Rear tailboard	\$ 138.00
		\$ 2,758.00
	Less 10%	\$ 275.80
		\$ 2,482.20

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Owner : Ong Eng Chuan

Accident Date : 19-Nov-18

Vehicle No : FBM 1958 M

Vehicle Model : Yamaha Fino

Estimated Repair Costs

c/f: \$ 2,482.20

Special Nett Items

1	Number plate (1 set)	\$	502	28.00	10
2	Fork oils	\$	11	30.00	2
2	Fork oil seals	\$	11	56.00	2
1	Steering cone (1 set)	\$	11	75.00	2
1	ERP IU	\$	11	175.00	2
		\$		364.00	

S/No.


Labour

1	To provide towing service.	\$	45.00	35
2	To check wiring and reset headlamp focusing.	\$	11 80.00	2
3	To provide labour.	\$	480.00	300
4	To repair body frame.	\$	350.00	780
		\$	955.00	

Grand Total

\$ 3,801.20

Dollars: Three Thousand Eight Hundred One And Twenty Cents Only.


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: