

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

26/11/2018 11:41

JOB-NO: 50111155

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHB2265J

TRANS: AUTO

CHASSIS: KMHLB41UMGU093539

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDGU670618

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,000.00	0.00	1,000.00		Y	200
2 R&R SPARE TYRE & CARPET & TRIM	1.00	80.00	0.00	80.00		Y	X
3 RESPRAY REAR BUMPER	1.00	230.00	0.00	230.00		Y	200
4 RESPRAY REAR BUMPER DIFFUSER	1.00	200.00	0.00	200.00		Y	100
5 RESPRAY BOOTLID	1.00	230.00	0.00	230.00		Y	X
6 REMOVE & RE-DRILL REVERSE SENSOR	1.00	80.00	0.00	80.00		Y	30
TOTAL:		1,820.00	0.00	1,820.00			
MATERIALS							
1 REAR BUMPER	1.00	599.32	119.86	479.46	L	Y	de
2 REAR BUMPER REINFORCEMENT	1.00	438.40	87.68	350.72	L	Y	?
3 REAR BUMPER REINFORCEMENT BRACKET LHS	1.00	85.63	17.13	68.50	L	Y	?
4 REAR BUMPER REINFORCEMENT BRACKET RHS	1.00	85.63	17.13	68.50	L	Y	?
5 REAR BUMPER REINFORCEMENT SPONGE	1.00	150.15	30.03	120.12	L	Y	?
6 REAR BUMPER RETAINER LHS	1.00	49.14	9.83	39.31	L	Y	?
7 REAR BUMPER RETAINER RHS	1.00	49.14	9.83	39.31	L	Y	?
8 REAR BUMPER DIFFUSER	1.00	218.40	43.68	174.72	L	Y	Ry
9 REPAIR BOOTLID	1.00	0.00	0.00	0.00	L	Y	X
10 BOOTLID EMBLEM-LOGO	1.00	33.55	6.71	26.84	L	Y	X
11 BOOTLID EMBLEM-I 40	1.00	36.50	7.30	29.20	L	Y	X
12 BOOTLID EMBLEM-CRDI	1.00	36.50	7.30	29.20	L	Y	X
13 REAR BUMPER RUBBER PROTECTOR PAD	1.00	160.00	0.00	160.00	S	Y	new
14 REAR BUMPER REVERSE SENSOR	1.00	230.00	0.00	230.00	S	Y	200?
15 BOOTLID STICKER-COMFORTDELGRO BOOKING 65521111	1.00	120.00	0.00	120.00	S	Y	X
16 REAR BUMPER CLIP SET	1.00	35.00	0.00	35.00	S	Y	NA
17 REAR BUMPER ADS STICKER	1.00	160.00	0.00	160.00	S	Y	NA
TOTAL:		2,487.36	356.48	2,130.88			
TOTAL PARTS & LABOUR :		4,307.36	356.48	3,950.88			

EXCESS/LOADING: S\$ 0.00

No. Of Day: 02

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: S\$

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

DATE OF SURVEY: 20.11.18

SURVEYED BY: Tanjun

CONTACT NO: 9944 5119

FAX NO:

surellklands.com
'wp'

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: