

INS. CASE OWNER:

KE

CC 4, Asm 180 21324, Real 4

LKK:

IDAC:

84152

Surveyor:

HSM

DOI:

ASSIGNMENT

20/11/18

Date / Time:

26-11-2018

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJS5440 L

Name of Insured:

My Kee Siang

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

20/11/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

58m013 MS

Policy No.:

Make / Model:

Place of Accident:

PIE 7 CHANAL

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SBU778E



INSRS:

WSP:

Tel:

Liability:

RMKS:

PML



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

27/11

Ashur

SBU778E X

SJS5440 L X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

Email 26.11.18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: MIB

Repair Cost:

PIE \$5,339.93

(3 days)

Reduction:

40 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 20.11.18

Confirm with CAROLINE

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.: 31

If NO or B 28, Ask Lia:

Repair Cost:

WLB \$5,101.15

0. Repair ended TP

Loss of Rental (LOR):

WLB \$5,339.93

(2 days)

> \$100

Loss of Use (LOU):

\$ -

(\$ x

days)

Loss of Income (LOI):

\$ -

(\$ x

days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search:

\$52.00

Medical:

\$ -

Disbursement:

\$ -

(e.g. Tow/ Independent)

Legal Cost:

\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$350

Total:

\$54,380.53

Global Sum SS:

FINAL PAYMENT

Date/Time: 20.11.18

Confirm with CAROLINE

Email ☒ Call ☐

Payee 1:

\$54,380.53

Name 1:

TELECOMANCE MOTOR LIMITED

Payee 2: (Strike if N.A.)

\$ -

Name 2:

Payee 3: (Strike if N.A.)

\$ -

Name 3:

Signature *Pam*

REF:

ASM CAXA1

None/Please

71048

ASSIGNMENT

From: Date: 10-12-2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: *SBU 778E*
at Workshop m/s: *Performance*
of: *303 Alexandra Rd*

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Intiran

(Policy Condition)

Before 12pm

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

140K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lump Sum: - % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'DS'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: *SBU 778E* Yr Regn: *2015 APR*

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *B.M.W X4 XDRIVE 28I* C.C. *1997*

Colour: *BLACK* A/C Insured / Std / NI / NA

Sp. Reading: *74280* T/Radio: Insured / Std / NI / NA

Eng/No:

C/N: *WBAKW320X00F 78.778.*

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *245/45R18*

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: *6* mm R/Bal: *6* mm

L/Bal: *6* mm L/Bal: *6* mm

D.O.A: *20/11/18* D.O.I: *10/12/18*

Survey held at: *Performance*

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear o/s

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/P: 73,734.93 (220 → 344.2) 46%

Date/Time: File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1 S + RS SR

1 Photos

1 Videos

1

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Ash

Survey & repair
16/12 @ 10 am
aka survey before 12pm



MS Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 19741359W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 119941
Tel: 63190120 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

280, Serpong Asemp Road
East Coast Centre
Singapore 438180
Tel: 63190888 (AfterSales)
Fax: 63447773

211, Alexandra Road
Sime Darby Business Centre
Singapore 119944
Tel: 63190528 (AfterSales)
63190511/535 (Motorrad)
Fax: 64794621 (AfterSales)
64794624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

26 NOV 2018

ESTIMATE

Page No. : 1 of 5

Estimate No. : b1 49244
Date Estimated : 26/11/2018
Prepared By : Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -

Tan Chin Huat
17 GreenLeaf Rise

Singapore 279378

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBU778E	0F78778	30/04/2015	X4 xDrive 28i	0

DESCRIPTION

Replacing rear bumper panel, etc to knock out dents caused by the accident

Spray rear bumper

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries *Nu*

	VALUE
755	850 1,200.00
840.40	934 1,028.00
155	150 171.00
80	? 80.00

Total Labour 1: 2,995.00

DESCRIPTION

REAR BUMPER SET MOUNTING PARTS (VAL *? Xan*)
RR BUMPER CARRIER ECE *? Xan*
FLAP TOWING EYE REAR *as Xan*
RR RH BUMPER MOUNTING MIDDLE *? Xan*
RR BUMPER LH MOUNT *? Xan*
RR BUMPER RH MOUNT *? Xan*
COVER MIDDLE BOTTOM *as Xan*
REAR BUMPER PANEL PRIMED (X LINE) *DE*
REAR BUMPER CLADDING (PDC/SCHWARZ) *DE*
UNDERSIDE GUARD PRIMED REAR (X LINE) *? Seal*
RH REFLECTOR *? Xan*
ULTRASONIC SENSOR BLACK *as Xan*
DECOUPING RING PDC TORQUE CONVERTER *as Xan*

QTY	PRIC	VALUE
1	38.55	38.55
1	756.50	756.50
1	37.00	37.00
1	137.75	137.75
1	192.15	192.15
1	198.30	198.30
1	70.40	70.40
1	1,389.65	1,389.65
1	204.30	204.30
1	332.90	332.90
1	36.10	36.10
1	248.70	497.40
4	5.05	20.20

Total Parts : 3,911.20

Performance Motors Limited

A member of the Sime Darby Group
CO. Reg. No. 197401559K GST Reg. No. M2-0020081-X

107, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64797770

107, Kembangan Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63443773

118, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190828 (AfterSales)
63190833/330 (Motorrad)
Fax. 64796401 (AfterSales)
64796424 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.	b1 49244	Page No. : 2 of 5
Date Estimated	26/11/2018	
Prepared By	Inthiran A/L Thurasamy	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBU778E	0F78778	30/04/2015	X4 xDrive 28i	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 10/12/18 9:11:50 Excess \$ _____

Surveyor's Name RSUL Sign _____

Surveyor's Tel 90010068 Authored Yes / No _____

Authorized Date _____ Time _____

RESURVEY PARTS PHOTO BY 2018/12/10 10:11:50

Surveyor's Email _____

No. of Working Days Recommended 3 days

Repair by paint

Labour 1	:	2,995.00
Parts	:	3,911.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	483.43
Grand Total	:	7,389.63

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-8



SUPPLEMENTARY

Estimate No. : b1 49244 Page No. :
Date Estimated : 26/11/2018
Prepared By : Inthiran A/L Thurasamy

REPAIR FOR -
Tan Chin Huat
17 GreenLeaf Rise

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 279378

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SBU778E	0F78778	30/04/2015	X4 xDrive 28i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CLAMP *	1.55	8.00	3.00	12.03
# BLIND RIVET *	2.95	10.00	3.00	28.61

Total Labour :	
Total Parts :	40.64
Total Labour & Parts :	40.64

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W; GST Reg. No. M2-000081-E



FINAL REPORT

Estimate No. : b1 49244
Date Estimated : 26/11/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Tan Chin Huat
17 GreenLeaf Rise

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 279378

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SBU778E	0F78778	30/04/2015	X4 xDrive 28i	0
DESCRIPTION		ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments include knocking out dents caused by the accident		850.00	10.00	765.00
To spray paint rear bumper		934.00	10.00	840.60
To check electrical wiring systems and lightings at the rear section for proper function		150.00	10.00	135.00
Sundries		80.00	0.00	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CLAMP *	1.55	8.00	3.00	12.03
# BLIND RIVET *	2.95	10.00	3.00	28.61
REAR BUMPER PANEL PRIMED (X LINE)	1,444.49	1.00	3.00	1,401.16
REAR BUMPER CLADDING (PDC/SCHWARZ)	212.35	1.00	3.00	205.98
UNDERSIDE GUARD PRIMED REAR (X LINE)	279.95	1.00	3.00	271.55

SUPPLEMENTARY ITEMS

Total Labour :	1,820.60
Total Parts :	1,919.33
Total Labour & Parts :	3,739.93
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,739.93
GST @7%:	261.80
Grand Total :	4,001.73

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559M GST Reg. No. M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747772

180, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63190888 (AfterSales)
Fax: 63449773

118, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax: 64794601 (AfterSales)
64794624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

26 NOV 2018

ESTIMATE

Estimate No. : b1 49244
Date Estimated : 26/11/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Tan Chin Huat
17 GreenLeaf Rise

Singapore 279378

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBU778E	0F78778	30/04/2015	X4 xDrive 28i	0

DESCRIPTION

Replacing rear bumper panel, etc to knock out dents caused by the accident

VALUE
850 1,700.00

Spray rear bumper

934 1,038.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 171.00

Sundries

? 80.00

Total Labour 1: 2,995.00

DESCRIPTION

REAR BUMPER SET MOUNTING PARTS (VAL ?
RR BUMPER CARRIER ECE ?
FLAP TOWING EYE REAR ms /
RR RH BUMPER MOUNTING MIDDLE ?
RR BUMPER LH MOUNT ?
RR BUMPER RH MOUNT ?
COVER MIDDLE BOTTOM ed /
REAR BUMPER PANEL PRIMED (X LINE) DE /
REAR BUMPER CLADDING (PDC/SCHWARZ) DE /
UNDERSIDE GUARD PRIMED REAR (X LINE) ?
RH REFLECTOR ?
ULTRASONIC SENSOR BLACK m /
DECOUPING RING PDC TORQUE CONVERTER m /

QTY	PRIC	VALUE
1	38.55	38.55
1	756.50	756.50
1	37.00	37.00
1	137.75	137.75
1	192.15	192.15
1	198.30	198.30
1	70.40	70.40
1	1,389.65	1,389.65
1	204.30	204.30
1	332.90	332.90
1	36.10	36.10
1	248.70	497.40
4	5.05	20.20

Total Parts : 3,911.20

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



305, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

380, Kampong Arang Road
East Coast Centre
Singapore 438183
Tel. 63190888 (AfterSales)
Fax. 63448773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190538 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796614 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49244
Date Estimated : 26/11/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBU778E	0F78778	30/04/2015	X4 xDrive 28i	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 10/12/18 9:11:50 Excess \$1 _____

Surveyor's Name PASUL Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR: [Signature] [Stamp]

Surveyor's E-mail _____

No. of Working Days Recommended 3 days

Repairing 64 panel

Labour 1	:	2,995.00
Parts	:	3,911.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	483.43
Grand Total	:	7,389.63

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Wednesday, 28 November 2018 10:57 AM
To: PBSP
Subject: RE: REQUEST FOR DIRECT SETTLEMENT - SBU778E & SJS5440L ON 20/11/2018 *** LKK REF: CC4/ASM18021324/ea3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)
Sent: Monday, 26 November 2018 4:35 PM
To: PBSP <pml-pbsp@simedarby.com.sg>
Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Subject: RE: REQUEST FOR DIRECT SETTLEMENT - SBU778E & SJS5440L ON 20/11/2018 *** LKK REF: CC4/ASM18021324/ea3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Caroline,

We refer to the above matter.

Please be informed that we are currently **pending verification for direct settlement**.

Fyi, OI has reported. Please refer to the below OI's sketch plan and statement.

Sketch Plan Pg. 2

SKETCH PLAN

PIE.

1m

1m

← From East Side East

← Towards Chongli Airport

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along PE towards Chongli Airport direction on 20/11/18 morning. Road condition was wet after early morning rain. Traffic was moderate as usual with a driving speed of about 70km/h. On lane 1.

As shown in the above picture, Vehicle A came to a complete stop while Vehicle B follows. I was about 50m away, cautioning at about 70km/h. I was aware of the vehicle and started to brake to slow down vehicle. However, the braking time took to bring my vehicle to a stop was longer than usual. Brake was jammed as I was passing Vehicle B. Unable to bring vehicle to a complete stop, my front left bump into right rear of Vehicle B as I steered my vehicle to the right.

No injury sustained for all parties, however, I will pursue refund to private driving license or any particulars, only stating that I will file the report.

☐ Reporting Only

Kindly note that for liability, claim negotiation and settlement, please contact Asher at 6841 6051.

Our respective case handler will look into the matter and revert to you in due course.

Meanwhile, please arrange appointment for TP survey.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@sime-darby.com.sg>

Sent: Monday, 26 November, 2018 3:44 PM

To: SG AXA Insurance SM AXA SGP - Motor Survey <motor_survey@axa.com.sg>

Subject: REQUEST FOR DIRECT SETTLEMENT - SBU778E & SJ55440L ON 20/11/2018

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."



MANDATE IA (S8M013MS)

Type

🔗 Question

Message

Liability: Insured rear ended third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$4,001.73 (w/GST) Loss of Rental : \$256.80 (2days x \$120) (w/GST) LTA Search: \$2.00 Total: \$4,260.53 Immediate Advice with Mandate and relevant document uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (26/03/2019)

Reply



Re:RE: MANDATE IA (S8M013MS)

Type

🔗 Question

Message

ERROR ON YOUR LAST MESSAGE. PLEASE PROCEED FOR SETTLEMENT NOT EXCEEDING \$4,260.53

Reply



redefining / insurance

AXA Insurance Pte Ltd
 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4740
 customer.care@axa.com.sg
 www.axa.com.sg

TAN CHIN HUAT
 17 GREENLEAF RISE
 BAN GUAN PARK
 SINGAPORE 279378

Renewal

date
 27/08/2018

your servicing distributor
 MAXURANCE VENTURE / 03926

your servicing distributor contact
 6100 2592

Policy Schedule

Your SmartDrive Comprehensive Private APW

Your policy snapshot

Policyholder name	TAN CHIN HUAT	Policy number	VA1 / GA059419
Cover	Comprehensive	FIN / NRIC	S0197104B
Period of Insurance	from 19/09/2018 to 18/09/2019 (both dates inclusive)		

Premium breakdown

Gross Premium after 50% NCD	SGD 928.78
7% GST	SGD 65.01
Final Premium	SGD 993.79

Your benefits highlights

(refer to Policy Wording for full terms and conditions)

SmartDrive Comprehensive Private APW Benefits

- 24/7 Towing & Transportation in Singapore or Overseas
- Guaranteed Repairs for twelve (12) Months
- Loss or Damage
- Legal Liability
- Loss of Personal Effects in Singapore up to \$3,000
- Daily Transport Allowance of \$50 for a maximum of five (5) days
- Personal accident benefit of up to \$30,000 for you or your named drivers while driving
- Medical and dental expenses up to \$500 per person for either you as the driver or your authorised driver and a passenger
- Basic Own Damage Excess Reduction for AXA Premium Workshop
- Windscreen Replacement with Excess OR Repair your windscreen at your preferred location and get \$50 cash reward with no excess

Vehicle details

Make & Model of Vehicle	HONDA VEZEL 1.5	Year of manufacture	2014
Vehicle registration number	SFR7788Z	Type of Use	Private use
Body type	SALOON	Engine capacity (c.c.)	1496
Seating capacity (excl driver)	4	Engine number	L15B3508477
Off-Peak car	No	Chassis number	RU11008461

Insured's Estimated Market Value	Market Value at the time of Loss (including accessories and spare parts)
Limitation to use	As per Certificate of Insurance
Finance Loan Company	HONG LEONG FINANCE LIMITED

Excess applicable (refer to Policy Wording for other applicable Excesses)

Basic Own Damage Excess	SGD 0.00
Windscreen Excess	SGD 100.00



redefining / insurance

AXA Insurance Pte Ltd
☎ 1800 880 4888 (Within Singapore)
(65) 6880 4888 (International)
☎ (65) 6880 4740
✉ customer.care@axa.com.sg
🌐 www.axa.com.sg

TAN CHIN HUAT
17 GREENLEAF RISE
BAN GUAN PARK
SINGAPORE 279378

GA059419-2018-73460

SmartDrive Comprehensive Private

APW

Renewal

Original

date

27/08/2018

policy number

VA1 / GA059419

your servicing distributor

MAXURANCE VENTURE / 03926

Tax Invoice

(Client Copy)

Your policy information

Policyholder name	: TAN CHIN HUAT
Period of Insurance	: from 19/09/2018 to 18/09/2019 (both dates inclusive)
Transaction Number	: AXA-MTR-SG-REN-2018-73460
Effective Date	: 19/09/2018

Billing details

Gross Premium after 50% NCD	SGD 928.78
7% GST	SGD 65.01
Total Payable	SGD 993.79

What you should do

- Please keep this Tax Invoice as reference for premium due.

AXA Insurance Pte Ltd

This is an auto-generated document thus no signature is required

Issued by RAJ Seelam on 27/08/2018 12:50:15 PM

AXA Insurance Pte Ltd (199903512M)
8 Shenton Way, #24-01, AXA Tower,
Singapore 068811
Customer Centre, #B1-01

1 of 1

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S0197104B



Name

TAN CHIN HUAT



陳振發

Race

CHINESE

Date of birth

01-02-1946

Country/Place of birth

SINGAPORE

Sex

M



IDENTITY CARD NO. S0197104B

5953060



Date of issue

06-06-2018

Address

17 GREENLEAF RISE
SINGAPORE 279378

REPUBLIC OF SINGAPORE **DRIVING LICENCE**

 **License Number** **S0197104B**
Name
TAN CHIN HUAT


Birth Date **01 Feb 1946**
Issue Date **12 Apr 2003**

 **000377098D**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	PASS DATE
Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	07 Jun 1965

NP 425A

 **License No: S0197104B**



Settlement breakdown

Type

 Information

Message

Dear LKK, Please send us the payment settlement breakdown with supporting documents for us to process payment. TP PML is chasing for settlement Regards, Christopher Chionh

Reply



AXA Insurance Pte Ltd
8 Shenton Way
#27-01
Singapore 068811
Attention: Motor Claims

Asher

"Without Prejudice"

Your Ref:

Our Ref:

Date:

Subject:

26 January 2019

ACCIDENT INVOLVING VEHICLES SBU778E & SJS5440L ON 20.11.2018

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	:	S\$	4001.73
Car Rental	:	S\$	256.80
GA search fee	:	S\$	2.00
Total	:	S\$	4260.53

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill & GA search slip
3. Copy of Car Rental bill & Car Rental Agreement & Certificate of Insurance
4. Copy of Identification Card & Driving License
5. Copy of Letter of Authorisation & Discharge Voucher

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@simeдарby.com.sg.

Yours sincerely

Teng Wai Khan
Customer Service Manager, Body & Paint

Performance Motors
Limited
1800-Call-BMW
(1800-2255-269)

www.pml.com.sg

303 Alexandra Road
Sime Darby
Performance Centre
Singapore 159941
Tel Sales 6319 0100
Tel AfterSales:
6319 0111
Fax 6474 7770

315 Alexandra Road
#01-01
Sime Darby
Business Centre
Singapore 159944
Tel Sales 6319 0511
Tel AfterSales:
6319 0527
Fax 6479 6624

260
Kampong Arang Rd
East Coast Centre
Singapore 438180
Tel AfterSales:
6319 0888
Fax 6344 1332

Registered office
305 Alexandra Road
#02-01
Vantage
Automotive Centre
Singapore 159942

Co. Reg. No:
197401559W

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Friday, 28 December 2018 9:31 AM
To: 'ADENNG@GMAIL.COM'
Subject: ACCIDENT INVOLVING SJS 5440L AND SBU 778E ALONG PIE TWDS CHANGI AIRPORT BEFORE KIM KEAT LINK ON 20/11/2018

28 DEC 2018

NG KEE SIANG

Dear Sir/ Mdm

OUR REF : CC4/ASM18021324/R1ea3
YOUR REF : SJS 5440L
ACCIDENT INVOLVING SJS 5440L AND SBU 778E ALONG PIE TWDS CHANGI AIRPORT BEFORE KIM KEAT LINK ON 20/11/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s PERFORMANCE MOTORS LTD acting on behalf of the owner of SBU 778E against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had rear-ended the Third Party vehicle SBU 778E. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to ashersng@lkkauto.com within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at ashersng@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: ashersng@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

Performance Motors Limited

A member of the Sime Darby Group



LETTER OF AUTHORISATION

ACCIDENT INVOLVING SBU7T8E & SJS5440L ON 20/11/2018.

I, TAN CHIN HUAT owner of Vehicle Registration No. SBU7T8E hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement amount in respect of such claim shall constitute the full discharge of my claim in respect of such loss and damage.

Signed by:

Name: TAN CHIN HUAT (Date) 10/12/18

NRIC No.: 50197104 B

In the presence of:

Name: _____ (Date) 10/12/18

NRIC No.: _____

Witness At: **Performance Motors Limited**
303 Alexandra Road
Sime Darby Performance Centre
Singapore 119941



redefining / insurance

CLAIM REF : SBMD13MS
INSURED : NG KEE SUNG

DISCHARGE VOUCHER

We/I Tan Chiu Huat, NRIC NO. 50197104B hereby agree to accept the sum of dollars [FOUR THOUSAND TWO HUNDRED SIXTY AND (FIFTY) THREE ONLY.] (S\$ 4260.53) paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. SJSS440L as a result of an accident along PIE Changi Near Toa Payoh on 20.11.18 of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. SB477BE.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. SJSS440L in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. SJSS440L.

Dated this 22 day of 04 2019

Claimant's Signature :

NRIC no./ Company Stamp :

50197104B

Occupation/ Business :

Address :


17 GREENLEAF ROAD S(219318)

Telephone No. :

Witness's Name :

Witness's Signature :

Witness's NRIC No. :





103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190180 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

318, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/538 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1321969

Date IN : 10/12/2018

Cust. Svc. Advisor: Inthiran A/L Thurasamy

Page No. : 1 of 2

Invoice Number : 2058263 / WSB

Invoice Date : 24/01/2019

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Mr Tan Chin Huat
17 GreenLeaf Rise

Singapore 279378

- INVOICE TO - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBU778E	0F78778	30/04/2015	X4 XDRIVE 28I	74280

- - - - L A B O U R 1 - - - -

To replace rear bumper and attachments including to
remove and install body parts in order to carry out painting
job.

To respray rear bumper.

To check electrical wiring systems and lightings at the
rear section for proper function.

Sundries

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 20.11.2018. 3RD PARTY CAR : SJS5440L.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR RUSAL FROM LKK AUTO
CONSULTANTS PTE LTD ON 10.12.2018 AT 11.50 AM.
AUTHORISED REPAIR BY MS ASHER SNG FROM LKK ON
28.11.2018 VIA E-MAIL.

PROPOSE CAR RENTAL = \$256.80. THE AMOUNT IS SUBJECTED
TO INSURANCE COMPANY CONFIRMATION.

GIA SEARCH FEE = \$2.00.

Retail

Price

DISC%

NETT

850.00

10.00

765.00

934.00

10.00

840.60

150.00

10.00

135.00

80.00

0.00

80.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

Total Labour 1: 1,820.60

- - - - P A R T S - - - -

REAR BUMPER PANEL PRIMED (X LINE)

REAR BUMPER CLADDING (PDC/SCHWARZ)

UNDERSIDE GUARD PRIMED REAR (X LINE)

BLIND RIVET

CLAMP

Retail

Qty

Price

DISC%

NETT

1

1,444.50

3.00

1,401.16

1

212.35

3.00

205.98

1

279.95

3.00

271.55

10

2.95

3.00

28.61

8

1.55

3.00

12.03

Total Parts : 1,919.33



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax 64747770

380, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190088 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/330 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1321969	Page No. : 2 of 2
Date IN : 10/12/2018	Invoice Number : 2058263 / WSB
Cust. Svc. Advisor: Inthiran A/L Thurasamy	Invoice Date : 24/01/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

Labour Charges :	1,740.60	Total Labour & Parts Charges :	S\$ 3,739.93
Parts Charges :	1,919.33	Less Insurance Excess :	S\$ 0.00
Lubricant/Misc :	80.00	Invoice Total Amount Exclude GST :	S\$ 3,739.93
		GST @ 7% :	S\$ 261.80
		Invoice Total Amount Include GST :	S\$ 4,001.73

Computer generated invoice. No signature is required.	Amount Payable Include GST :	S\$ 4,001.73
---	------------------------------	---------------------

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





TAX INVOICE

Invoice No. 55 - 512800

Page 1 of 1

MR TAN CHIN HUAT

BLK 748 JURONG WEST STREET 73 #09-129
SINGAPORE 640748

SIME DARBY SERVICES PTE LTD

Thrifty International Licensee

305 Alexandra Road, #03-01

Vantage Automotive Centre, Singapore 159942

p (65) 6447.3388 f (65) 6345.7247

Co. Reg. No. 197501065W GST Reg. No. M2-0021986-4

INVOICE DATE : 13-DEC-2018

R.A. No. 55005254 / Benjamin Loo ZhiWei

TITLE	: MR	KILOMETER OUT/IN	: 25574 / 25800
AUTHORIZED DRIVER	: TAN CHIN HUAT	KILOMETER DRIVEN	: 226
NRIC/PASSPORT NO.	: S7181206E	PETROL LEVEL OUT/IN	: FULL / 7 / 8
MAKE & MODEL	: FORD MONDEO TITANIUM 2.0 AT	DATE & TIME OUT	: 10-DEC 2018 10:00
CAR REGISTRATION NO.	: SLQ2126B / UNIT #: 0002972	DATE & TIME IN	: 12-DEC 2018 17:30
CAR GROUP GIVEN	: I	CHECK IN LOCATION	: SHORT TERM-HQ (SIN55)-THRIFTY
CAR GROUP CHARGED	: H	NO. OF DAY(S) CHARGED	: 2 DAY(S) 8 HOUR(S)

DESCRIPTION	UNIT PRICE (SGD)	UNIT	AMOUNT BEFORE GST (SGD)	GST @ 7%	AMOUNT (SGD)
INSURANCE CLAIMS RATES 2017					
2 DAY(S) @ \$120.00 / DAY			240.00	16.80	256.80
5 HOUR(S) @ \$24.00 / HOUR			120.00	8.40	128.40
WAIVED EXCESS HOURS DUE TO CAR REPAIR PICK UP INFORMED LATE			-120.00	-8.40	-128.40
SUB-TOTAL			240.00	16.80	256.80
REMARKS: BMW OWNER: SBU778E \$150.00 / DAY 2000CC PML CSA: INTHIRAN		TOTAL (SGD) :	240.00	16.80	256.80
* ITEMS NOT SUBJECT TO GST					
		MC XXXXXXXXXXXX1020			-256.80
		MC XXXXXXXXXXXX6041			0.00
		BALANCE DUE			0.00

NOTE:

I/ WE HEREBY AGREE TO THE TERMS AND CONDITIONS AND BE HELD LIABLE FOR ALL AMOUNT DUE UNDER THIS AGREEMENT; ALL TRAFFIC FINES INCLUDING ADMIN FEES INCURRED DURING PERIOD OF HIRE; ANY COSTS INCURRED BY SIME DARBY SERVICES PTE LTD FOR MY FAILURE TO REPORT ANY ACCIDENT WITHIN 24 HOURS. FINAL CHARGES IS SUBJECT TO FULL INSPECTION OF THE VEHICLE BY A COMPANY REPRESENTATIVE.

HIRER'S AND/OR ADDITIONAL DRIVER'S SIGNATURE

Printed on 13-Dec-2018

9:44

Entered by Benjamin Loo ZhiWei

**SIME DARBY SERVICES PTE LTD**

Thrifty International Licensee

305 Alexandra Road, #03-01

Vantage Automotive Centre, Singapore 159942

p (65) 6447.3388 f (65) 6345.7247

Co. Reg. No. 197501065W GST Reg. No. M2-0021986-4

TO BE PAID BY

PAYMENT : MC - XXXXXXXXXXXX8041

HIRER'S DETAILS

TITLE : MR
 NAME : TAN CHIN HUAT
 ADDRESS : BLK 748 JURONG WEST STREET 73
 #09-129
 SINGAPORE 640748

NRIC/PASSPORT NO. : S7181206E ISSUE: 12/11/2012

ISSUED BY : SINGAPORE
 LICENSE : S7181206E EXPIRY: 31/12/2999ISSUED BY : SINGAPORE
 NATIONALITY : MALAYSIAN D.O.B : 27/06/1971

FREQUENT FLYER NO. :

LOCAL CONTACT : 9770-9416

HOTEL

COMPANY'S DETAILS

NAME :

ADDRESS :

IMPORTANT NOTICE

- Hirer is liable for all traffic fines including admin fees that are issued by Singapore or Malaysia authorities for a grace period of 12 months from the date of car return.
- A security deposit depending on the respective car group rented will be withheld on the Hirer's credit card.
- Any accident has to be reported within the next working day to Sime Darby Services Pte Ltd. In the event of failure to report, hirer shall be liable for any costs incurred by Sime Darby Services Pte Ltd or claims made by the other party.
- Smoking, durians and pets are not allowed in the vehicle. An additional 3 days rental would be imposed if smoking and durian smell/pet's fur is detected upon car return.
- Hirer must inform Sime Darby Services Pte Ltd in advance for vehicle drop-off in Thrifty Malaysia renting location. A one-way rental fee and Malaysia surcharge are applicable as stated in our One Way Rental policy.
- Hirer is responsible for any missing items/car accessories or loss of keys will be charged accordingly.
- The excess do not cover i) Car accessories ii) Loss of key iii) Vandalism iv) Alcohol/Intoxicants/Drugs.
- Vehicles are prohibited to be driven into Thailand.
- Strictly no key-drop services allowed, security deposit will be forfeited.

The vehicle is rented subject to all terms and conditions on this page and on the reverse side whether printed or handwritten. Hirer represents that they have read, understand and agree with the conditions of the rental agreement. The hirer authorises all amounts due under the rental agreement to be charged to the hirer's credit card shown on this form.

x  x
 Hirer Additional Driver

ADDITIONAL DRIVERS:

RENTAL AGREEMENT NUMBER : 55005254
 RENTAL LOCATION : SHORT TERM-HQ (SIN55)-THRIFTY

CHECKOUT

UNIT # / REGN NO. : 00002972 / SLQ2126B
 MAKE & MODEL : FORD MONDEO TITANIUM 2.0 AT
 CAR GROUP GIVEN : I CHARGE: H
 KILOMETER OUT : 25,574
 PETROL LEVEL OUT : FULL
 DATE & TIME OUT : 10/12/2018 10:00
 DUE DATE & TIME IN : 13/12/2018 10:00
 CHECKIN LOCATION : SHORT TERM-HQ (SIN55)-THRIFTY

RENTAL RATES

AS: INSURANCE CLAIMS RATES 2017
 DAILY @ S\$ 120.00
 EXTRA DAY @ S\$ 120.00
 EXTRA HOUR @ S\$ 24.00

TOTAL: S\$ 385.20**FOR RATES TO APPLY**

MINIMUM 24 HOURS.
 CAR MUST BE RETURNED TO RENTING LOCATION
 ON THE DUE DATE

INSURANCE

BY INITIALS, THE HIRER
 INCLUSIVE LDW
 NON-WAIVERABLE DAMAGE EXCESS S\$ 2,000.00 (SIN USE)

DECLINES PAI @ S\$ 5.00 PER DAY

DECLINES WSC @ S\$ 5.00 PER DAY

THIS CAR IS FOR SINGAPORE USE ONLY. THERE IS NO INSURANCE
 COVERAGE FOR USE OUTSIDE SINGAPORE

OTHER CHARGES

FUEL SERVICES @ S\$2.70 / LITRE

CASH & CHEQUE DEPOSIT**REMARKS**

BMW OWNER: 5BU778E
 \$150.00 / DAY 2000CC
 PML CSA: INTIRAN

HI RESERVATION

RES. ID# SD000005109
 Benjamin Loo ZhiWei

TACO#

REF SRC: INSCLAIMS

Printed on: 10-Dec-2018 8:48
 Entered by: Benjamin Loo ZhiWei



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-183236

Date of Request: 26/11/2018

Your Ref No:

Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 26/11/2018
Enquiry By Melanie Setiawati
TP Vehicle No. SJS5440L
Accident Date 20/11/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJS5440L	AXA Insurance Pte Ltd	24/08/2018-23/08/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-183236

Date of Request: 26/11/2018

Your Ref No:

Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 26/11/2018
Enquiry By Melanie Setiawati
TP Vehicle No. SJS5440L
Accident Date 20/11/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJS 5440L (Insd veh)	Model:	B.M.W. X4 XDRIVE28i
	SBU 778E (TP veh)		
Date of Accident:	20/11/2018		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	:	\$		7,447.23
Final Repair Cost	:	\$		4,001.73
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		256.80 2 days
LTA / GIA Search Fee	:	\$		2.00

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	4,260.53

Is Third Party Workshop GIA Registered?	[X] YES	[] NO	(Kindly indicate below)
A) For Non GIA Registered Workshop: Agreed Liability _____ (%)			
B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____			
BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____ _____			

Payment Instruction: Payee's Breakdown		
1)	PERFORMANCE MOTORS LIMITED	\$ 4,260.53

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

03/05/2019
Date


Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18021324/R1ea3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN			Date : 03-05-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJS 5440L	Veh. Inspected	SBU 778E	
Policy No.	GA258044/1	Coverage (\$)	0.00	
Claim No.	S8M013MS	Excess (\$)	0.00	
Assign From		Assign Date	26/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. X4 XDRIVE28i	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WBAXW320X00F78778	Colour	BLACK	
Odometer	74280	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45 R18	PIRELLI	6 mm	
L/H Front Tyre	245/45 R18	PIRELLI	6 mm	
R/H Rear Tyre	245/45 R18	PIRELLI	6 mm	
L/H Rear Tyre	245/45 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/11/2018	Inspection Date	10/12/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBU 778E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	80.00	80.00
1	REAR BUMPER SET MOUNTING PARTS (VAL) (SN) (CONSISTENT)	NOT NECESSARY	38.55	-
1	RR BUMPER CARRIER ECE (SN) (CONSISTENT)	NOT NECESSARY	756.50	-
1	FLAP TOWING EYE REAR (SN) (CONSISTENT)	NOT NECESSARY	37.00	-
1	RR RH BUMPER MOUNTING MIDDLE (SN) (CONSISTENT)	NOT NECESSARY	137.75	-
1	RR BUMPER LH MOUNT (SN) (CONSISTENT)	NOT NECESSARY	192.15	-
1	RR BUMPER RH MOUNT (SN) (CONSISTENT)	NOT NECESSARY	198.30	-
1	COVER MIDDLE BOTTOM (SN) (CONSISTENT)	NOT NECESSARY	70.40	-
1	REAR BUMPER PANEL PRIMED (X LINE) (SN) (CONSISTENT)	DEFORMED	1,401.16	1,401.16
1	REAR BUMPER CLADDING (PDC/SCHWARZ) (SN) (CONSISTENT)	DEFORMED	205.98	205.98
1	UNDERSIDE GUARD PRIMED REAR (X LINE)(SN) (CONSISTENT)	SCRATCHED	332.90	271.55
1	RH REFLECTOR (SN) (CONSISTENT)	NOT NECESSARY	36.10	-
2	ULTRASONIC SENSOR BLACK (SN) (CONSISTENT)	NOT NECESSARY	497.40	-
4	DECOUPING RING PDC TORQUE CONVERTER (SN) (CONSISTENT)	NOT NECESSARY	20.20	-
8	CLAMP (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	12.03	12.03
10	BLIND RIVET (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	28.61	28.61
			4,045.03	1,999.33
LABOUR				
	REPLACE REAR BUMPER PANEL ,ETC TO KNOCK OUT DENTS CAUSED BY THE ACCIDENT.		1,700.00	765.00
	SPRAY REAR BUMPER.		1,038.00	840.60
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	135.00
			2,915.00	1,740.60
GRAND TOTAL			6,960.03	3,739.93
RECOMMENDED COST OF REPAIRS				3,739.93

Report Ref No. CC4/ASM18021324/R1ea3q2



Report Ref No. CC4/ASM18021324/R1ea3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Actions	Wait for Approve Invoice	
Next Step		Send To Invoice

Claims	SUM013M5
Reference	CC4/ASM1802132M/R1ea362
Loss Date	20 November 2018
Report Date	20 Nov 2018 11:33:00 AM
Request Date	26 November 2018
Due Date	
Vendor Name	LKX AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Vehicle Information	
Incident Vehicle Registration #	5BU77HE
Make	TPND BMW
Model	X4 XDRIVE30i AWD LED 30 NAV HUD
Service Address	
...	
Primary Contact/Insured	
NG KEE SIANG BLK 547B SECAR ROAD #06-01, 672547, Singapore 96501211 ademg@gmail.com	
Claim Handler	
CHAN Kian Chuan 6568804269 kianchuan.chan@aia.com.sg	

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Mileage

Notes

Document Type















▼

Document SubType

▼

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1_64.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	3 May 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 May 2019
 payment breakdown.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 May 2019
 LCD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 May 2019
 LKK Inspection (5).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 May 2019
 LKK Adjustment 1a (5).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 May 2019
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 May 2019
 DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	3 May 2019
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	PCA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	3 May 2019
 WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	3 May 2019
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	3 May 2019
 LKK Survey Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 March 2019
 LKK Resurvey Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 March 2019
 Immediate Advice with Mandate.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 March 2019
 TP ESTIMATE MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	26 March 2019

