

MW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)Survey & repair
10/12 @ 10 am
Survey before 12pm

GST REG. NO : M2 - 0020081 - X

26 NOV 2018

E S T I M A T E

Page No. : 1 of 5

Estimate No. : b1 49244
Date Estimated : 26/11/2018
Prepared By : Inthiran A/L Thurasamy**- ESTIMATE REPAIR FOR -**
Tan Chin Huat
17 GreenLeaf Rise**- ACCOUNT - 40000**
Cash Sales - Service
Singapore

Singapore 279378

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBU778E	0F78778	30/04/2015	X4 xDrive 28i	0

DESCRIPTION

Replacing rear bumper panel, etc to knock out dents caused by the accident

850 ~~1,700.00~~

Spray rear bumper

934 ~~1,038.00~~

To check electrical wiring systems and lightings at the rear section for proper function.

150 ~~171.00~~

Sundries

? 80.00

Total Labour 1: **2,995.00**DESCRIPTION

REAR BUMPER SET MOUNTING PARTS (VAL ?
RR BUMPER CARRIER ECE ?
FLAP TOWING EYE REAR *ms* ?
RR RH BUMPER MOUNTING MIDDLE ?
RR BUMPER LH MOUNT ?
RR BUMPER RH MOUNT ?
COVER MIDDLE BOTTOM *cut* ?
REAR BUMPER PANEL PRIMED (X LINE) *DE* ?
REAR BUMPER CLADDING (PDC/SCHWARZ) *DE* ?
UNDERSIDE GUARD PRIMED REAR (X LINE) ?
RH REFLECTOR ?
ULTRASONIC SENSOR BLACK *ms* ?
DECOUPING RING PDC TORQUE CONVERTER *ms* ?

QTY	PRIC	VALUE
1	38.55	38.55
1	756.50	756.50
1	37.00	37.00
1	137.75	137.75
1	192.15	192.15
1	198.30	198.30
1	70.40	70.40
1	1,389.65	1,389.65
1	204.30	204.30
1	332.90	332.90
1	36.10	36.10
1	248.70	497.40
4	5.05	20.20

Total Parts : **3,911.20**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49244
Date Estimated : 26/11/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBU778E	0F78778	30/04/2015	X4 xDrive 28i	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 10/12/18 01:50 Excess S\$ _____

Surveyor's Name PSUL Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 3 days

Repair by part

Labour 1	:	2,995.00
Parts	:	3,911.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	483.43
Grand Total	:	7,389.63

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **