

ASS. REC. BY:

REF:

CS/MSG18021205/Kvd3n2

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Chhia Nyuk Pui

of

MSG

Date/Time:

26/11/18 @ 2:21pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 278M

Insured:

SCE 6665E

at Workshop m/s

Cheng He Motor

Tel:

6755 6142

of

BLK 101A # 01-3741382 Yishun Ind. park A

Policy No:

80406433AVW

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/11/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

3:04pm @ 26/11/18

Person Contacted:

Jure

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLB 278M - X

SCE 6665E - X

28/11/18

Send preli. revised via merimen

ASS. REC. BY:

REF: *MSL**Kenneth*

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s *Cheng Hae*

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *06* days Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SLB 278M* Yr Regn: *01.11*

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: *Toy Vios* c.c. *1.8P7*Colour: *White* A/C: Insured / Std / NI / NASp. Reading: *232503* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *NR05314930517715*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *1P5160R15*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. *7* mm R/Bal. *7* mmL/Bal. *7* mm L/Bal. *7* mmD.O.A. *23/11/18* D.O.I. *26/11/18*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

None N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*1/11 File pass to Catherine**3/11 L/R @ 3550 confirm E heads (Red 1524.08, 30M)*

RECEIVED 8 JAN 2019

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2) *3/1 - typist*Days Of Repair: *6*Resurvey No. of Trip: *2*Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + P.S. \$

Fixtures

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$)

*merimen
3550/-*

150
10
160

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 28 Nov 2018

Preliminary Advice

Insured Vehicle No	: SCE6665E	Accident Date	: 23/11/2018
TP Vehicle No	: SLB278M	Assignment Date	: 26/11/2018
Make	: TOYOTA VIOS	Est. Duration of Repair	: 6.00
Date of Inspection	: 26/11/2018		
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,074.08
Revised Amount	:S\$	3,953.53
Check Items (Estimated)	:S\$	846.71
Total	:S\$	4,800.24

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Nov 2018		26 Nov 2018 14:21 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TENG FOONG YEE, ID: S1735313F		
Main Claimant:	CHUA LENG HUAT, ID: S0155285F		
Vehicle Reg. No.:	SLB278M	Date of Loss:	23/11/2018 21:00 - :59 [94 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	80406433AVW (Comprehensive) Coverage: 30/06/2018 - 29/06/2019
Vehicle Reg. No. (Insured):	SCE6665E	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pul - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/11/2018]		
Driver/Custodian (Insured):	TENG FOONG YEE (52 / Female), NRIC: S1735313F		
Adj Asg. Remarks:	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK. LIABILITY:100%. CONTACT: JUNE PHUA 6755 6142		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

SLB278M

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5285F
Vehicle Details	
Vehicle No.:	SLB278M
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOSE AUTO
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	1NZY131706
Chassis No.:	MR053HY9305177715
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,306.00
Original Registration Date:	06 Jan 2011
First Registration Date:	06 Jan 2011
Transfer Count:	2
Actual ARF Paid:	\$12,306.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Jan 2021
PARF Rebate Amount:	\$7,383.00
Intended COE Rebate Details	
COE Expiry Date:	05 Jan 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$46,129.00
COE Rebate Amount:	\$9,759.00
Total Rebate Amount:	\$17,142.00

The information contained herein is correct as at 24 Nov 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLB278M

TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
 16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/YS

Claim Type: Third Party

Accident Date: 23/11/2018

TP Veh Reg No: SLE6665E

Estimate No: ES1891337/YISHUN

Date: 26 Nov 2018

Policy No: 5078703120-02

Veh Reg No: SLB278M

Make/Model: TOYOTA VIOS E AUTO

Chassis No: MR053HY9305177715

Engine No: 1NZY131706

Reg. Date: 06/01/2011

Estimate Repair Cost to Vehicle No :SLB278M

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 REAR BUMPER	407.25	1 PC	407.25	—
2 REAR BUMPER LH SIDE RETAINER	91.40	1 PC	91.40	—
3 REAR BUMPER LH BRACKET	63.77	1 PC	63.77	✓
4 REAR BUMPER LH REFLECTOR	89.90	1 PC	89.90	✓
5 REAR BUMPER CLIPS	3.50	6 PCS	21.00	—
6 LH TAILLAMP	210.40	1 PC	210.40	✓
7 TAILLAMP PANEL	108.91	1 PC	108.91	✓
8 TAILLAMP INNER RUBBER	24.36	1 PC	24.36	✓
9 TAILLAMP LOWER RETAINER	35.10	1 PC	35.10	—
10 RH TAILLAMP	210.40	1 PC	210.40	✓
11 TAILLAMP INNER RUBBER	24.36	1 PC	24.36	✓
12 REAR BOOT	742.20	1 PC	742.20	—
13 REAR BOOT LOGO	50.20	1 PC	50.20	—
14 REAR BOOT EMBLEM (VIOS)	47.20	1 PC	47.20	—
15 REAR BOOT EMBLEM (E)	41.20	1 PC	41.20	—
16 REAR BOOT INNER LOCK	100.30	1 PC	100.30	✓
17 REAR BOOT INNER RUBBER	175.35	1 PC	175.35	501.12 87.67
18 REAR END PANEL	698.10	1 PC	698.10	—
19 REAR END PANEL INNER TOP GARNISH	200.76	1 PC	200.76	—
20 REAR SPARE TYRE PANEL SIDE SPONGES	191.75	2 PCS	383.50	—
21 REAR SPARE TYRE PANEL FRT SPONGE	186.45	1 PC	186.45	—
			3,912.11	
		Less 25%	978.03	2,934.08

Special Net

22 REVERSE SENSOR	200.00	1 PC	200.00	✓
23 REAR SPARE TYRE PANEL TOP COAT	150.00	1 PC	150.00	✓
			350.00	350.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/YS

Claim Type: Third Party

Accident Date: 23/11/2018

TP Veh Reg No: SLE6665E

Estimate No: ES1891337/YISHUN

Date: 26 Nov 2018

Policy No: 5078703120-02

Veh Reg No: SLB278M

Make/Model: TOYOTA VIOS E AUTO

Chassis No: MR053HY9305177715

Engine No: 1NZY131706

Reg. Date: 06/01/2011

Estimate Repair Cost to Vehicle No :SLB278M

Description	U/Price	Quantity	List Price SS	Amount SS
Labour				
24 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMP, REAR BOOT & ATTACHMENT, TO CUT, WELD & RENEW REAR PANEL, KNOCK & REPAIR REAR SPARE TYRE COMPARTMENT, REAR LH FENDER & REALIGN THE SAME	850.00	1 LA	850.00	750
25 PUTTY & RESPRAY ON REAR PANEL, REAR SPARE TYRE COMPARTMENT, REAR BOOT, REAR BUMPER, REAR BOTH FENDERS	850.00	1 LA	850.00	720
26 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	30.00	1 LA	30.00	✓
27 RUSTPROOFING	60.00	1 LA	60.00	✓
			1,790.00	1,790.00
Total				SS 5,074.08
Add GST @ 7%				355.19
Total Amount Payable				SS 5,429.27

For Cheng Hoe Motor Pte Ltd


AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18021325/KVD3N2
Date: 04/01/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80406433AVW
Claimant Vehicle No :	SLB278M	Insured Vehicle No :	SCE6665E
Date of Loss:	23/11/2018	Nature of Claim:	TP
		Claim No:	576919

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB278M	Engine No:	1NZY131706
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305177715
Reg. Date:	06/01/2011 (Man. Year: 2010)	Odometer:	232503 km
Colour:	White		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60R15	Rear Tyre Size:	195/60R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,284.08	2,866.34	417.74	12.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,790.00	1,560.00	230.00	12.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,074.08	4,426.34	647.74	12.77
Approved Total (Overridden) (\$\$)		3,550.00		
(\$\$)	5,074.08	3,550.00	1,524.08	30.04
+ GST 7.00/7.00% (\$\$)	355.19	248.50	106.69	30.04
Nett Amount (\$\$)	5,429.27	3,798.50	1,630.77	30.04

INSPECTION

Date of Assignment:	26/11/2018	
Date Inspected:	26/11/2018 Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Jan 2019)
Parts: 143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLB278M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	407.25 FL	*407.25 FL
2	1		*REAR BUMPER LH SIDE RETAINER	Distorted	91.40 FL	*91.40 FL
3	1		*REAR BUMPER LH BRACKET	Repair	63.77 FL	*- FL
4	1		*REAR BUMPER LH REFLECTOR	Mtg Cracked	89.90 FL	*89.90 FL
5	6		*REAR BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
6	1		*LH TAILLAMP	Cracked	210.40 FL	*210.40 FL
7	1		*TAILLAMP PANEL	Bent	108.91 FL	*108.91 FL
8	1		*TAILLAMP INNER RUBBER	Necessary	24.36 FL	*24.36 FL
9	1		*TAILLAMP LOWER RETAINER	Distorted	35.10 FL	*35.10 FL
10	1		*RH TAILLAMP	Serviceable	210.40 FL	*- FL
11	1		*TAILLAMP INNER RUBBER	Not Necessary	24.36 FL	*- FL
12	1		*REAR BOOT	Buckled	742.20 FL	*742.20 FL
13	1		*REAR BOOT LOGO	Necessary	50.20 FL	*50.20 FL
14	1		*REAR BOOT EMBLEM (VIOS)	Necessary	47.20 FL	*47.20 FL
15	1		*REAR BOOT EMBLEM (E)	Necessary	41.20 FL	*41.20 FL
16	1		*REAR BOOT INNER LOCK	Dented	100.30 FL	*100.30 FL
17	1		*REAR END PANEL	Bent	698.10 FL	*698.10 FL
18	1		*REAR END PANEL INNER TOP GARNISH	Dented	200.76 FL	*200.76 FL
19	2		*REAR SPARE TYRE PANEL SIDE SPONGES	Deformed	383.50 FL	*383.50 FL
20	1		*REAR SPARE TYRE PANEL FRT SPONGE	Cracked	186.45 FL	*186.45 FL
21	1		*REAR BOOT INNER RUBBER (50%)	Distorted	131.51 FS	*87.67 FS
22	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
23	1		*REAR SPARE TYRE PANEL TOP COAT	Not Necessary	150.00 FS	*- FS
					Sub Total (S\$)	4,218.27 3,725.90
					- List Item Discount on L Items 25.00/25.00% (S\$)	934.19 859.56
					Total Parts (S\$)	3,284.08 2,866.34

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR BUMPER ASSY, TAILLAMP, REAR BOOT & ATTACHMENT, TO CUT, WELD & RENEW REAR PANEL, KNOCK && REPAIR REAR SPARE TYRE COMPARTMENT, REAR LH FENDER & REALIGN THE SAME	New	850.00	750.00
2	PUTTY & RESPRAY ON REAR PANEL, REAR SPARE TYRE COMPARTMENT, REAR BOOT, REAR BUMPER, REAR BOTH FENDERS	New	850.00	720.00
3	REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	New	30.00	30.00
4	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (\$\$)			1,790.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS/AIG18018993/Gsbe2	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120 ATTN : SHAWN WUI		Date : 04-01-2019	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	SLJ 2282U	Veh. Inspected	GBA 5383H
Policy No.		Coverage (\$)	0.00
Claim No.	8010120000SG-003	Excess (\$)	0.00
Assign From	SHAWN WUI	Assign Date	18/10/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JTFAT35Y603001252	Colour	RED
Odometer	444137	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	YOKOHAMA	5 mm
L/H Front Tyre	195 R15	YOKOHAMA	5 mm
R/H Rear Tyre	155 R12	YOKOHAMA	5 mm
L/H Rear Tyre	155 R12	YOKOHAMA	5 mm
4. Description of Damages			
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information			
Accident Date	22/07/2018	Inspection Date	15/11/2018
Survey held at	385 SIN MING DRIVE #01-02		
Repairer	TEAM AUTOPRO PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	