

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE

Lonpac

ATTN: MOTOR CLAIMS DEPT

QUOTE NO :
ACCIDENT DATE 23/11/2018@1520HRS
VRN : SJX33355U
MODEL : Toyota Estima
TP VRN : YN1975K

Qty S\$ Unit S\$ Amt S\$ Labor

PARTS REPLACEMENT

1. Body Repair

1 Front Bumper	1	\$	585.00	\$	585.00 <i>Rx</i>
2 Front Bumper Clips	10	\$	5.50	\$	55.00 <i>y</i>
3 Front Bumper Outer Bracket LH	1	\$	65.00	\$	65.00 <i>x</i>
4 Front Fender LH	1	\$	685.00	\$	685.00 <i>Rx</i>
5 Front Fender Shield LH	1	\$	175.00	\$	175.00 <i>x</i>
6 Front Fender Shield Clips LH	8	\$	5.50	\$	44.00 <i>x</i>
7 Headlamp LH	1	\$	2,232.00	\$	2,232.00 <i>x</i>

Discount 25%

\$ (960.25)

TOTAL \$ 2,880.75

2. Labor Charges

1 Panel beat, cut, weld, re-align and replace damaged parts of affected area	<i>375</i>	\$	750.00
2 Putty, Blend and paint affected area	<i>500</i>	\$	750.00
3 Check wiring, re-align headlamps and ensure proper function	<i>20</i>	\$	80.00

Sub Total : \$ 1,580.00

Grand Total : \$ 4,460.75

Add 7% GST : \$ 312.25

Nett Total : \$ 4,773.00

No. of repair days:

3

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CUSTOMER SIGNATURE

Tanpin 97495749
- wp
28/11/18 4:55pm
3 days
sure (lkkauto.com)
Reply after repair.

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Panel beat, Cut, Weld, Re-align Damaged Part Of End Panel	New	125 250.00
Gross Labour Cost (S\$)			250.00

Hitachi Capital Asia Pacific Pte. Ltd/SLW8267G/31/10/2018 14:03. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

Signature
28/11