

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLH 5579 E.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	OUTER DOOR SEAL - LH REAR <i>new</i>	\$ 192.00	✓ 154
22	BONDING AGENT <i>new</i>	\$ 43.00	? X
23	CLEANING SOLUTION <i>new</i>	\$ 64.00	? X
24	DOOR CATCH <i>new</i>	\$ 105.00	X
25	COVER FOR DOOR CATCH	\$ 14.00	X
26	SUNDRIES <i>new</i>	\$ 500.00	✓ 9.60
TOTAL SPARE PARTS		:	\$ 8,319.00
TOTAL LABOUR CHARGES		:	\$8,432.00
GRAND TOTAL		:	\$16,751.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King.
Surveyed Date : 27/11/18.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 06 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1357/2018/PH
Date : 23-Nov-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

We took 7 days of repairs exclude

1 Sunday - jb - 16 May 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Lee Wayne , Shane
Address : Blk 403C Fernvale Lane
#16-163
Singapore 793403
Telephone : HP +65 98639323
Type of Claim : Own Damage Claims
Policy No. : 1700028316-01
Vehicle No : **SLH 5579 E**
Model Code : Audi A4 Sedan 1.8 TFSI
Model / Year : Jul-14
Engine No : CJE 081312
Chassis No : WAUZZZ8K8EA143896
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 22-Nov-18
Place of Accident : Somapah Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLH 5579 E .

S/N	Nature of Jobs	Estimated Charges			
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N	\$ 480.00	\$	480.00
2	To remove and transfer lhs front and lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N	\$ 560.00	\$	560.00
3	To dismantle front bumper, lhs front fender, lhs front door and lhs rear door. To repair lhs rear fender and lhs sill panel. To renew lhs front fender, lhs front door and lhs rear door. Re-organise crash management components. Reinstall all parts removed.		\$ 3,600.00	\$	2,250.00
4	To respray lhs front fender, lhs front door, door handle, lhs rear door, lhs rear fender and lhs sill panel.		\$ 3,600.00	\$	2,850.00
5	To carry out diagnostic check.	S/N	\$ 192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 8,432.00	\$	6,332.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLH 5579 E.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT FENDER - LH	\$ 860.00	\$ 688.00
2	ATTACHMENT PARTS FOR FRONT FENDER	\$ 49.00	
3	BRACKET FOR FENDER	\$ 46.00	
4	BRACKET FOR DEFORMATION	\$ 43.00	
5	FRONT FENDER BRACE - LH LOWER	\$ 103.00	
6	STONE CHIP GUARD - LH FRONT	\$ 39.00	\$ 37.92
7	WHEEL HOUSING LINER	\$ 215.00	
8	ATTACHMENT PARTS FOR WHEEL HOUSING LINER	\$ 38.00	
9	FRONT DOOR - LH	\$ 2,509.00	\$ 2,007.20
10	ATTACHMENT PARTS FOR DOOR	\$ 77.00	
11	OUTER DOOR SEAL	\$ 184.00	\$ 146.80
12	BONDING AGENT	\$ 43.00	
13	CLEANING SOLUTION	\$ 64.00	
14	DOOR CATCH	\$ 105.00	
15	COVER FOR DOOR CATCH	\$ 14.00	
16	DOOR HANDLE, EXTERIOR	\$ 131.00	
17	DOOR HANDLE KEY HOLE CAP	\$ 26.00	
18	DOOR HANDLE MOUNTING BAR	\$ 274.00	
19	REAR DOOR - LH	\$ 2,509.00	\$ 2,007.20
20	ATTACHMENT PARTS FOR DOOR	\$ 72.00	
SUB-TOTAL SPARE PARTS		\$ 7,401.00	\$ 4,887.12

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Material List for Accident Vehicle Regn No. SLH 5579 E.

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 23 May 2019 2:48 PM
To: Boo seng yak; Carrine Leong; jiayee.yap@premiumauto.com.sg; Chang Chee Sing; SUR
Subject: RE: FINAL REVISION - SLH5579E - OD AIG - SURVEYED 27 NOV 18

Dear Mr Boo,

Confirm repair cost of \$11,382.72 before excess \$800 and GST @ 7 days of repairs

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Thursday, 16 May 2019 3:30 PM

To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - ALH5579E - OD AIG - SURVEYED 27 NOV 18

Hi Adrian and all,

Revised estimate attached.

Please confirm repair cost of \$11,382.72 @ 7 days of repairs exclude 1 Sunday.

Your early closure is appreciated.

Best regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLH 5579 E

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1357/2019/NS

16 Aug 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

1

total pages

RE: INSURANCE CLAIM FOR SLH 5579 E, Audi A4 1.8 TFSI MU

With reference to the above-mentioned vehicle, no. **SLH 5579 E**, claimant,
Mr. Lee Wayne, Shane please find the related document per attached.

1. A copy of the Original invoice no. 85014108 – S\$11,323.51.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the
payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at
6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLH 5579 E

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 11:45

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85014108 Date: 15/08/2019 Order: SLH5579E Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SLH5579E (V 23612)	Regn Date: 31/07/2014	Mileage: 75205	WIP No.: 33074
Model: A4 1.8 TFSI MU (EU6)	Chassis: WAUZZZ8K8EA143896	Engine: CJE081312	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-800.00	1.00	-800.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO REMOVE AND TRANSFER LHS FRONT AND REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	560.00	1.00	560.00
S	BODYWORK	M: TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR AND LHS REAR DOOR. TO REPAIR LHS REAR FENDER AND LHS SILL PANEL. TO RENEW LHS FRONT FENDER, LHS FRONT DOOR AND REAR DOOR. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	2250.00	1.00	2,250.00
S	BODYWORK	M: TO RESPRAY LHS FRONT FENDER, LHS FRONT DOOR, LHS REAR DOOR, DOOR HANDLE, LHS REAR FENDER AND LHS SILL PANEL	2850.00	1.00	2,850.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8K0821105J	FENDER	1.00	860.00	860.00
X	A8K0831051J	(A) (SK) DOOR	1.00	2509.00	2,509.00
X	A8K5833051D	DOOR	1.00	2509.00	2,509.00
X	A8K5839911Q	SEAL	1.00	183.50	183.50
X	A8K0853823	STONEGUARD	1.00	47.40	47.40
X	A8K0837911Q	SEAL	1.00	192.50	192.50
X	AN 0161857	POP-RIVET	4.00	3.00	12.00

Parts 5,050.72
Labour 0.00
Sublet 6,332.00
Menus 0.00
Lubricant 0.00

Sub-Total 10,582.72

7% GST 740.79

Grand Total 11,323.51



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLH5579E

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1357/2018/TF
24 December 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 1.8 TFSI MU
Vehicle Chassis No. : WAUZZZ8K8EA143896
Vehicle Regn No. : **SLH5579E**
Vehicle Mileage : 73649 KM
Vehicle Owner : Mr. Lee Wayne, Shane
Certificate No : 1700026316-01
Own Damage Excess : S\$ 856.00 (inclusive of 7% GST)
Accident Date : 22 November 2018
Place : Somapah Road
Repair Cost : S 11 323.51
WIP No. : 33074
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 24/12/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Nov 2018		27 Nov 2018 12:49 Edit Adj Rpt	S\$11,382.72 Edit Estimates	S\$11,382.72 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LEE WAYNE, SHANE , ID: S8236619I, Tel: +6598639323, Email: LEEWAYNESHANE@GMAIL.COM									
Vehicle Reg. No.: SLH5579E		Date of Loss: 22/11/2018 00:00 - :59 [51 Months and 22 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 5670221605SG		Policy/Cover Note No.: (Comprehensive) Excess: S\$800.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 06/12/2018]									
Driver/Custodian: LEE WAYNE, SHANE (36 / Male) , NRIC: S8236619I, Tel: +6598639323 Email: LEEWAYNESHANE@GMAIL.COM									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (03/12/2018): Alert - Adj Mandate Approved (S\$12920.25) - SLH5579E - Claim Handler: Dally Amri... - AIG_SG (30/11/2018): Alert - Adj Mandate Maintained - SLH5579E - Claim Handler: Dally Amri, Mimi Zari... - AIG_SG (28/11/2018): Alert - Adj Mandate Approved (S\$12125.00) - SLH5579E - Claim Handler: Dally Amri... - AIG_SG (28/11/2018): SLH5579E / OD / 22/11/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLH5579E (5670221605SG)**

OD

Nov 22 2018 12:00AM

[LEE WAYNE, SHANE]

Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View In Browser ▼	
Assessment Reports			1 per page ▼ ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	27/11/18 13:51	Adjuster Immediate Advice		Load HTM
2	29/11/18 16:59	Adjuster Immediate Advice		Load HTM
Photos/Images			3 per page ▼ ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	27/11/18 13:40	General View		Load JPG ☒
2	27/11/18 13:40	General View		Load JPG ☒
3	27/11/18 13:40	General View		Load JPG ☒
4	27/11/18 13:40	General View		Load JPG ☒
5	27/11/18 13:40	General View		Load JPG ☒
6	27/11/18 13:40	General View		Load JPG ☒
7	27/11/18 13:40	General View		Load JPG ☒
8	27/11/18 13:40	General View		Load JPG ☒
9	27/11/18 13:40	General View		Load JPG ☒
10	27/11/18 13:40	General View		Load JPG ☒
11	27/11/18 13:40	General View		Load JPG ☒
12	27/11/18 13:40	General View		Load JPG ☒
13	27/11/18 13:40	General View		Load JPG ☒
14	27/11/18 13:40	General View		Load JPG ☒
15	27/11/18 13:40	General View		Load JPG ☒
16	27/11/18 13:40	General View		Load JPG ☒
17	27/11/18 13:40	General View		Load JPG ☒
18	27/11/18 13:40	General View		Load JPG ☒
19	27/11/18 13:40	General View		Load JPG ☒
20	27/11/18 13:40	General View		Load JPG ☒
21	27/11/18 13:40	General View		Load JPG ☒
22	27/11/18 13:40	General View		Load JPG ☒
23	27/11/18 13:40	General View		Load JPG ☒
24	27/11/18 13:40	General View		Load JPG ☒
Documentation			1 per page ▼ ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	27/11/18 13:45	Singapore Accident Statement		Load PDF
2	27/11/18 13:46	Certificate of Insurance		Load PDF
3	27/11/18 13:46	Insured's Driving License		Load PDF
4	27/11/18 13:46	MARK ESTIMATE		Load PDF
5	29/11/18 16:52	SURVEYOR MARKING		Load PDF
6	29/08/19 09:56	DISCHARGE VOUCHER		Load PDF
7	29/08/19 09:56	WORKSHOP INVOICE		Load PDF

Linked Accident Report Documents

			View	View in Browser ▼
Assessment Reports			1 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/11/18 17:29	Accident Statement	 Load HTM	
Photos/Images			3 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/11/18 17:22	Accident Photo	 Load JPG	☒
2	22/11/18 17:22	Accident Photo	 Load JPG	☒
3	22/11/18 17:22	Accident Photo	 Load JPG	☒
4	22/11/18 17:22	Accident Photo	 Load JPG	☒
5	22/11/18 17:22	Accident Photo	 Load JPG	☒
6	22/11/18 17:22	Accident Photo	 Load JPG	☒
7	22/11/18 17:22	Accident Photo	 Load JPG	☒
8	22/11/18 17:22	Accident Photo	 Load JPG	☒
9	22/11/18 17:22	Accident Photo	 Load JPG	☒
10	22/11/18 17:22	Accident Photo	 Load JPG	☒
11	22/11/18 17:22	Accident Photo	 Load JPG	☒
12	22/11/18 17:22	Accident Photo	 Load JPG	☒
Documentation			1 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/11/18 17:11	Sketch Plan	 Load JPG	☒
2	22/11/18 17:11	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18021369/AVD3S2

Date: 29/08/2019

REFERENCE

Insured/Claimant: LEE WAYNE, SHANE
Date of Loss: 22/11/2018

Policy No:

Nature of Claim:

OD Claim No: 5670221605SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLH5579E**
Make & Model: AUDI A4, 1.8 TFSI MU CVT (A)
Reg. Date: 31/07/2014 (Man. Year: 2014)
Colour: White
Engine Capacity: 1798 cc
Market Value/New Car Price: S\$75,000.00
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: CJE081312
Chassis No: WAUZZZ8K8EA143896
Odometer: 72527 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,319.00	5,050.72	3,268.28	39.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,432.00	6,332.00	2,100.00	24.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,751.00	11,382.72	5,368.28	32.05
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	15,951.00	10,582.72	5,368.28	33.65
+ GST 7.00/7.00% (S\$)	1,116.57	740.79	375.78	33.65
Nett Amount (S\$)	17,067.57	11,323.51	5,744.06	33.65

INSPECTION

Date of Assignment: 27/11/2018

Date Inspected: 27/11/2018

Estimated Period of Repair: 7.0 days

Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER-LH	Dented	860.00 FS	*688.00 FS
2	1		*ATTACHMENT PARTS FOR FRONT FENDER	Not Necessary	49.00 FS	*- FS
3	1		*BRACKET FOR FENDER	Not Necessary	46.00 FS	*- FS
4	1		*BRACKET FOR DEFORMATION	Not Necessary	43.00 FS	*- FS
5	1		*FRONT FENDER BRACE-LH LOWER	Not Necessary	103.00 FS	*- FS
6	1		*STONE CHIP GUARD-LH FRONT	Necessary	39.00 FS	*37.92 FS
7	1		*WHEEL HOUSING LINER	Not Necessary	215.00 FS	*- FS
8	1		*ATTACHMENT PARTS FOR WHEEL HOUSING LINER	Not Necessary	38.00 FS	*- FS
9	1		*FRONT DOOR-LH	Dented	2,509.00 FS	*2,007.20 FS
10	1		*ATTACHMENT PARTS FOR DOOR	Not Necessary	77.00 FS	*- FS
11	1		*OUTER DOOR SEAL	Necessary	184.00 FS	*146.80 FS
12	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS
13	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
14	1		*DOOR CATCH	Not Necessary	105.00 FS	*- FS
15	1		*COVER FOR DOOR CATCH	Not Necessary	14.00 FS	*- FS
16	1		*DOOR HANDLE, EXTERIOR	Repair	131.00 FS	*- FS
17	1		*DOOR HANDLE KEY HOLE CAP	Repair	26.00 FS	*- FS
18	1		*DOOR HANDLE MOUNTING BAR	Not Necessary	274.00 FS	*- FS
19	1		*REAR DOOR-LH	Dented	2,509.00 FS	*2,007.20 FS
20	1		*ATTACHMENT PARTS FOR DOOR	Not Necessary	72.00 FS	*- FS
21	1		*OUTER DOOR SEAL-LH RERA	Necessary	192.00 FS	*154.00 FS
22	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS
23	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
24	1		*DOOR CATCH	Not Necessary	105.00 FS	*- FS
25	1		*COVER FOR DOOR CATCH	Not Necessary	14.00 FS	*- FS
26	1		*SUNDRIES	Necessary	500.00 FS	*9.60 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	8,319.00	5,050.72
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HANRESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS FRONT AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES.	New	560.00	560.00
3	TO DISMANTLE FRONT BUMPER,LHS FRONT FENDER,LHS FRONT DOOR AND LHS REAR DOOR. TO REPAIR LHS REAR FENDER AND LHS SILL PANEL.TO RENEW LHS FRONT FENDER,LHS FRONT DOOR AND LHS REAR DOOR.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED. INCLUSIVE THE REPAIR OF DOOR HANDLE,EXTERIOR AND DOOR HANDLE KEY HOLE CAP.	New	3,600.00	2,250.00
4	TO RESPRAY LHS FRONT FENDER,LHS FRONT DOOR,DOOR HANDLE,LHS REAR DOOR,LHS REAR FENDER AND LHS SILL PANEL.	New	3,600.00	2,850.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (S\$)			8,432.00	6,332.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >