

AXA INSURANCE PTE LTD.
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. : **SLT1577Z**
CHASSIS NO : GP71117541
ENGINE NO : LEB6321637
MAKE / MODEL : HONDA SHUTTLE HYBRID 1.5 AUTO
DATE OF ACCIDENT : 17.11.2018 @ 12:00hrs
YOUR INSURED VEHICLE NUMBER : SJJ2788B

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PARTS DISCRIPTION

REAR RH FENDER *Repair*
REAR BUMPER ASSY *Scr*
REAR BUMPER CLIPS *new*

QTY	List Price	Total List Price
1	\$ 663.40	\$ 663.40
1	\$ 802.50	\$ 802.50
1 SET	\$ 30.25	\$ 30.25
Total		\$ 1,496.15
ADD 10%		\$ 149.62
TOTAL PARTS		\$ 1,645.77

832.75
+ 10%
916.02

LABOUR CHARGES

TO REMOVE, REPLACE & REPAIR ALL DAMAGES PARTS DUE TO ACCIDENT

\$ ~~700.00~~ *350*

TO SPRAY PAINT ON THE AFFECTED AREAS DUE TO THE ACCIDENT

\$ ~~600.00~~ *400*

TO APPLY ANTI RUSTPROOFING

\$ ~~100.00~~ *40*

Repair
4p 900/10068
4 days

TOTAL LABOUR **\$ 1,400.00**

SUB TOTAL **\$ 3,045.77**

790

27/11/18 @ 1600

Resurvey after repair

Prepared By : -
LYNN AHMAD
Motor Claims Manager
Motorway Car Care Centre Pte Ltd
TEL: 6571 9635 FAX : 6278 5535
EMAIL: lynn@motorway.com.sg

916.02
790.00
1706.02
20%
1364.81
45-1,350
4 days