



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

26/11/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPAXA

xiao Tony

4BAPG56060NM25916

Accident date: 25/11/2018

Estimated repair cost for vehicle no: SJZ5593S BMW 320i 2.0 A '10

CHASSIS: WBAPG56060NM25916

S/n	Qty	Items	U/price	Amount
1	1	Front R/H Door <i>Dented</i>		\$1,204.15 ✓
2	2	Front R/H Door Hinge	\$58.60	\$117.20 x
3	1	Front R/H Door Side Mirror Assy <i>new</i>		\$761.90 +
4	1	Front R/H Door Side Mirror Cover		\$96.20 +
5	1	Front R/H Door Outer Handle <i>new</i>		\$70.70 x
6	1	Front R/H Door Outer Handle Key Cover		\$35.35 x
7	1	Front R/H Door Inner Lock <i>new</i>		\$287.45 ✓
8	1	Front R/H Door Inner Rubber <i>new</i>		\$164.35 ✓
9	1	Front R/H Door Inner Trim Board <i>new</i>		<u>\$1,594.60</u> 965
10	1	Front R/H Door Frame Sticker <i>new</i>		\$75.00 ✓
11	1	Front R/H Door Gear Motor Assy <i>new</i>		\$288.55 x
12	1	Rear R/H Door <i>Dented</i>		\$1,204.15 ✓
13	2	Rear R/H Door Hinge <i>Lower Bent</i>	\$58.60	\$117.20 58.60
14	1	Rear R/H Door Outer Handle <i>new</i>		\$70.70 x
15	1	Rear R/H Door Outer Handle Cover <i>new</i>		\$354.35 x
16	1	Rear R/H Door Inner Lock <i>new</i>		\$287.75 x
17	1	Rear R/H Door Inner Rubber <i>new</i>		\$164.35 ✓
18	1	Rear R/H Door Inner Trim Board <i>new</i>		\$1,086.05 x
19	1	Rear R/H Door Frame Sticker <i>new</i>		\$75.00 ✓
20	1	Rear R/H Door Gear Motor Assy <i>new</i>		\$230.85 x
21	1	Rear R/H Door Centre Pillar <i>new</i>		\$2,477.65 x
22	1	Rear R/H Rim <i>at</i>		\$810.75 ✓
23	1	Rear R/H Tyre <i>new</i>		\$380.00 x
24	1	Rear R/H Lower Arm		\$226.45 x
25	1	Rear R/H Knuckle Arm		\$1,034.20 x
26	1	Rear R/H Knuckle Arm Bearing <i>new</i>		\$229.75 x
27	1	Rear R/H Trailing Arm		\$180.45 x
28	1	Rear R/H Stabilizer Bar		\$300.05 x
	1	Rear R/H Shock Absorber		\$330.30 x

30	1	Rear Bumper <i>Repair</i>		\$1,136.80	X
31	1	R/H Rocker Panel Skirt <i>Rhd</i>		\$612.80	✓
32	16	R/H Rocker Panel Skirt Clip <i>ru</i>	\$6.50	\$104.00	30

5851.60
5369.02

Subtotal :- \$15,809.05

Labour charges

To remove & refit seat cushion & carpet	\$380.00	X
To remove & refit front & rear R/H door, glass, lock, rubber, frame sticker & trim board	\$380.00	200
To remove & refit reverse sensor	\$100.00	X
To remove & refit rear R/H undercarriage	\$380.00	X
To check wheel alignment	\$150.00	20
To check wiring	\$100.00	30
Tuff kote	2110	\$150.00 X
Panel beating	\$2,000.00	800
Spray painting	\$1,800.00	1000

Subtotal :- \$5,440.00

Total:- \$21,249.05

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Supplementary 1028.92
total 8507.94
4/s 6.8k.
06 arp.

6.8k

Adrian - LKK - AXA



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

26/11/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 25/11/2018

Estimated repair cost for vehicle no: SJZ5593S BMW 320i 2.0 A '10

S/n	Qty	Items	U/price	Amount
1	1	Footwell module <i>Damaged</i>		\$851.50 ✓

851.50

808.92

Subtotal :- \$851.50

Labour charges

To remove & refit footwell module

220

~~\$180.00~~ 100

To reset computer

~~\$380.00~~ 120

Subtotal :- \$560.00

Total:- \$1,411.50

Supplementary: 1028.92