

15/02/2018

INS. CASE OWNER:

CC / AXA1802

LKK
IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

FAM BELTA

9400AM BIR HUSSEIN

#500

(YES / NO)

HP:

D.O.A:

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

88M010A (84209)

AW316735

Bnjar

JPP UluMuti PO.

If NO, Driver Name / Age:

Driver Tel No.:

(VL: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SBS 5m

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

9400AM - X

FAM BELTA - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

45 \$5,050.00

(4 days) Reduction:

56 %

Email

Call

FINAL SETTLEMENT

Date/Time: 07.03.19

Confirm with YONG SHUN

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

36

If NO or B 28, Ass. Lia:

Repair Cost:

WHS: \$5,338.50

OI LOST CONTROL + TP

Loss of Rental (LOR):

\$5 -

(days)

Loss of Use (LOU):

\$5,300.00

(5325 x 4 days)

Loss of Income (LOI):

\$5 -

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

\$5 2.00

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

Legal Cost

\$5 -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

7350

Total:

\$5,635.50

Global Sum \$5:

FINAL PAYMENT

Date/Time: 07.03.19

Confirm with: YONG SHUN

Email

Call

Payee 1:

\$5,635.50

Name 1:

LEXBUILD INTERNATIONAL PTE LTD

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

Kah

REF: AXA

ASSIGNMENT

From:

Date: 28/11/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SBS 5M

at Workshop m/s

Go Ahead

of

2 layang way

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Before 1pm

Yongshun @ 9029 6574

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SBS 5M

Yr Regn:

16 Sep 2015

Type: M.Car / M.Cycle / B/T / Van / Lorry / T/B / Prime Mover /

Truck / Trailer or

Make:

Volvo B9TL

C.C. 936x

Colour:

Green

A/C:

Insured / Std / NI / NA

Sp Reading:

221858

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

YV354P923FA173381

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

275/70 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Conti

Front

Rear

R/Bal.

4

mm

R/Bal.

4.4

mm

L/Bal.

4

mm

L/Bal.

4.4

mm

D.O.A.

2/11/18

D.O.I.

28/11/18

Survey held at

Go Ahead

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s Body.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

45:44.060 (RED:5068.40 56%)

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS. St

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Week-end (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18021387/eb3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 27-11-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBM 6417A	Veh. Inspected	SBS 5M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	27/11/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	02/11/2018	Inspection Date
Survey held at	LEXBUILD INTERNATIONAL PTE LTD 2 WOODLANDS SECTOR 1, #05-12 (WOODLANDS SPECTRUM 1) SINGAPORE 738068	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

27th Nov 2018

AXA Insurance Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Dear Sir/Mdm



Quotation No.: Q18-OPS-1220

Estimated Cost of Repair job for SBS5M (Accident on 02/11/2018, along JALAN ANGIN LAUT / UPPER CHANGI ROAD involving SBS5M & FBM6417A)

We are pleased to submit herein, our quotation for your consideration.

S/N	Description	Qty.	Unit Price	Total Price
1	Supply skilled labour to Replace LHS 2 nd body panel with fuel cap (LHS of exit door)	1 day	\$880.00	\$880.00 440
2	Supply skilled labour & sealant to replace exit door skirting	1 day	\$880.00	\$880.00 440
3	Supply skilled labour & sealant to replace exit door RHS pillar cover & bracket	1 day	\$880.00	\$880.00 440
4	Supply skilled labour to replace exit door rubber	1 day	\$880.00	\$880.00 440
5	Supply skilled labour to Replace LHS body panel with fuel cap (RHS of exit door)	1 day	\$880.00	\$880.00 440
6	Supply skilled painter & paint material to spraypaint LHS 2 nd body panel with fuel cap(LHS of exit door), exit door skirting, exit door RHS pillar cover & bracket, LHS 3 rd bodypanel with fuel cap (RHS of exit door) - (Green color, Black Colour)	3 day	\$880.00	\$2,640.00 1320
7	LHS 2 nd body panel with fuel cap (LHS of exit door)	1 pcs	\$605.22	\$605.22
8	Exit door skirting	1 pcs	\$452.56	\$452.56
9	Exit door RHS pillar cover	1 pcs	\$67.85	\$67.85
10	Exit door RHS pillar structure	1 pcs	\$75.60	\$75.60
11	LHS 3 rd body panel with fuel cap (RHS of exit door)	1 Pcs	\$663.92	\$663.92
12	Exit door rubber	1 pcs	\$543.33	\$543.33
13	"Go-Ahead Singapore" Sticker	1 pcs	\$50.00	\$50.00
14	Advertisement sticker	1 lot	\$500.00	\$500.00 400
Sub-total				\$9,118.48

LexBuild International Pte. Ltd.
2 Woodlands Sector 1, #05-12 (Woodlands Spectrum 1), Singapore
738068.
Tel: (65) 6456 3533, Fax: (65) 6456 3353
Website: www.LexBuild.com, Email: sales@LexBuild.com



9998.48

Terms and Conditions:

Payment Terms : 30 days upon invoice

Quotation Validity : 30 days

Lead Time : 8 Working day (not inclusive waiting for parts)

Price quoted subject to 7% GST

Yours faithfully



Tien Yong Shun
Operation Executive

Approval by

Kali 16/11/15
28/11/15 1000hrs
4 hrs
L/S
After Repair photo

Auto Consultants hence notify
the Repairer of the following:

- Survey before/after spray painting
- To display damaged part(s) during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resubmitted and subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

L/S 4050

10/12/15
L/S \$4050/ 4 hrs

LexBuild International Pte. Ltd.

2 Woodlands Sector 1, #05-12 (Woodlands Spectrum 1), Singapore 738068.

Tel: (65) 6456 3533, Fax: (65) 6456 3353

Website: www.LexBuild.com, Email: sales@LexBuild.com



ROC / CR GST Reg. No. 200004370R

27th Nov 2018

Quotation No.: Q18-OPS-1220

AXA Insurance Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Dear Sir/Mdm

Estimated Cost of Repair job for SBS5M (Accident on 02/11/2018, along JALAN ANGIN LAUT / UPPER CHANGI ROAD involving SBS5M & FBM6417A)

We are pleased to submit herein, our quotation for your consideration.

S/N	Description	Qty.	Unit Price	Total Price
1	Supply skilled labour to Replace LHS 2 nd body panel with fuel cap (LHS of exit door)	1 day	\$880.00	\$880.00 440
2	Supply skilled labour & sealant to replace exit door skirting	1 day	\$880.00	\$880.00 440
3	Supply skilled labour & sealant to replace exit door RHS pillar cover & bracket	1 day	\$880.00	\$880.00 440
4	Supply skilled labour to replace exit door rubber	1 day	\$880.00	\$880.00 440
5	Supply skilled labour to Replace LHS body panel with fuel cap (RHS of exit door)	1 day	\$880.00	\$880.00 440
6	Supply skilled painter & paint material to spraypaint LHS 2 nd body panel with fuel cap(LHS of exit door), exit door skirting, exit door RHS pillar cover & bracket, LHS 3 rd bodypanel with fuel cap (RHS of exit door) – (Green color, Black Colour)	3 day	\$880.00	\$2,640.00 1320
7	LHS 2 nd body panel with fuel cap (LHS of exit door)	1 pcs	\$605.22	\$605.22
8	Exit door skirting	1 pcs	\$452.56	\$452.56
9	Exit door RHS pillar cover	1 pcs	\$67.85	\$67.85
10	Exit door RHS pillar structure	1 pcs	\$75.60	\$75.60
11	LHS 3 rd body panel with fuel cap (RHS of exit door)	1 Pcs	\$663.92	\$663.92
12	Exit door rubber	1 pcs	\$543.33	\$543.33
13	"Go-Ahead Singapore" Sticker	1 pcs	\$50.00	\$50.00
14	Advertisement sticker	1 lot	\$500.00	\$500.00 400
Sub-total				\$9,118.48

LexBuild International Pte. Ltd.

2 Woodlands Sector 1, #05-12 (Woodlands Spectrum 1), Singapore 738068.

Tel: (65) 6456 3533, Fax: (65) 6456 3353

Website: www.LexBuild.com, Email: sales@LexBuild.com



ROC / CR GST Reg. No. 200004370R

Terms and Conditions:

Payment Terms : 30 days upon invoice

Quotation Validity : 30 days

Lead Time : 8 Working day (not inclusive waiting for parts)

Price quoted subject to 7% GST

Yours faithfully



Tien Yong Shun
Operation Executive

Approval by

Kali 11/11/18
28/11/18 1000hrs
4 Days
L/S
After Repair photo

Auto Consultants hence notify
Repairer of the following:

- Survey before/after spray painting
- Spray damaged part(s) during recovery
- Repair prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Legal modification(s) is allowed
- Supplementary item(s) must be resubmitted
- Subject to final approval from Insurance company


Acknowledged by Repairer
Signature:
Date:

[Home](#) > [Buy Information](#) > [Buy Business Profile and Other Information](#)

Type of Business Information

Instant Information

 [Business Profile](#)

 [Business Profile with Certificate of production](#)

 [Corporate Compliance and Financial Profile](#)

 [People Profile](#)

 [Extracts](#)


 [Certificates](#)

 [Register](#)

 [Product Bundle](#)

Package Information

 [Standard Package](#)

 [Pick and Choose](#)

Useful eServices

[Transaction Status Enquiry](#)

[Product Authentication](#)

[Refund Application](#)

[Refund Enquiry](#)

Enter Entity Name or Unique Entity Number (UEN)

201541900C

Search Criteria



Captcha (Enter the above 5 characters) *

Search

Entity

PA

Filter by  Reset

Showing 1 - 1 of 1 Rows

Show [« Back](#) [Next »](#)


Name : GO AHEAD SINGAPORE PTE. LTD.(n.k.a)
GO AHEAD LOYANG PTE. LTD.(f.k.a)

UEN : 201541900C

Status : LIVE COMPANY

Address : 2 LOYANG WAY SINGAPORE 508776

Industry  : OTHER TRANSPORTATION SUPPORT ACTIVITIES N.E.C.

Annual Return  : Last filed on 04/10/2018 for Financial Year Ending 30/06/2018

Annual General Meeting  : Last held on 04/10/2018

Financial Statements Filed  :

[Buy information](#)

Initiatives of ACRA

File Financial Statement at



Download
XBRL Tool



Download
Mobile APP



Follow us



Primary Contact/Insured

BIN HUSSAIN SADDAM
454 CLEMENTI AVENUE 3, #18-554, 120454, Singapore
90722275
SADDAM_94@HOTMAIL.COM

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

TYPE



SENT

11/27/18 5:06 PM

FROM

WANG Peter

SUBJECT

TP Excess: \$500

BODY



TYPE



SENT

11/27/18 4:59 PM

FROM

WANG Peter

SUBJECT

Liability unclear - pending TP video

BODY

Pls request for TP video.





MANDATE REQUEST FOR S8M011QA

Type

🔗 Question

Message

Liability: Insured lost control and hit third party vehicle (refer to TP video). Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$4,333.50 (w/GST) Loss of Use: \$1,300.00 (4days x \$325) LTA : \$2.00 Total: \$5,635.50 Immediate Advice with Mandate uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng
(15/02/2019)

Reply



Pls proceed DS with quantum as proposed

Type

🔗 Question

Message

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	FBM 6417A (Insd veh)	Model:	VOLVO B9TL
	SBS 5M (TP veh)		
Date of Accident:	02/11/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	10,698.37
Final Repair Cost	:	\$	4,333.50
Loss of Use	:	\$	1,300.00
Rental (if any)	:	\$	4 days at \$325.00 per day
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	5,635.50

Is Third Party Workshop GIA Registered?		<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: ____		
BOLA Liability: ____ (%)		Assessed Liability (*): ____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks				

Payment Instruction: Payee's Breakdown			
1)	LEXBUILD INTERNATIONAL PTE LTD	:	\$ 5,635.50

NUR SHAQILAH BTE ABDOL
WAHAB

14/03/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18021387/K1eb3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: PETER WANG		Date : 14-03-2019 Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBM 6417A	Veh. Inspected	SBS 5M
Policy No.	AN3162375	Coverage (\$)	0.00
Claim No.	S8M011QA	Excess (\$)	0.00
Assign From	PETER WANG	Assign Date	27/11/2018
2. Vehicle Particulars & Condition			
Make & Model	VOLVO B9TL	c.c	9364
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	YV3S4P923FA173381	Colour	GREEN
Odometer	221858	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	CONTINENTAL	4 mm
L/H Front Tyre	275/70 R22.5	CONTINENTAL	4 mm
R/H Rear Tyre	275/70 R22.5 (D)	CONTINENTAL	4/4 mm
L/H Rear Tyre	275/70 R22.5 (D)	CONTINENTAL	4/4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	02/11/2018	Inspection Date	28/11/2018
Survey held at	LEXBUILD INTERNATIONAL PTE LTD 2 WOODLANDS SECTOR 1, #05-12 (WOODLANDS SPECTRUM 1) SINGAPORE 738068		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBS 5M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	LHS 2ND BODY PANEL WITH FUEL CAP (LHS OF EXIT DOOR) (CONSISTENT)	TO REPAIR SEE LABOUR	605.22	-
1	EXIT DOOR SKIRTING (CONSISTENT)	BENT	452.56	452.56
1	EXIT DOOR RHS PILLAR COVER (CONSISTENT)	CUT	67.85	67.85
1	EXIT DOOR RHS PILLAR STRUCTURE (CONSISTENT)	BENT	75.60	75.60
1	LHS 3RD BODY PANEL WITH FUEL CAP (RHS OF EXIT DOOR) (CONSISTENT)	TO REPAIR SEE LABOUR	663.92	-
1	EXIT DOOR RUBBER (CONSISTENT)	TORN	543.33	543.33
1	"GO-AHEAD SINGAPORE" STICKER (CONSISTENT)	NECESSARY	50.00	50.00
1	LOT ADVERTISEMENT STICKER (CONSISTENT)	NECESSARY	500.00	400.00
			2,958.48	1,589.34
LABOUR				
	SUPPLY SKILL LABOUR TO REPLACE LHS 2ND BODY PANEL WITH FUEL CAP (LHS OF EXIT DOOR). INCLUSIVE OF THE REPAIR OF LHS 3RD BODY PANEL WITH FUEL CAP (RHS OF EXIT DOOR).		880.00	440.00
	SUPPLY SKILL LABOUR & SEALANT TO REPLACE EXIT DOOR SKIRTING.		880.00	440.00
	SUPPLY SKILL LABOUR & SEALANT TO REPLACE EXIT DOOR RHS PILLAR COVER & BRACKET.		880.00	440.00
	SUPPLY SKILL LABOUR TO REPLACE EXIT DOOR RUBBER.		880.00	440.00
	SUPPLY SKILL LABOUR TO REPLACE LHS BODY PANEL WITH FUEL CAP (RHS OF EXIT DOOR)		880.00	440.00
	SUPPLY SKILLED PAINTER & PAINT MATERIAL TO SPRAY PAINT LHS 2ND BODY PANEL WITH FUEL CAP (LHS OF EXIT DOOR), EXIT DOOR SKIRTING, EXIT DOOR RHS PILLAR COVER & BRACKET, LHS 3RD BODY PANEL WITH FUEL CAP (RHS OF EXIT DOOR) - (GREEN COLOR, BLACK COLOUR)		2,640.00	1,320.00
			7,040.00	3,520.00
GRAND TOTAL			9,998.48	5,109.34
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,050.00



Report Ref No. CC4/ASM18021387/K1eb3s2

A stylized handwritten signature in black ink.

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

A handwritten signature in black ink, appearing to be 'Ho Leong Chuan'.

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.