

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933
Tel : 6844-1985 Fax : 6844-5185
Reg : 201838521G

Repair Estimate

Date :20/11/2018

Reference: OPEL
Make: ASTRA

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SJM1424S
CHASSIS NO.: W0LBE6EA4HG180065
ENGINE NO.: B1171497HRXX0501

Name of insured :LIM PECH HWA BERENICE
Date of accident.: 19/11/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BUMPER	\$ 1,994.00
2	15	FRT BUMPER CLIP	\$ 97.50
3	1	FRT BUMPER SIDE RETAINER LH - GUIDE	\$ 136.00
4	1	FRT BUMPER SIDE RETAINER LH - UPP	\$ 106.00
5	1	FRT BUMPER BRACKET LH	\$ 192.00
6	1	LH HEADLAMP	\$ 820.00
7	1	FRT FENDER LH	\$ 682.00
8	1	FRT FENDER SIGNAL LAMP LH	\$ 146.00
9	1	FRT FENDER BRACKET LH	\$ 192.00
10	1	FRT FENDER INNERSHIELD LH	\$ 138.00
11	10	FENDER INNERSHIELD CLIP	\$ 65.00
12	1	FRT RIM LH	\$ 1,200.00
13	1	FRT WHEEL BEARING LH - with Hub	\$ 492.00
14	1	FRT KNUCKLE ARM LH	\$ 414.00
15	1	FRT LOW ARM LH	\$ 867.00
16	1	FRT SHOCK ABSORBER LH	\$ 528.00

Parts Total: \$ 8,069.50
Less 10%: \$ 806.95
Total: \$ 7,262.55

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 600.00
2	Carry out spray painting on affected area; FRT BUMPER, FRT FENDER LH, FRT DOOR LH	\$ 600.00

3	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 120.00	30
4	To remove and replace LHF under carriage parts	\$ 200.00	+
5	To conduct 4 wheel alignment	\$ 160.00	80

910

Labour Total : \$ 1,680.00

Others

Other Description

No.	Price (SGD)

Other Total: 0.00

TOTAL: 8,942.55
GST (7%): 625.98

GRAND TOTAL : 9,568.53

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully


Service Advisor
Kelvin Chew
HP: 8292 5595 Fax: 68445185

Adrian Lj
L/S 26/1/18.

04 Days.

Total: 5458.60

L/S: 4.3K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: