

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

26 NOV 2018

Estimate No. : b1 49246 Page No. : 1 of 5
Date Estimated : 26/11/2018
Prepared By : Kevin Leong Wai Kit

- ESTIMATE REPAIR FOR -
Koh Seok Leng (Xu Xueling)
355 Bukit Timah Road
#04-04 Maidson Residences
Singapore 259724

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLK369L	D793134	26/08/2016	520iA	0

DESCRIPTIONVALUE

Replacing front bumper panel, right front fender, etc to
knock out dents caused by the accident

1700 2,550.00

Spray front bumper and right front fender

1730 1,923.00

To replace right headlight.

408? 481.00

To check electrical wiring systems at the front section
for proper function.

150 177.00

To carry out body cavity preservation.
(Per panel) FRT RH side panel

100 118.00

Sundries.

? 150.00

Total Labour 1: 5,399.00

DESCRIPTIONQTYPRICVALUE

FRT RH FENDER

1

884.90

57 884.90

FRT BUMPER CARRIER

1

701.90

X 701.90

FRT BUMPER BOTTOM MOUNT

1

161.45

? 161.45

FRT BUMPER RH SPACER

1

9.65

new 9.65

RH GRILLE AIR INLET PARTLY CLOSED

1

68.65

? 68.65

FRT SHOCK ABSORBER

1

49.20

? 49.20

FRT BUMPER RH PROTECTIVE RUBBER STR

1

22.85

? 22.85

FRT BUMPER PANEL PRIMED (PDC)

1

1,309.50

del 1,309.50

EMBLEM GROMMET

2

0.80

new 1.60

BMW EMBLEM

1

71.25

new 71.25

RH HEADLAMP SUPPORT

1

131.65

? 131.65

FRT RH WHEEL ARCH COVER

1

128.20

? 128.20

COVER RIGHT

1

5.45

? 5.45

RH COVER BOTTOM

1

71.30

? 71.30

RH HEADLIGHT LED TECHNOLOGY

1

4,203.70

? 4,203.70

Total Parts : 7,821.25

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X**E S T I M A T E**

Estimate No. : **b1 49246**
Date Estimated : **26/11/2018**
Prepared By : **Kevin Leong Wai Kit**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLK369L	D793134	26/08/2016	520iA	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

OD / 3rd Party / Uninsured losses / Direct Settlement

Claim No. 312/18 2245pm

Excess \$ Tanpin

Sign WP

Authorised Yes / No WP

Time 5 days

RESURVEY PARTS PHOTO BY SURVEYOR (Yes / No) Yes PML Yes / No Yes

Surveyor's E-mail tanpin@lkkauto.com

No. of Working Days Recommend 5 days

Labour 1	:	5,399.00
Parts	:	7,821.25
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	925.42
Grand Total	:	14,145.67

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **