

764 K12



BUS REGISTRATION NUMBER	SMB3570L
BUS TYPE (SD/DD)	DD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

	Part No.	Part or Item Description	Quantity	Total Cost
			7% GST	\$0.00
			FINAL TOTAL COST	\$0.00

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR ONLY)		
	LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
	TO REPLACE/REPAIR THE DAMAGED PARTS (INCLUDING SPRAY PAINTING)	\$800.00
		7% GST \$56.00
		FINAL TOTAL COST \$856.00

ESTIMATED ACCIDENT REPAIR COST



SECTION 5: REPAIRS TO BUS ADVERTISEMENT VINYL/PANELS (ADVERTISEMENT COST)

TOTAL ADVERTISEMENT REPAIR COST	-
---------------------------------	---

SECTION 6: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	-
-------------------	---

SECTION 7: NUMBER OF DAYS UNDER ACCIDENT REPAIR (LOSS OF USE COST)

		Date In For Repairs	30/11/2018	
		Date Out From Repairs	1/12/2018	
		Number of Days Under Repair	1	
BUS TYPE (SD / DD)	DD	LOSS OF USE COST		\$400.00

SUMMARY	
SECTION NO.	COST
1	\$0.00
2	\$856.00
3	-
4	-
5	\$400.00
ESTIMATED ACCIDENT REPAIR COST (1+2+3+4+5)	\$1,256.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resur
Hy 90010068
1 day
29/11/18 @ 1420
Resur after repair