


CC 6, CTI 180 21405, Aea3m2

LKK:
IDAC:

INS. CASE OWNER:

Surveyor: lmp DOI: 26/11/18 Date / Time: 26/11/18
Registered in Merimen: _____

Pre-assign / CCU / FTE



Insured Vehicle No. : GBF 872U Claim No. : _____
Name of Insured : KOPB ACCESS MEMORABLE Policy No. : _____
Insured Tel No. : _____ HP: _____ Make / Model : _____
Excess Sec II :SS _____ D.O.A : 23-11-18 Place of Accident : _____
Is driver the owner? (YES / NO) Nature of Accident : _____

If NO, Driver Name / Age : _____ OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
Driver Tel No. : _____ (V/L: YES / NO) Insured Liability : _____ % Final ? Yes / No

MB

GBH 9138L → → → →

	INSRS: WSP: Tel: Liability: RMKS:	<u>Lee Shay.</u>		INSRS: WSP: Tel: Liability: RMKS:		INSRS: WSP: Tel: Liability: RMKS:		INSRS: WSP: Tel: Liability: RMKS:
--	---	----------------------	--	---	--	---	--	---

Date / Time	STAGE	DATE / PIC
<u>5/12</u>	Non-Reporting ltr (1st):	
<u>5/12</u>	Non-Reporting ltr (2nd):	
<u>5/12</u>	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	<u>ASHER 26.12.18</u>
<u>20-12-18</u>	After call ltr to OI:	
	Documentation Check List:	Handler Typist
<u>15/2/19</u>	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
<u>8/10/19</u>	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice	<input type="checkbox"/>
	LTA / GIA :	<input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____ Confirm with: _____ Confirm by: _____

FINALIZATION Repair Cost: \$S _____ (_____ days) Reduction: _____ % Email Call

FINAL SETTLEMENT Date/Time: 4/10/19 Confirm with Ms Lee Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 01 If NO or B 28, Ass. Lia : _____
Repair Cost: (w/45) \$S 7574.58 OND REAR BENDED TP.
Loss of Rental (LOR): \$S 700.00 (7 days) x \$100
Loss of Use (LOU): \$S - (\$ x days)
Loss of Income (LOI): \$S - (\$ x days)
LOR only LOU only LOR + LOU LOR + LOI [Tick only one]
GIA/LTA Search \$S -
Medical: \$S -
Disbursement: \$S - (e.g. Tow/ Independent)
Legal Cost \$S -
Total: \$S 8274.58 Global Sum \$S: _____

9/10/19

1) Claim status: Normal/Reject/Private Settle
2) Report Format: TP
3) Survey fee: \$400

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: \$S 8274.58 Name 1: Lee Shay Auto Pte Ltd
Payee 2: (Strike if N.A.) \$S _____ Name 2: _____
Payee 3: (Strike if N.A.) \$S _____ Name 3: _____

ASS. REC. BY:

REF:

ASSIGNMENT

Adrian

Front: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: I.B.L % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBH 9138L Yr Regn: 2018 / Oct

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Nissan NV200 c.c. 1461 cc

Colour Grey A/C: Insured / Std / Nil / NA

Sp. Reading 2274 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: VSKY BAM 20201716

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 175/70R14

R: 175/70R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front	Rear
R/Bal. <u>06</u> mm	R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm	L/Bal. <u>06</u> mm
D.O.A. _____	D.O.I. <u>26/11/18</u>

Survey held at Lee Shee

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>IP Check</u>
	<u>P/P - \$7079.05 (Red \$2390.03 / 25%)</u>

Date/Time, File Pass to?	Date/Time, File Return to?	Part Prices Check:	Survey Fee:	Date:					
1) _____	2) _____	IN _____ OUT _____	Basic & Add. _____	<table border="1"> <tr><td>_____</td></tr> <tr><td>_____</td></tr> <tr><td>_____</td></tr> <tr><td>_____</td></tr> <tr><td>_____</td></tr> </table>	_____	_____	_____	_____	_____

3) _____	4) _____		* S + RS, SI _____						
5) _____	6) _____		Photos _____						
Prel. Report: _____			Others _____						
Final Report: _____			TOTAL _____						

LEE SHENG AUTO PTE LTD

1, Kaki Bukit Ave 6, Autobay@KakiBukit
 #01-60/58, Singapore 417883
 Tel No. : 67477333 Fax No. : 67457138
 E-Mail : leesheng@singnet.com.sg
 Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. FANG FANG DELIGHT PTE LTD
 BLK 295B COMPASSVALE CRES #04-223
 SINGAPORE 542295

Attention : Motor Claim Department
 Contact : 97815374

TP Chian.
Jiale.

Estimate : ES000789

Date : 24/11/2018
 Vehicle Num. : GBH9138L
 Make/Model : NISSAN NV200 1.5L MT ABS-2018
 Chassis/Eng# : VSKYBAM20Z0171716/K9KE628D6192
 Accident Date : 23/11/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
NETT ITEMS :				
1.	1	NO PLATE GARNISH <i>new</i>		55.00 ✓
2.	1	NISSAN EMBLEM		87.00 ✓
3.	1	70 KM/H STICKER <i>new</i>		20.00 ✓
4.	1	NV 200 EMBLEM		97.00 ✓
5.	1	REAR DOOR RH <i>Disturbed</i>		1,165.20 ✓
6.	1	REAR DOOR LH		1,165.20 ✓
7.	1	REAR DOOR CHECKER LH <i>new</i>		65.00 ✓
8.	1	REAR DOOR CHECKER RH <i>new</i>		65.00 ✓
9.	1	REAR DOOR LOCK (INNER) <i>new</i>		187.70 ✓
10.	1	REAR DOOR LATCH RH <i>new</i>		48.00 ✓
11.	1	REAR DOOR LATCH RH <i>new</i>		48.00 ✓
12.	2	REAR DOOR ARRESTOR <i>new</i>		48.00 ✓
13.	1	REAR END PANEL <i>Disturbed</i>	195.20	390.40 ✓
14.	1	REAR DOOR HINGE LOWER LH <i>new</i>		5522 844.90 ✓
15.	1	REAR DOOR HINGE LOWER RH <i>new</i>		86.80 ✓
16.	1	REAR BUMPER <i>Disturbed</i>		86.80 ✓
17.	1	REAR BUMPER REINFORCEMENT <i>Best new</i>		581.20 ✓
18.	1	REAR BUMPER REFLECTOR <i>new</i>		195.20 ✓
19.	1	REAR BUMPER RETAINER LH <i>new</i>		58.00 ✓
20.	1	REAR BUMPER RETAINER RH <i>new</i>		48.00 ✓
21.	1	REAR EXHAUST ASSY <i>Best</i>		48.00 ✓
				545.00 ✓
		Nett Total S\$:		5,884.40
		30.00% Discount S\$:		1,765.32
		<i>10%</i>		4,119.08

4554.50
Less 10% : 4099.05

CONTINUE / ...

LEE SHENG AUTO PTE LTD

1, Kaki Bukit Ave 6, Autobay@KakiBukit
 #01-60/58, Singapore 417883
 Tel No. : 67477333 Fax No. : 67457138
 E-Mail : leesheng@singnet.com.sg
 Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. FANG FANG DELIGHT PTE LTD
 BLK 295B COMPASSVALE CRES #04-223
 SINGAPORE 542295

Attention : Motor Claim Department
 Contact : 97815374

Estimate : ES000789

Date : 24/11/2018
 Vehicle Num. : GBH9138L
 Make/Model : NISSAN NV200 1.5L MT ABS-2018
 Chassis/Eng# : VSKYBAM20Z0171716/K9KE628D6192
 Accident Date : 23/11/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	SPECIAL NETT ITEMS :		
2.	1	NO PLATE (METAL) <i>fine</i>	180	25.00 +
3.	1	NO PLATE HOLDER		25.00 ✓
		COMPANY ADVERTISE STICKER <i>NEC</i>		200.00 / 80
		Special Nett Total S\$:		250.00
		LABOUR :		
		TO REMOVE & REFIX BUMPER / REAR END PANEL , KNOCKING CUTTING , JACKING		1,800.00 ¹⁴⁰⁰ 1400
		TO SPRAY PAINTING ON REAR END PANEL / DOOR / ETC		1,500.00 ⁸⁰⁰ 800
		TO REMOVE & REFIX ALUMINIUM CHECKER PLATE FOR REPAIR	2800	1,800.00 ⁶⁰⁰ 600
		SUPPLY CHECKER PLATE AND RR DOOR ALUMINIUM PLATE		
		Labour Total S\$:		5,100.00

Total S\$: 10645.96
 9,469.08
 =====

LEE SHENG AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian Lj
L/S BP/P??
06 days.
toluk: 7079 05
(P/P).

Mei Kwan (LKKAuto)

From: Catherine Thia <catherine.thia@sg.cntaiping.com>
Sent: Wednesday, 28 November, 2018 2:27 PM
To: Mei Kwan (LKKAuto)
Cc: Lucas Lee; Asher Sng (LKKAuto); Admin A; CS A Team
Subject: RE: Direct Settlement - Accident Involving GBF872U (OI : CTI - SNM18D05525C01) and GBH9138L (TP : LKK REF - CC6/CTI18021405/Aea3) on 23/11/2018
Attachments: GBE872U report.pdf
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear Mei Kwan

Please see attached GIA report

Thanks

Catherine Thia
Senior Executive
Motor Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6193
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Tuesday, 27 November, 2018 7:56 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Catherine Thia <catherine.thia@sg.cntaiping.com>; Lucas Lee <lucas.lee@sg.cntaiping.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Thursday, 20 December 2018 2:39 PM
To: 'Ms Lee (Lee Sheng Auto)'
Subject: Accident Involving GBH 9138L & GBF 872U on 23/11/2018

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Your Ref: GBH 9138L
Our Ref: CC6/CTI18021405/Aea3

Dear Sir/Madam,

Accident Involving GBH 9138L & GBF 872U on 23/11/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18021405/Ada3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 10-10-2019	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBF 872U	Veh. Inspected	GBH 9138L
Policy No.	DMCVSN3043351801	Coverage (\$)	0.00
Claim No.	SNM18D05525C02/2	Excess (\$)	0.00
Assign From		Assign Date	26/11/2018
2. Vehicle Particulars & Condition			
Make & Model	NISSAN NV200	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	VSKYBAM20Z0171716	Colour	GREY
Odometer	2274	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/70 R14	GOODYEAR	6 mm
L/H Front Tyre	175/70 R14	GOODYEAR	6 mm
R/H Rear Tyre	175/70 R14	GOODYEAR	6 mm
L/H Rear Tyre	175/70 R14	GOODYEAR	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/11/2018	Inspection Date	26/11/2018
Survey held at	LEE SHENG AUTO PTE LTD 1 KAKI BUKIT AVE 6 #01-60 SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 9138L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	NO PLATE GARNISH (N)	NOT NECESSARY	55.00	-
1	NISSAN EMBLEM (N)	NECESSARY	87.00	87.00
1	70KM/H STICKER (N)	NECESSARY	20.00	20.00
1	NV 200 EMBLEM (N)	NECESSARY	97.00	97.00
1	REAR DOOR RH (N)	DISTORTED	1,165.20	1,165.20
1	REAR DOOR LH (N)	DISTORTED	1,165.20	1,165.20
1	REAR DOOR CHECKER LH (N)	NOT NECESSARY	65.00	-
1	REAR DOOR CHECKER RH (N)	NOT NECESSARY	65.00	-
1	REAR DOOR LOCK (INNER)(N)	DAMAGED	187.70	187.70
1	REAR DOOR LATCH RH (N)	NOT NECESSARY	48.00	-
1	REAR DOOR LATCH RH (N)	NOT NECESSARY	48.00	-
2	REAR DOOR ARRESTOR @\$195.20 (N)	NOT NECESSARY	390.40	-
1	REAR END PANEL (N)	DISTORTED	841.90	552.20
1	REAR DOOR HINGE LOWER LH (N)	NOT NECESSARY	86.80	-
1	REAR DOOR HINGE LOWER RH (N)	NOT NECESSARY	86.80	-
1	REAR BUMPER (N)	DISTORTED	581.20	581.20
1	REAR BUMPER REINFORCEMENT (N)	NOT NECESSARY	195.20	-
1	REAR BUMPER REFLECTOR (N)	CRACKED	58.00	58.00
1	REAR BUMPER RETAINER LH (N)	NECESSARY	48.00	48.00
1	REAR BUMPER RETAINER RH (N)	NECESSARY	48.00	48.00
1	REAR EXHAUST ASSY (N)	BENT	545.00	545.00
	LESS 10% DISCOUNT		-588.44	-455.45
			5,295.96	4,099.05
SPECIAL NETT ITEMS				
1	NO PLATE (METAL)(SN)	NOT NECESSARY	25.00	-
1	NO PLATE HOLDER (SN)	NOT NECESSARY	25.00	-
1	COMPANY ADVERTISE STICKER (SN)	NECESSARY	200.00	180.00
			250.00	180.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE & REFIX BUMPER/REAR END PANEL,KNOCKING CUTTING,JACKING.		1,800.00	1,400.00
	TO SPRAY PAINTING ON REAR END PANEL/DOOR/ETC.		1,500.00	800.00
	TO REMOVE & REFIX ALUMINIUM CHECKER PLATE FOR REPAIR.		1,800.00	600.00
	SUPPLY CHECKER PLATE AND RR DOOR ALUMINIUM PLATE.			
			5,100.00	2,800.00
	GRAND TOTAL		10,645.96	7,079.05
	RECOMMENDED COST OF REPAIRS			7,079.05

Report Ref No. CC6/CT118021405/Ada3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.