

GRE
JU
L 8m

DATE 26/11/2018 9:20

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Fender (RH) <i>x repair</i>			\$ 1,935.90
	Rear Fender Inner Lining (RH) <i>x</i>			\$ 74.10
	Rear Windscreen Moulding <i>x</i>			\$ 60.00
	Rear Wheel Hup-Cap (RH) <i>—</i>			\$ 145.00
	<i>Rear Door (RH) x repair</i>			
	<i>Rear Bumper x repair</i>			
	SUB TOTAL			\$ 2,215.00
	LESS 20% <i>25%</i>			\$ 443.00
	DISCOUNTED TOTAL			\$ 1,772.00
	Rear Bumper Rubber Mat <i>x</i>			\$ 50.00
	Rear Fender Comfort Sticker (RH) <i>x</i>			\$ 30.00
	Rear Windscreen Sealant <i>x</i>			\$ 46.00
	Rear Door Tel No. Sticker (RH) <i>—</i>			\$ 10.00
				\$ 136.00
	Labour Charge			
	Panel Beating-Repair Rear RH Door			\$ 850.00 <i>400</i>
	Spray Painting Charge			\$ 750.00 <i>600</i>
	Wiring Charge			\$ 50.00 <i>x</i>
	Tuff Kote			\$ 50.00 <i>x</i>
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 <i>50</i>
	Remove/Refix Rear Windscreen Glass			\$ 120.00 <i>x</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>x</i>
	Rear Wheel Alignment			\$ 120.00 <i>x</i>
	TOTAL LABOUR			\$ 2,210.00
	ESTIMATE TOTAL			\$ 4,118.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: *26/11/18*

Ka Li 11/11/18

26/11/18

3 Reps.

L/S Alta Repair pth

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.