

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3469X

DATE 24/11/2018 10:15

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper XXXX ✓			\$ 553.00
	Rear Bumper Reinforcement ?			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs X			\$ 22.00
	Rear Bumper Bracket X		\$ 35.60	\$ 71.20
	Rear Bumper Sponge ?			\$ 103.50
	Rear Bumper Under Cover X			\$ 228.00
	Rear Bumper Reflector Lamp (RH) ✓			\$ 30.60
	SUB TOTAL			\$ 1,597.30
	LESS 20%			\$ 319.46
	DISCOUNTED TOTAL			\$ 1,277.84
	Rear Bumper Rubber Mat X			\$ 50.00 Nett
	Rear Bumper Advertisement Logo ✓			\$ 50.00 Nett
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00 Nett
	Rear Bumper Reverse Sensor ✓			\$ 135.70 Nett
				\$ 435.70
	Labour Charge			
	Panel Beating			\$ 350.00 200
	Spray Painting Charge			\$ 250.00 200
	Wiring Charge			\$ 30.00 X
	Remove/Refix Reverse Sensor			\$ 80.00 8X
	TOTAL LABOUR			\$ 710.00
	ESTIMATE TOTAL			\$ 2,423.54
1ca li 1/11/18 26/11/18 10254 2 hrs PIP After Repair photo				
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Fz

pp