

REPAIR ESTIMATE*

VEHICLE NO : SHC 8951S

DATE 24/11/2018 9:15

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Fender (RH) ✓			\$ 566.30
	Front Fender Shield (RH) ✕			\$ 175.90
	Frt Windscreen Pillar Upper Cover ✕			\$ 225.00
	SUB TOTAL			\$ 967.20
	LESS 20%			\$ 193.44
	DISCOUNTED TOTAL			\$ 773.76
	Front Fender Advertisement Logo (RH) ✓			\$ 100.00
				\$ 100.00
	Labour Charge			200
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 250.00
				200
	TOTAL LABOUR			\$ 600.00
	ESTIMATE TOTAL			\$ 1,473.76
	Calvin 10/11/18 26/11/18 1005h 2 by, PIP Before Post photo			
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

F2