

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5831U**AAD1811-206***Not Authorised*
Resurvey B4 paint

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 5831U

JTDKB3FU603075072

RENAULT

LATITUDE

23.11.2018

EQ

PART		LIST	
1	1 REAR BUMPER	\$	<i>Per</i> 458.60 ✓
2	1 REAR BUMPER RE-INFORCEMENT	\$	318.80 7
3	1 REAR BUMPER TOWING COVER	\$	<i>Per</i> 14.70 ✓
4	1 REAR BUMPER UNDER COVER (BLACK)	\$	<i>SL</i> 552.60 X
5	1 REAR BUMPER SIDE RETAINER LH	\$	<i>SL</i> 112.70 X
6	1 REAR BUMPER SIDE RETAINER RH	\$	<i>SL</i> 112.70 ✓
7	1 REAR TAILGATE	\$	<i>R</i> 1,547.27
8	1 REAR TAILGATE OUTER GARNISH	\$	<i>SL</i> 905.10
9	1 COVER, REAR COMBINATION LAMP, RH	\$	<i>SL</i> 54.70
10	1 COVER, REAR COMBINATION LAMP, RH	\$	<i>SL</i> 54.70
11	1 GARNISH, BACK DOOR SIDE, LH	\$	<i>SL</i> 93.60
12	1 GARNISH, BACK DOOR SIDE, RH	\$	<i>SL</i> 93.60 X
13	1 BOARD ASSY, BACK DOOR TRIM	\$	<i>SL</i> 254.40
14	1 PANEL ASSY, BACK DOOR TRIM, UPPER	\$	<i>SL</i> 51.20
15	1 REAR TAILGATE WEATHERSTRIP	\$	<i>SL</i> 365.20
16	1 REAR END PANEL	\$	<i>R</i> 602.10
17	1 TAILLAMP LOWER RH	\$	<i>SL</i> 548.40
18	1 TAILLAMP UPPER RH	\$	<i>SL</i> 557.90
19	1 REAR BUMPER SIDE RH	\$	<i>mgcM</i> 232.00 ✓
20	1 REAR BUMPER SIDE LH	\$	<i>SL</i> 232.00 X
20	1 REAR FENDER RH	\$	<i>R</i> 817.50 X
		\$	7,979.77
25%		\$	1,994.94
		\$	5,984.83

Special Nett

1 1SET PARKING AID

\$

SL 700.00 X

Trans-cab Auto Services Pte Ltd**AAD1811-206**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5831U

2	1SET REAR BUMPER CLIP	\$	<i>nn</i> 22.00	✓
3	2 REAR WINDSCREEN SELANT	\$	<i>nn</i> 80.00	} X
4	1 WINDSCREEN MOULDING	\$	<i>nn</i> 100.00	
5	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00	
6	1 REAR TAILGATE TOYOTA LOGO	\$	<i>nn</i> 47.00	
7	1 REAR TAILGATE WORDING 'PRIUS'	\$	<i>nn</i> 52.90	
8	1 REAR TAILGATE WORDING 'HYBRID'	\$	<i>nn</i> 53.50	
9	1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>nn</i> 80.00	}
10	1 REAR TAILGATE STICKER '6555-3333'	\$	<i>nn</i> 80.00	
11	1 REAR BUMPER PROTECTOR	\$	<i>nn</i> 100.00	

TOTAL \$ 1,315.40**TOTAL PARTS \$ 7,300.23****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	<i>2201</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	<i>2001</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	<i>501</i>
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	X
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1811-206**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5831U

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>

TOTAL \$ 7,580.00**Over All Total \$ 20,865.06****(PART-BY-PART) Repair Days****~~10 DAYS~~***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: