

ASS. REC. BY:

REF: CS/FCI(8021420/RIVD3

Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

From (Person):

CWS

Sifhem

of

FCI

Date/Time: 11:40am @ 27/11/18

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKK 3288D

Insured:

SHA 9342D

at Workshop m/s

cycle & carriage Ind.

Tel:

91865112

of

188 pandan loop

Policy No:

Claim No:

D18008391MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

24/11/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time: 1:30pm @ 27/11/18

Person Contacted:

Alan

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKK 3288D - CS/AXA/6020318/Tlvbmj

Dof: 23/10/16

20/11/18

VNI

1/12/18

vehicle not in yet

10/12/18

Email preli revised to FCI

2019/04/19 *Rasul*

REF:

3473F

Week 19. 2028/200

ASSIGNMENT

From: Date: Vch No: SKK 3288D Yr Regn: 2008 NSW
 Estimated Cost: Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV Truck / Trailer or
 To Inspect Vehicle No: SKK 3288D Make: Mercedes Benz SLK 200 Kompe 1796
 at Workshop n/s: CYCLE & CARAVAGE Colour: WHITE A/C: Insured / Std / NI / NA
 of 188, Pinner Loop Sp. Reading: - T/Radio: Insured / Std / NI / NA
 Insured: FCI Eng/No:
 Policy No: CNo: WDB1714452F196054
 Claims No: Gen. Cond: Good / ☒ Fair / Poor / Burnt
 Sum Insured: Excess: Steering: ☒ In order / Jammed / Leaked / Burnt or
 (Client's Record) Brake: ☒ In order / Jammed / Leaked / Burnt or
 Make of Veh: Modi: Nil / ☒ S/Rim / STD A/Rim or
 (Policy Condition) Tyre Size: F: 225/40R18
 Remark: The veh had commenced its R: 1.
 repair at the time of inspection. BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or CONTINENTAL
 Bal. or Market Value: 74K Front Rear
 IDAC Accident Report: Consistent? : Yes or No R/Bal. 6 mm R/Bal. 6 mm
 GIA / PR Seen: Consistent? : Yes or No L/Bal. 6 mm L/Bal. 6 mm
 Est. Repairs: days Res.: Yes or No D.O.A. 24/11/18 D.O.L. 07/12/18
 Lum Sum: % 3 Val: Yes or No Survey held at CEC (PL)
 CA / REV / REP. / 24 HRS wp Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 Date: Person Contacted: 6/8 FR
 Vehicle: IN / OUT The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Date / Time Action / Instruction

25/4/19 @ 446pm Rasul confirmed \$ 6966.35 with Alan (Red 1655.03, 1970)

MV: \$ 74K (EST) LTA: \$ 32,005 NV: \$ 41,995

[Signature]
25/4/2019

RECEIVED 26 APR 2019

Date/Time, File Pass 60? ☐ : Preli, Report
☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: -

Survey Fee:

Transportation

\$ + RS \$

Photos

Chairs

TOTAL

160
90
21
231

Date/Time, File Return to?

25/4 - typist

Report Format: cws
 Lump Sum / I.B.I. (\$) 6966.35

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18008391MFSH

Our Ref: CS/FCI18021420/R1vd3

Date :10/12/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKK 3288D


We thank you for your instruction on 27/11/2018

Please be informed that we had conducted the inspection of the above mentioned
7/12/2018 at the premises of M/s CYCLE & CARRIAGE IND PTE LTD
and have the following to report:-

Workshop Estimate Amount	: S\$8,576.75
Revised Estimate Amount	: S\$7,634.83
"Check" Items Amount	: S\$17.13
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
o/s front portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	26-11-2018	Our Ref No. D18008391MFSH
Accident Date	24-11-2018	Claim Type. Third Party
Insured Vehicle	SHA9342D	Third Party Vehicle. SKK3288D
Survey Location	PANDAN LOOP SERVICE CENTER 188 PANDAN LOOP	
Contact Person.	ALAN QUEK	
Contact No.	67714377/ 91865112	Fax No. 68721272
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE INDUSTRIES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 10 December 2018 12:44 PM
To: 'CWS Motor Claims'
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008391MFSH/1, SKK 3288D
Attachments: SKK 3288D PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKK 3288D
Date of survey: 7/12/2018
Number of days : 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 27 November 2018 1:33 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008391MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 27 November 2018 11:49 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008391MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3473F
Vehicle Details	
Vehicle No.:	SKK3288D
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Dec 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	SLK 200 KOMPRESSOR
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	27195431061943
Chassis No.:	WDB1714452F196054
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$50,285.00
Original Registration Date:	28 Nov 2008
First Registration Date:	28 Nov 2008
Transfer Count:	4
Actual ARF Paid:	\$50,285.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Nov 2028
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$32,121.00
COE Rebate Amount:	\$32,005.00
Total Rebate Amount:	\$32,005.00

The information contained herein is correct as at 10 Dec 2018

OK

74,000
32,005

41,995



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111-X

ESTIMATE FOR SKK3288D

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information
WIP No 28724
Reg No/Reg Date SKK3288D / 28/11/2008
Date In/Mileage / 0
Chassis No WDB1714452F196054
Engine No 27195431061943
Make/Model MB/SLK 200 K ROADSTER (NEW G
Colour/Trim 021 197 Obsidian Bl/ 048 801 Black

Account No	Terms	Date/Time Printed	CSE	Operator				
WF001862	Credit	26/11/2018/ 12:16	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE :GA262564 // 24-11-2018 DRIVE IN:26-11-2018 // TP CAR NO:SHA9342D (FIRST CAPITAL INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :								
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT							0.10	380.00
S BPNSUB SUPPLY & TRANSFER 1PC FRONT RIGHT RIM PURCHASE ORDER NO:								60.00
A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT								540.00
A BPILAB REMOVE & REPLACE FRONT BUMPER, FRONT RIGHT FENDER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.								2400.00
A BPIRES RESPRAY FRONT BUMPER & FRONT RIGHT FENDER								1500.00
M RH/F FENDER					1.00	836.76	00.00	836.76
M RH/F INTERMEDIATE LAYER					1.00	17.13	00.00	17.13
M RH/F FENDER EMBLEM					1.00	144.79	00.00	144.79
M FRT BUMPER					1.00	1396.00	00.00	1396.00
M RH/F BUMPER BRACKET					1.00	61.92	00.00	61.92
M RH/F DISC WHEEL					1.00	1240.15	00.00	1240.15

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 8,576.75
7% GST on 8576.75 600.37
Total Payable 9,177.12

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18021420/R1vd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 30-04-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 9342D	Veh. Inspected	SKK 3288D
Policy No.		Coverage (\$)	0.00
Claim No.	D18008391MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	27/11/2018
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ SLK 200 KOMPRESSOR	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	WDB1714452F196054	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/40 R18	CONTINENTAL	6 mm
L/H Front Tyre	225/40 R18	CONTINENTAL	6 mm
R/H Rear Tyre	225/40 R18	CONTINENTAL	6 mm
L/H Rear Tyre	225/40 R18	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	24/11/2018	Inspection Date	07/12/2018
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKK 3288D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RH/F FENDER (SN)	BENT	853.48	853.48
1	RH/F INTERMEDIATE LAYER (SN)	NOT NECESSARY	17.13	-
1	RH/F FENDER EMBLEM (SN)	NOT NECESSARY	144.79	-
1	FRT BUMPER (SN)	SCRATCHED	1,423.91	1,423.91
1	RH/F BUMPER BRACKET (SN)	NOT NECESSARY	61.92	-
1	RH/F DISC WHEEL (SN)	SCRATCHED	1,240.15	648.96
1	FRONT RIGHT RIM (SN)	NOT NECESSARY	60.00	-
			3,801.38	2,926.35
<u>LABOUR</u>				
	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.		380.00	380.00
	INSPECT & CONDUCT WHEEL ALIGNMENT.		540.00	540.00
	REMOVE & REPLACE FRONT BUMPER, FRONT RIGHT FENDER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.		2,400.00	1,920.00
	RESPRAY FRONT BUMPER & FRONT RIGHT FENDER.		1,500.00	1,200.00
			4,820.00	4,040.00
GRAND TOTAL			8,621.38	6,966.35
RECOMMENDED COST OF REPAIRS				6,966.35

Report Ref No. CS/FCI18021420/R1vd3n2

MARKET VALUE: \$74,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$32,005.00=NETT VALUE: \$41,995.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.