	22/03/2002 -		BEE: 00	/ K	21 12 21		
4	ASS. REC. BY:		REF: CS CT	118021421/ 11	V d3/1/8 pecial	Instruction:	
	Surveyor:			GNMENT (Office			
	From (Person)	Irone Tay	of	CTI	Dat	e/Time: 27/11/186	12.32pn
	Estimated Cost			Bill to:			
	OD TP WS	TP RES / OD B	ES/EVA/INV	MYTCS			
	To Inspect Vel	nicle No:	S1F	74200	Insured:	SIP 956	P
	at Workshop n	Vs	Esteam	Poxtormina	Tel:	8790 MGG	
	of	B K 503	RAMK Ind.	park 2 #01-	251/250	7	
	Policy No:						
	Sum Insured:_			Excess:			
	Make of Veh: (Client's Record)				D.C	A 13/11/18	
	CA / REV /	REP. / REV 24	HRS		H	.O.D. Endorsement:	
	Date/Time:	·3/fc@mq+6.	Person Con	tacted: Coww	en Vehic	le IN/OU	*
	Date/Time	Action/Instruction		timate			
		815-7420	1C-X				
		SIP956P	-7 .				
	28/11/18.	VMI yet					
		. ,				-	-
	7//	\$ 2001.	39 Cah	w hy enoil	(Red	0730.65 5790	•
			0.000	-		- 112	,

REF:

MI

# Nivitha (LKK Auto)

From:

Irene Tay <irene.tay@sg.cntaiping.com>

Sent:

Tuesday, 27 November 2018 12:32 PM

To:

Carmen Lim

Cc:

assignments; Admin A; Lucas Lee

Subject:

CTP REF NO. SJP956P E REF: SLF7429C - ACCIDENT INVOLVING SJP956P AND

SLF7429C ON 13 NOVEMBER 2018

Dear Sir.

We refer to the above matter and our telephone conversation a moment ago.

As spoken, you have requested for LKK to survey your vehicle.

# Aside to LKK: Please liaise with Ms Carmen from Esteem @ 8799-0066 for the PRS.

Thank you.

### Irene Tay

Executive

Claims Department (Motor Division)

### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6192

Fax (65) 62247478/62247175

Email: claimsdept@sg.cntaiping.com

www.sg.cntaiping.com



Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insura

### > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Company	
Owner ID: <b>Vehicle Details</b>	7200G	
Vehicle No.:	SLF7429C	
Vehicle to be Exported:	No	
Intended Deregistration Date:	09 Jan 2019	
Vehicle Make:	TOYOTA	
Vehicle Model:	PRIUS HYBRID 1.8 CVT	
Primary Colour:	White	
Manufacturing Year:	2016	
Engine No.:	2ZRR933053	
Chassis No.:	JTDKB3FU703532133	
Maximum Power Output:	90.0 kW (120 bhp)	
Open Market Value:	\$31,008.00	
Original Registration Date:	08 Sep 2016	
First Registration Date:	08 Sep 2016	
Transfer Count:	0	
Actual ARF Paid: Intended PARF Rebate Details	\$5,412.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	07 Sep 2026	
PARF Rebate Amount: Intended COE Rebate Details	\$4,059.00	
COE Expiry Date:	07 Sep 2026	
COE Category:	E - Open Category	
COE Period(Years):	10	
QP Paid:	\$58,201.00	
COE Rebate Amount:	\$44,364.00	
Total Rebate Amount:	\$48,423.00	

The information contained herein is correct as at 09 Jan 2019

ОК

# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

			-				-		_	_	
	^	$\sim$				S				_	<b>1 - 4</b>
а				-	чı		ΙА	1 -	111	-	ч.

14/11/2018 13:09 Date Of Report 13/11/2018 17:15 Date Of Accident

ALONG CHANGI RD TOWADS GEYLANG **Exact Location Of Accident** 

SINGAPORE Country/State of Loss

#### **DETAILS OF OWN VEHICLE**

SLF7429C Vehicle Registration Number

Insured/Policyholder

GRAB RENTALS PTE LTD Name Of Registered Owner

201617200G Co Reg No NOEMAIL Email Address

Mobile Phone No

OFFICE-66550005 Alternative Phone No

Vehicle Particulars

TOYOTA Manufacturer **PRIUS** Model

Exact Purpose for which vehicle was being used at

time of accident

HIRE & REWARD

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE HIRE

Insurance Company

MSIG INSURANCE (SINGAPORE) PTE. LTD. Name of Insurance Company

COMPREHENSIVE Type Of Coverage

YES Fleet Policy

A29069766MKF Policy Number

Cover Note Number

Driver

FAIZAL BIN ISMAIL Name of Driver

S1773062B NRIC No 25/07/1966 Date Of Birth OUTDOOR Occupation 21/05/1992 Date Of Driving Pass

26 YEARS AND 5 MONTHS Driving Experience

MALE Gender

(LOCAL) +65-94882370 Mobile Number

Fax Number

Contact Number

FAIZALISMAIL949@GMAIL.COM **EMail Address** 

Address

NIL

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

4

Passenger 1

NAME:

: P1

: MALE

Passenger 2

NAME:

: P2

GENDER:

GENDER:

: FEMALE

Passenger 3

NAME:

: P3

GENDER:

: FEMALE

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

#### Circumstances of Accident

ON THE DATE AND TIME MENTIONED,I WAS DRIVING ALONG THE SAID MENTIONED ROAD. VEHICLE B WAS SEEN PARKED IN A PARKING LOT ON THE RIGHT SIDE OF THE ROAD. AS I CAME ALONG SIDE VEHICLE B, SUDDENLY VEHICLE B MOVED OUT OF THE LOT, WITHOUT SIGNALLING, AND HIT AGAINST THE RIGHT PORTION OF MY VEHICLE. NOBODY WAS INJURED. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

RETRIEVING

Was there any audio recorded?

# **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

SJP956P

Vehicle Make/Model/Colour

MITSUBISHI LANCER DARK GRAY

**Details Of Properties** 


Vehicle Category

PRIVATE CAR

Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

. ", .

KOHAMMED SHAFIEE BIN AAMUNI S8437641H 84987605



# Common Statement Pg. 1

ACCIDENT	STATEMENT	(2000 characters)
----------	-----------	-------------------

Production of Management of the Contract of th
ON THE DATE AND TIME MENTIONED, I WAS DRIVING ALONG THE SAID MENTIONED ROAD. VEHICLE B WAS SEEN PARKED IN A PARKING LOT ON THE RIGHT SIDE OF THE ROAD. AS I CAME ALONG SIDE VEHICLE B, SUDDENLY VEHICLE B MOVED OUT OF THE LOT, WITHOUT SIGNALLING, AND HIT AGAINST THE RIGHT PORTION OF MY VEHICLE. NOBODY WAS INJURED.
STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.
Taxi Voucher No.:
DECLARATION
VWe declare that the above particulars & information provided above are true in every aspect
wive decare that the above particulars a imprimation provided above are the instance.
VERIFIED BY AJAX MARS REPORTING OFFICER-HASHIM BIN KAMARI
VERIFIED BY AJAX MARS REPORTING OFFICER-HASHIM BIN KAMARI  MARS Officer
VERIFIED BY AJAX MARS REPORTING OFFICER - HASHIM BIN KAMARI



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

	Repair Estimates	SI	LF 7429 C	Not Nothering Runny Bépany
Parts	(a) Cost / List Price Items	\$	3,616.05	Received
	Plus/Less25%	\$	904.01	Jahny Bepany
	Total of Cost / List	\$	2,712.04	
	(b) Nett Price Items			LKK Auto Consultants hence notify
	Less			• To resurvey pefor:
	Total of Nett Item			Parts prices are subject to confirmation     Third party surveys a second confirmation.
	(c) Special Nett Items			Third party survey son a "Without Prejudice" basis No illegal modificatin(s) allowed Supplementary (feet s) must be resurveyed and is subject to final approval from Jesses and
Total	Parts Cost	\$	2,712.04	is subject to final approval from insurance Company  Acknowledged by Repairer
Labo	ur	\$	2,020.00	Signature:
Total		\$	4,732.04	
	bove total will be subjected to	7% G.S.T.		<i>К.</i>
Na	ame of Surveyor	# !*		Kenneth
Co	ompany	i.		
Su	rvey conducted on	74 25		/2/18at
Re	emarks By Surveyor			
(a)	The repair of this vehicle is	authorized /		
14			04	day(s)
(b)	Recommended Days of Re	pair :		day(s)
(c)		pair : :	Required / Not Require	uay(s)
	Resurvey	pair : : :\$		uay(s)



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.eşteemperf.com.sg

S	pai	re	Pa	irts

Vehicle No.	:
Make & Model	:
Chassis No	:

**SLF 7429 C** 

TOYOTA PRIUS

JTDKB3FU703532133

Submit By

Year Manufacture : Engine No. :

Carmen Lim

2016

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor	
1	Front bumper	R	1	\$450.80		×
2	Front bumper clip	Na	10	\$40.00		~
3	Front bumper side retainer RH	Sin	1	\$107.20		X
4	Front bumper emblem	Na	1	\$87.10		X
5	RH front fender	Ry	1	\$868.70		
6	RH front fender undershield	Sn	1	\$185.64		×
7	RH front fender undershield clip	ın	10	\$25.00		X
8	RHF fender wording "HYBRID"	M	1	\$44.17		
9	RH front door	R	1	\$1,121.75		X
10	RH front door hinge top	n	1	\$78.30		X
11	RH front door hinge bottom	И	1	\$78.30		×
12	RH front door weatherstip	SL	1	\$211.69		×
13	RHF door glass outer moulding	Su	1	\$121.75		X
14	RH front hub cab	nd16	y 1	\$195.65		
15						
16						
17						
18						
19						
20						
21						
22						
23						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

will be charged accordingly under supplementary.



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour	

Vehicle No.	: _	SLF 7429 C	Submit By :	Carmen Lim
Make & Model	: _	TOYOTA PRIUS	Year of Manufacture:	2016

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (FRONT BUMPER,RHF FENDER,RHF DOOR)	\$800.00	4001
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (FRONT BUMPER,RHF FENDER,RHF DOOR)	\$800.00	669
3	To check wiring	\$50.00	201
4	To do wheel alignment.	\$120.00	601
5	To tuff coat	\$100.00	30f
6	To remove & refit Door trim, door glass, window regulator,		
	door lock to assist work load.	\$150.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUBF	OLDER TRA	CKING									
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj S	Submitted	Ins Auth'ed		Status	
Main	26 Nov 2018		28 Nov 2018 14:28 Edit Adj Rpt	S\$2,001.	1		<b>001.39</b> w Rpt			Pending for Report Cancel Cas	
	Main	R	eference	Cla	im Deta	ils		Docume	nts	$\supset$	Show All
CLAIM SU	BFOLDER DE	TAILS					[Created l	y insurer]			
Insured:	-, Co. Re	g. No.: -									
Main Claimant:	GRAB REI	NTALS PTE LTD									
Vehicle Reg No.:				Date of L	oss:	13/11/2018 00:00 - :59 [ <b>26</b> Months and <b>5</b> Days From LTA Reg Date (Man Yr)]					
Claim Type:	The Design Management Constitution of the Cons			Policy/Co Note No.:		DMPCSN3054531801					
Vehicle Reg No. (Insured):	SJP956P				Policy No. (Claimant						
					Excess:		S\$0.00				
Repairer:	Esteem P	erformance Pte	Ltd - Sin Ming (HQ)	) 385 Sin Mi	ng Drive,	5757	718 Sin Ming	- Tel:			
Handling Insurer:			(Singapore) Pte. Lt		Maria Maria		ELEVEL VECTOR DE LOS			100.00	
Adjuster:	LKK Auto	<b>Consultants Pte</b>	Ltd (HQ) - Tel: 625	66-3561 [	Handled	by KE	ENNETH KO	NG] [Fina	I Rpt	due 07/12	2/2018]
Adj Asg. Remarks:	EST \$4732	2.04 , CASE WITH	SJE.								
ASSOCIAT	ED MAIL RE	CEIVED							View All	Compo	se Case Mail
There are n	o mail for this	case.									
		sks⊟				V	iew All S	earch Tasks	Create	New Task	Complete

### **Claim Documents**

\*SLF7429C (SNM18D05556C02) [SJP956P] GRAB RENTALS PTE LTD Nov 13 2018 12:00AM [-]
Esteem Performance Pte Ltd - Sin Ming

Upload Documents Upload Photos Compose New Letter			View View in Browser				
Doc	umentation			1 per p	page 🔽	<b>✓</b>	
No	Finalized On	China Taip	ing Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print	
1	28/11/18 14:27	EMAIL FM	ESTEEM	0	Load PDF		
2	28/11/18 14:28	REPAIR ES	ST WITH TP GIA	0	Load PDF		

# **Documents Checklist**

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI18021421/KVD3E2

Date:

10/01/2019

No:

REFERENCE

Handling Insurer:

China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No:

DMPCSN3054531801

Claimant Vehicle

No :

SLF7429C

Insured Vehicle No :

SJP956P

Date of Loss:

13/11/2018

Nature of Claim: TP

Claim SNM18D05556C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SLF7429C

Make & Model:

TOYOTA PRIUS, 1.5 (A)

Engine No:

2ZRR933053

231594 km

Reg. Date: Colour: 08/09/2016 (Man. Year: 2016) Metallic Pearl White Chassis No: Odometer: JTDKB3FU703532133

Engine Capacity:

1798 cc

Market Value/New Car Price: N/A Sum Insured (S\$): Mar

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side:

Davanti 4 mm

Rear Left Side:

Davanti 2 mm

Front Right Side:

Davanti 4 mm

Rear Right Side:

Davanti 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,712.04	831.39	1,880.65	69.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,020.00	1,170.00	850.00	42.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,732.04	2,001.39	2,730.65	57.71
+ GST 7.00/7.00% (S\$)	331.24	140.10	191.14	57.70
Nett Amount (S\$)	5,063.28	2,141.49	2,921.79	57.71

**INSPECTION** 

Date of Assignment:

28/11/2018

Date Inspected:

04/12/2018 Inspected At:

Esteem Performance Pte Ltd - Sin Ming

(HQ)

BLK 5033ANG MO KIO INDUSTRIAL

PARK 2#01-259 SINGAPORE 569536

Estimated Period of Repair:

4.0 days

Adjuster Report Page 2 of 4

Adjuster: KENNETH KONG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Jan 2019)

Parts: 144 TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLF7429C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	450.80 FL	*-FL
2	10		*FRONT BUMPER CLIP	Not Necessary	40.00 FL	*-FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	107.20 FL	*-FL
4	1		*FRONT BUMPER EMBLEM	Not Necessary	87.10 FL	*-FL
5	1		*RH FRONT FENDER	Bent	868.70 FL	*868.70 FL
6	1		*RH FRONT FENDER UNDERSHIELD	Serviceable	185.64 FL	*- FL
7	10		*RH FRONT FENDER UNDERSHIELD CLIP	Not Necessary	25.00 FL	*-FL
8	1		*RHF FENDER WORDING HYBRID	Necessary	44.17 FL	*44.17 FL
9	1		*RH FRONT DOOR	Repair	1,121.75 FL	*-FL
10	1		*RH FRONT DOOR HINGE TOP	Repair	78.30 FL	*-FL
11	1		*RH FRONT DOOR HINGE BOTTOM	Repair	78.30 FL	*-FL
12	1		*RH FRONT DOOR WEATHERSTRIP	Serviceable	211.69 FL	*- FL
13	1		*RHF DOOR GLASS OUTER MOULDING	Serviceable	121.75 FL	*-FL
14	1		*RH FRONT HUB CAB	Dented / Cut	195.65 FL	*195.65 FL
F=Fra	anchise	part. L=ListIt	emDisc.	-		
				Sub Total (S\$)	3,616.05	1,108.52
			- List Item Discount on L Ite	ems 25.00/25.00% (S\$)	904.01	277.13
				Total Parts (S\$)	2,712.04	831.39

Report was unsubmitted during this print-out.

Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER, RHF FENDER, RHF DOOR)	New	800.00	400.00
TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER, RHF FENDER, RHF DOOR)	New	800.00	660.00
TO CHECK WIRING	New	50.00	20.00
TO DO WHEEL ALIGNMENT	New	120.00	60.00
TO TUFF COAT	New	100.00	30.00
TO REMOVE & REFIT DOOR TRIM, DOOR GLASS, WINDOW REGULATOR, DOOR LOCK TO ASSIST WORK LOAD	New	150.00	0.00
Gross Labou	r Cost (S\$)	2,020.00	1,170.00
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER, RHF FENDER, RHF DOOR) TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER, RHF FENDER, RHF DOOR) TO CHECK WIRING TO DO WHEEL ALIGNMENT TO TUFF COAT TO REMOVE & REFIT DOOR TRIM, DOOR GLASS, WINDOW REGULATOR, DOOR LOCK TO ASSIST WORK LOAD	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER, RHF FENDER, RHF DOOR) TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER, RHF FENDER, RHF DOOR) TO CHECK WIRING TO DO WHEEL ALIGNMENT New TO TUFF COAT New TO REMOVE & REFIT DOOR TRIM, DOOR GLASS, WINDOW New	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER, RHF FENDER, RHF DOOR) TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER, RHF FENDER, RHF DOOR)  TO CHECK WIRING TO DO WHEEL ALIGNMENT New 120.00 TO TUFF COAT New 100.00 TO REMOVE & REFIT DOOR TRIM, DOOR GLASS, WINDOW REGULATOR, DOOR LOCK TO ASSIST WORK LOAD

Report was unsubmitted during this print-out.

< END OF ESTIMATES >