

ASS. REC. BY:

REF:

CS/FCI/8021422/kt d3

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Karen Tan

of

FCI

Date/Time: 1pm @ 27/11/18

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBA 2800R

Insured:

SHA 4356Y

at Workshop m/s

Cheng Hwe Motor

Tel:

87556142

of

Blk 1019, Yishun Ind. Park A# 01-374

Policy No:

Claim No:

D18008359MP8H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/11/18

CA / REV / REP. / REV 24 HRS

CS

H.O.D. Endorsement:

Date/Time: 2.21pm @ 27/11/18

Person Contacted:

effender

Vehicle IN

OUT

Date/Time	Action/Instruction (✓) Estimate
	GBA 2800R - CC4/ASM18006325/T1mb3 DOA: 31/3/18
	SHA 4356Y - CS/FCI/8013452/R1vd352 DOA: 17/7/18
28/11/18-	vni yet
4/12/18-	vehicle still not in
21/12/18-	vni yet
21/5/19-	12:03pm sent email pending estimate.

ASS. REC. BY:

REF:

FC21

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: _____

at Workshop n/vs _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 18,500

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBA 2800R Yr Regn: 05, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Dm9 c.c. 2882Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 759565 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTIFNT24YX-05000090Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: MT / S/Rlm / STD A/Rlm orTyre Size: F: B5 1P5 R15X8R: 155R 12X810

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 4 mmL/Bal. 5 mm L/Bal. 4 mmD.O.A. 21/11/18 D.O.I. 13/5/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

131 N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/ File pass to
EIT not ready

1/7 L1Dp @ 2400 confirmed E feeds CRed: 2311.03: 49%

MV: 18,500/-

LTA: 15,843/-

NV: 2657/-

RECEIVED 08 JUL 2019

Date/Time, File Pass to?

1) 8/7 Typist

Date/Time, File Return to?

2)

☐: Prel. Report☒: Final ReportDays Of Repair: 4Resurvey No. of Trlp: 2

Survey Fee:

Transportation:

S + RS. SI

Fines

Others

TOTAL

Add Fee: ☐: Site Insp (\$)☐: Interview (\$)☐: Tech Invs (\$)☐: Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$)

TP
2400/-

135
50
50+50
21
306

MOTOR SURVEY ASSIGNMENT

Date	23-11-2018	Our Ref No. D18008359MFSH
Accident Date	21-11-2018	Claim Type. Third Party
Insured Vehicle	SHA4356Y	Third Party Vehicle. GBA2800R
Survey Location	BLK 1019 YISHUN IND. PARK A #01-374	
Contact Person.	JUNE	
Contact No.	67556142/ 67556142	Fax No. 67557719
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHENG HOE MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 21 May 2019 12:08 PM
To: 'CWS Motor Claims'
Cc: assignments; 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008359MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GBA 2800R on 13/5/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 27 November 2018 1:03 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008359MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> Back to OneMotoring

GBA2800R

7P/7C

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 0237Z

Vehicle Details

Vehicle No.: GBA2800R
Vehicle to be Exported: No
Intended Deregistration Date: 12 Jan 2019
Vehicle Make: TOYOTA
Vehicle Model: DYNA 100 MANUAL
Primary Colour: Silver
Manufacturing Year: 2007
Engine No.: 1KD1632115
Chassis No.: JTFNT24YX05000090
Maximum Power Output: -
Open Market Value: \$21,284.00
Original Registration Date: 08 May 2007
First Registration Date: 08 May 2007
Transfer Count: 0
Actual ARF Paid: \$0.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Apr 2022
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 5
PQP Paid: \$24,005.00
COE Rebate Amount: \$15,843.00
Total Rebate Amount: \$15,843.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 12 Jan 2019

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

GBA2800R
 TP/PC

M/S : MS FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

TEL: 65073848
 ATTN: Motor Claim Department

FAX: 65073849

WS Ref: TP/FC/WL
 Claim Type: Third Party
 Accident Date: 21/11/2018
 TP Veh Reg No: SHA4356Y

Not Notified
1/2 Day B?
Runny After Rain

Estimate No: ES1991507/WL
 Date: 13 May 2019
 Policy No: P1489850
 Veh Reg No: GBA2800R
 Make/Model: TOYOTA DYNA 100 MANUAL
 Chassis No: JTFNT24YX05000090
 Engine No: 1KD1632115
 Reg. Date: 08/05/2007

Estimate Repair Cost to Vehicle No :GBA2800R

PAGE:1/1

Description	U/Price	Quantity	List Price SS	Amount SS
List Price				
1 FRONT BUMPER	356.20	1 PC	356.20	—
2 LH HEADLAMP	573.50	1 PC	573.50	—
3 LH HEADLAMP LOWER RUBBER	23.20	1 PC	23.20	—
4 FRONT LH CORNAL PANEL	282.20	1 PC	282.20	—
5 FRONT LH CORNAL GARNISH	134.50	1 PC	134.50	X
6 FRONT PANEL LOGO	53.50	1 PC	53.50	—
7 FRONT PANEL EMBLEM (DYNA)	72.10	1 PC	72.10	—
8 FRONT LH DOOR	1,980.10	1 PC	1,980.10	X
9 FRONT LH SIDE MIRROR	659.40	1 PC	659.40	✓
			4,134.70	
		Less 25%	1,033.68	3,101.03
Special Net				
10 FRONT LH DOOR COY STICKER	20.00	1 PC	20.00	✓
11 FRONT LH DOOR ADVERTISEMENT	120.00	1 PC	120.00	—
			140.00	140.00
Labour				
12 REMOVE & REFIX FRT BUMPER ASSY,HEADLAMP,CORNAL PANEL,FRT LH DOOR,TRANSFER DOOR ATTACHMENT,KNOCK & REPAIR FRT PANEL PILLAR & REALIGN THE SAME	600.00	1 LA	600.00	500
13 REMOVE & REFIX LH DOOR GLASS & CHECK CENTRAL LOCKING & POWER MIRROR	60.00	1 LA	60.00	✓
14 PUTTY & RESPRAY FRT BUMPER,LH DOOR,FRT PANEL,CORNAL PANEL	750.00	1 LA	750.00	680
15 RUSTPROOFING	60.00	1 LA	60.00	30
			1,470.00	1,470.00

Total SS 4,711.03
 Add GST @ 7% 329.77
 Total Amount Payable SS 5,040.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBA2800R 06
TP/PC

M/S : MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
TEL: 65073848 FAX: 65073849
ATTN: Motor Claim Department

Estimate No: ES1991507/WL
Date: 13 May 2019
Policy No: P1489850
Veh Reg No: GBA2800R
Make/Model: TOYOTA DYNA 100
MANUAL
Chassis No: JTFNT24YX05000090
Engine No: 1KD1632115
Reg. Date: 08/05/2007

WS Ref: TP/FC/WL
Claim Type: Third Party
Accident Date: 21/11/2018
TP Veh Reg No: SHA4356Y

Estimate Repair Cost to Vehicle No :GBA2800R

PAGE:1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 FRONT BUMPER	356.20	1 PC	356.20	
2 LH HEADLAMP	573.50	1 PC	573.50	
3 LH HEADLAMP LOWER RUBBER	23.20	1 PC	23.20	
4 FRONT LH CORNAL PANEL	282.20	1 PC	282.20	
5 FRONT LH CORNAL GARNISH	134.50	1 PC	134.50	
6 FRONT PANEL LOGO	53.50	1 PC	53.50	
7 FRONT PANEL EMBLEM (DYNA)	72.10	1 PC	72.10	
8 FRONT LH DOOR	1,980.10	1 PC	1,980.10	
9 FRONT LH SIDE MIRROR	659.40	1 PC	659.40	
			4,134.70	
		Less 25%	1,033.68	3,101.03
Special Net				
10 FRONT LH DOOR COY STICKER	20.00	1 PC	20.00	
11 FRONT LH DOOR ADVERTISEMENT	120.00	1 PC	120.00	
			140.00	140.00
Labour				
12 REMOVE & REFIX FRT BUMPER ASSY,HEADLAMP,CORNAL PANEL,FRT LH DOOR,TRANSFER DOOR ATTACHMENT,KNOCK & REPAIR FRT PANEL PILLAR & REALIGN THE SAME	600.00	1 LA	600.00	
13 REMOVE & REFIX LH DOOR GLASS & CHECK CENTRAL LOCKING & POWER MIRROR	60.00	1 LA	60.00	
14 PUTTY & RESPRAY FRT BUMPER,LH DOOR,FRT PANEL,CORNAL PANEL	750.00	1 LA	750.00	
15 RUSTPROOFING	60.00	1 LA	60.00	
			1,470.00	1,470.00
			Total	S\$ 4,711.03
			Add GST @ 7%	329.77
			Total Amount Payable	S\$ 5,040.80

2154.60
138.65
1615.95
140
1220
43075.95

44 A2400Y

④ day

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

STENT 24x105000090 List/buy

GAA 2800 R

TP → FC → 13/5/18

1 pc for bumper BT — \$356.20 —

1 pc for head lamp cm — \$573.50 —

lower rubber m.r. — \$23.20 —

1 pc for the corral panel BT — \$282.20 —

1 pc for the corral garnish ? \$134.50 —

1 pc for panel ~~Dyna~~ logo m.c. \$53.50 —

emblem Dyna m.c. \$72.10 —

~~1 pc for the corral panel~~

1 pc for the door \$1980.10 —

1 pc for the side mirror \$659.40 —

\$4134.70

1033.67

less 25%

\$3101.03

PH

CHENG HOE

62557719

GBA 2800 R

1 pr for 1/4 door
any stroke

~ (#20) / 50 ✓

1 pr for 1/4 door advertisement

~ (#120) / 50 ✓

① R & R for bumper assy head lamp,
corner panel, for 1/4 door, transfer door attachment,
To R & R for panel and really the same
pillar (#600) / 500 ✓

② R & R for 1/4 door glass and check
central locking and power window

(#60) / ✓

③ body a respray for bumper, 1/4 door,
for panel, corner panel,

(#750) / 689

④ R & R

(#60) / 301

\$4711.03



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18021422/Ktd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 12-07-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4356Y	Veh. Inspected	GBA 2800R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008359MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	27/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	JTFNT24YX05000090	Colour	SILVER	
Odometer	759565	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	BRIDGESTONE	5 mm	
L/H Front Tyre	195 R15X8	BRIDGESTONE	5 mm	
R/H Rear Tyre	155 R12X8 (D)	FIRENZA	4/4 mm	
L/H Rear Tyre	155 R12X8 (D)	FIRENZA	4/4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/11/2018	Inspection Date	13/05/2019	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBA 2800R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	BENT	356.20	356.20
1	LH HEADLAMP	CRACKED	573.50	573.50
1	LH HEADLAMP LOWER RUBBER	DISTORTED	23.20	23.20
1	FRONT LH CORNAL PANEL	BENT	282.20	282.20
1	FRONT LH CORNAL GARNISH	MTG CRACKED	134.50	134.50
1	FRONT PANEL LOGO	NECESSARY	53.50	53.50
1	FRONT PANEL EMBLEM (DYNA)	NECESSARY	72.10	72.10
1	FRONT LH DOOR	TO REPAIR SEE LABOUR	1,980.10	-
1	FRONT LH SIDE MIRROR	BRACKET BENT	659.40	659.40
	LESS 25% DISCOUNT		-1,033.67	-538.65
			3,101.03	1,615.95
<u>SPECIAL NETT ITEMS</u>				
1	FRONT LH DOOR COY STICKER (SN)	NECESSARY	20.00	20.00
1	FRONT LH DOOR ADVERTISEMENT (SN)	NECESSARY	120.00	120.00
			140.00	140.00
<u>LABOUR</u>				
	REMOVE & REFIX FRT BUMPER ASSY, HEADLAMP, CORNAL PANEL, FRT LH DOOR, TRANSFER DOOR ATTACHMENT, KNOCK & REPAIR FRT PANEL PILLAR & REALIGN THE SAME..		600.00	500.00
	REMOVE & REFIX LH DOOR GLASS & CHECK CENTRAL LOCKING & POWER MIRROR.		60.00	60.00
	PUTTY & RESPRAY FRT BUMPER, LH DOOR, FRT PANEL, CORNAL PANEL.		750.00	680.00
	RUSTPROOFING.		60.00	30.00
-			-	-
-			-	-
-			-	-
			1,470.00	1,270.00
GRAND TOTAL			4,711.03	3,025.95



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,400.00
---	--	--	----------

Report Ref No. CS/FC18021422/Ktd3n2

MARKET VALUE: \$18,500.00 (EST)-LTA REIMBURSEMENT VALUE: \$15,843.00=NETT VALUE: \$2,657.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.