

ASS. REC. BY:

REF: CS/CT118021423/Kt d34 Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Irene Tay of CT1 Date/Time: 27/11/18 @ 12:31pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLT 1220C Insured: SLJ 2780Z

at Workshop m/s Esteem performance Tel: 8799 0066

of BIK 5033 AMK Ind. park 2 #01-251/259

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 16/11/18
(Client's Record)CA / REV / REP. / REV 24 HRS ^{1up} H.O.D. Endorsement:Date/Time: 1:37pm @ 27/11/18 Person Contacted: Carmen Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLT 1220C-X
	SLJ 2780Z-X
28/11/18-	VNI yet
8/11	@ 2271.18 Confirm by email Cred: 3288-38: 59%

REF: CTL

ASSIGNMENT

From: Date: 04.12.2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLT 1220C
at Workshop m/s: Esteem Performance
of: 385 Sim Ming Drive

Insured:

Policy No:

Claims No:


Sum Insured: Excess:

(Client's Record)

Make of Veh:

after Nam

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SLT 1220C Yr Regn: 10 / 17

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

C.C.

1798

Colour:

M. White

A/C: Insured / Std / NI / NA

Sp. Reading:

101810

T/Radio: Insured / Std / NI / NA

Eng/No:

J10RKB31FU 303 573908

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / Rim or

Tyre Size:

F: Yokohama

195/65R15

R: Gmax

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

6

mm

L/Bal.

9

mm

L/Bal.

6

mm

D.O.A.

16/11/18

D.O.I.

4/12/18

Survey held at

✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear door

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

5/12 File pass to Catherine

RECEIVED 09 JAN 2019

Date/Time, File Pass to?

1) 01/12 Typist

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / I.B.I: (\$ 2271.19)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

220

220

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Tuesday, 27 November 2018 12:31 PM
To: Carmen Lim
Cc: assignments; Admin A; Lucas Lee
Subject: CTP REF NO. SLJ2780Z E REF : SLT1220C - ACCIDENT INVOLVING SLJ2780Z AND SLT1220C ON 16 NOVEMBER 2018

Dear Sir,

We refer to the above matter and our telephone conversation a moment ago.

As spoken, you have requested for LKK to survey your vehicle.

Aside to LKK: Please liaise with Ms Carmen from Esteem @ 8799-0066 for the PRS.

Thank you.

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insura

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/11/2018 14:33
Date Of Accident	16/11/2018 09:45
Exact Location Of Accident	DRIVEWAY BLK 376C HOUGANG ST 32
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT1220C
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS HYBRID 1.8 CVT
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29069766MKF
Cover Note Number	
Driver	
Name of Driver	YUE SIEN KIAT
NRIC No	S8415613B
Date Of Birth	09/06/1984
Occupation	OUTDOOR
Date Of Driving Pass	17/01/2005
Driving Experience	13 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83093334
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CHOW YUAN KUEN
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE DATE AND TIME MENTIONED, I WAS AT THE MENTIONED LOCATION AND MY CAR WAS STATIONARY WHEN VEHICLE B WAS REVERSING TOWARDS MY VEHICLE AND SEEING THIS, I HONKED AT VEHICLE B, BUT IT KEPT ON REVERSING AND HIT THE REAR RIGHT PORTION OF MY VEHICLE. NO BODY WAS INJURED. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	RETRIEVING
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLJ2780Z
Vehicle Make/Model/Colour	TOYOTA/WISH 1.8 CVT/BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ANG YONG CHEE
NRIC/Passport Number	S8230814H
Contact Number	81218413
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS
REPORTING OFFICER
Hashim

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

161118

Sketch Plan

Common Statement

ACCIDENT STATEMENT (2000 characters)

ON THE DATE AND TIME MENTIONED, I WAS AT THE MENTIONED LOCATION AND MY CAR WAS STATIONARY WHEN VEHICLE B WAS REVERSING TOWARDS MY VEHICLE AND SEEING THIS, I HONKED AT VEHICLE B, BUT IT KEPT ON REVERSING AND HIT THE REAR RIGHT PORTION OF MY VEHICLE. NO BODY WAS INJURED. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect.

VERIFIED BY AJAX MARS REPORTING OFFICER -
HASHIM BIN KAMARI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

16 November 2018 at 11:28 AM

Date/Time:

16 November 2018 at 11:28 AM

China
LKK-4/12/18 @
11:00



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLT 1220 C

Parts	(a) Cost / List Price Items	\$	3,652.76
	Plus/Less 25%	\$	913.19
	Total of Cost / List	\$	2,739.57
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost		\$	2,739.57
Labour		\$	2,820.00
Total		\$	5,559.57

Not Authorized
Penney Bypain

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before later spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 4/12/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 03 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 4/12/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLT 1220 C
Make & Model : TOYOTA PRIUS
Chassis No : JTDKB3FU303573908

Submit By : Carmen Lim
Year Manufacture : 2017
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH rear door	1	\$1,181.75		✓
2	RH rear door hinge top	1	\$78.34		X
3	RH rear door hinge bottom	1	\$78.34		X
4	RH rear door lock	1	\$411.70		X
5	RH rear door checker	1	\$156.79		X
6	RH rear door weatherstrip	1	\$178.40		✓
7	RHR door glass outer moulding	1	\$111.61		X
8	RHR power window motor	1	\$511.69		X
9	RHR power window regulator	1	\$177.64		X
10	RH side skirt	1	\$721.50		✓
11	RH side skirt clip	10	\$45.00		✓
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLT 1220 C** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (RH REAR DOOR,RHR FENDER,RH SIDE SKIRT)	\$1,000.00	300
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (RH REAR DOOR,RHR FENDER,RH SIDE SKIRT)	\$800.00	400
3	To check wiring	\$50.00	20
4	To do wheel alignment. <i>nn</i>	\$120.00	x
5	To tuff coat	\$100.00	30
6	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$150.00	60
7	To do art work <i>(Bill)</i>	\$600.00	? x

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

...CLAIM SUBFOLDER...(Pending for Survey Report)












CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Nov 2018		05 Dec 2018 15:50 Edit Adj Rpt	S\$2,271.19 Edit Estimates	S\$2,271.19 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: ANG YONG CHEE , ID: S8230814H									
Main Claimant: GRAB RENTALS PTE LTD									
Vehicle Reg. No.: SLT1220C		Date of Loss: 16/11/2018 09:00 - :59 [12 Months and 28 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D05412C02		Policy/Cover Note No.: DMPCSN3082891700 (Comprehensive)							
Vehicle Reg. No. (Insured): SLJ2780Z		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259, 569536 Ang Mo Kio - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 14/12/2018]									
Adj Asg. Remarks: EST \$5559.57, CASE WITH SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT1220C (SNM18D05412C02)
[SLJ2780Z]
TP
GRAB RENTALS PTE LTD
Nov 16 2018 9:00AM
[ANG YONG CHEE]
Esteem Performance Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Video							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Jin Auto Services Pte Ltd (Defu)						Thumbnail	Print	
1	16/11/18 12:25	Video - Accident [Linked Accident Report Documents]					1	Load MP4		
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Jin Auto Services Pte Ltd (Defu)						Thumbnail	Print	
1	16/11/18 12:25	Accident Statement					1	Load HTM		
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Jin Auto Services Pte Ltd (Defu)						Thumbnail	Print	
1	16/11/18 12:24	Accident Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>	
2	16/11/18 12:24	Accident Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>	
3	16/11/18 12:24	Accident Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>	
4	16/11/18 12:24	Accident Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>	
5	16/11/18 12:24	Accident Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>	
6	16/11/18 12:24	Accident Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>	
7	16/11/18 12:24	Accident Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>	
8	16/11/18 12:24	Accident Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>	
9	16/11/18 12:24	Accident Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>	
10	16/11/18 12:24	Accident Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>	
11	16/11/18 12:24	Scene Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>	
12	16/11/18 12:24	Scene Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>	
13	16/11/18 12:24	Scene Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>	
14	16/11/18 12:24	Scene Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>	
15	16/11/18 12:24	Scene Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>	
16	16/11/18 12:24	Scene Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>	
17	16/11/18 12:24	Scene Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>	
18	16/11/18 12:24	Scene Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	08/01/19 17:31	General View					1	Load JPG	<input checked="" type="checkbox"/>	
2	08/01/19 17:31	General View					1	Load JPG	<input checked="" type="checkbox"/>	
3	08/01/19 17:31	General View					1	Load JPG	<input checked="" type="checkbox"/>	
4	08/01/19 17:31	General View					1	Load JPG	<input checked="" type="checkbox"/>	
5	08/01/19 17:31	General View					1	Load JPG	<input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
6	08/01/19 17:31	General View	 Load JPG	<input checked="" type="checkbox"/>
7	08/01/19 17:31	General View	 Load JPG	<input checked="" type="checkbox"/>
8	08/01/19 17:31	General View	 Load JPG	<input checked="" type="checkbox"/>
9	08/01/19 17:31	General View	 Load JPG	<input checked="" type="checkbox"/>
10	08/01/19 17:31	General View	 Load JPG	<input checked="" type="checkbox"/>
11	08/01/19 17:31	General View	 Load JPG	<input checked="" type="checkbox"/>
12	08/01/19 17:31	General View	 Load JPG	<input checked="" type="checkbox"/>
13	08/01/19 17:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
14	08/01/19 17:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/12/18 15:49	OI GIA	 Load PDF	
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	16/11/18 12:23	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	16/11/18 12:23	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	16/11/18 12:23	Identification Card [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	16/11/18 12:23	Driving Licence [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	16/11/18 12:23	Driving Licence [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	16/11/18 12:24	Driving Licence [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

View

View in Browser

Video			1 per page	
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	16/11/18 12:25	Video - Accident	<div>1</div> Load MP4	

Assessment Reports

1 per page

No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	16/11/18 12:25	Accident Statement	<div>1</div> Load HTM	

Photos/Images

3 per page

No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	16/11/18 12:24	Accident Photo	<div>1</div> Load JPG	<input checked="" type="checkbox"/>
2	16/11/18 12:24	Accident Photo	<div>1</div> Load JPG	<input checked="" type="checkbox"/>
3	16/11/18 12:24	Accident Photo	<div>1</div> Load JPG	<input checked="" type="checkbox"/>
4	16/11/18 12:24	Accident Photo	<div>1</div> Load JPG	<input checked="" type="checkbox"/>
5	16/11/18 12:24	Accident Photo	<div>1</div> Load JPG	<input checked="" type="checkbox"/>
6	16/11/18 12:24	Accident Photo	<div>1</div> Load JPG	<input checked="" type="checkbox"/>
7	16/11/18 12:24	Accident Photo	<div>1</div> Load JPG	<input checked="" type="checkbox"/>
8	16/11/18 12:24	Accident Photo	<div>1</div> Load JPG	<input checked="" type="checkbox"/>
9	16/11/18 12:24	Accident Photo	<div>1</div> Load JPG	<input checked="" type="checkbox"/>
10	16/11/18 12:24	Accident Photo	<div>1</div> Load JPG	<input checked="" type="checkbox"/>
11	16/11/18 12:24	Scene Photo	<div>1</div> Load JPG	<input checked="" type="checkbox"/>
12	16/11/18 12:24	Scene Photo	<div>1</div> Load JPG	<input checked="" type="checkbox"/>
13	16/11/18 12:24	Scene Photo	<div>1</div> Load JPG	<input checked="" type="checkbox"/>
14	16/11/18 12:24	Scene Photo	<div>1</div> Load JPG	<input checked="" type="checkbox"/>
15	16/11/18 12:24	Scene Photo	<div>1</div> Load JPG	<input checked="" type="checkbox"/>
16	16/11/18 12:24	Scene Photo	<div>1</div> Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
17	16/11/18 12:24	Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
18	16/11/18 12:24	Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	16/11/18 12:23	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	16/11/18 12:23	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	16/11/18 12:23	Identification Card	 Load JPG	<input checked="" type="checkbox"/>
4	16/11/18 12:23	Driving Licence	 Load JPG	<input checked="" type="checkbox"/>
5	16/11/18 12:23	Driving Licence	 Load JPG	<input checked="" type="checkbox"/>
6	16/11/18 12:24	Driving Licence	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18021423/KTD3E2

Date: 10/01/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3082891700

Claimant Vehicle
No: SLT1220CInsured Vehicle
No: SLJ2780Z

Date of Loss: 16/11/2018

Nature of Claim: TP

Claim
No: SNM18D05412C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT1220C

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No: 2ZRS103345

Reg. Date: 19/10/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU303573908

Colour: Metallic Pearl White

Odometer: 101810 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Yokohama 9 mm

Rear Left Side: Gremax 6 mm

Front Right Side: Yokohama 9 mm

Rear Right Side: Gremax 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,739.57	1,461.19	1,278.38	46.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,820.00	810.00	2,010.00	71.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,559.57	2,271.19	3,288.38	59.15
+ GST 7.00/7.00% (S\$)	389.17	158.98	230.19	59.15
Nett Amount (S\$)	5,948.74	2,430.17	3,518.57	59.15

INSPECTION

Date of Assignment: 05/12/2018

Date Inspected: 04/12/2018 Inspected At:

Esteem Performance Pte Ltd (HQ)
Blk 5033 Ang Mo Kio Ind Park 2, #01-259
Singapore 569536

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Jan 2019)
Parts: 144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT1220C)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH REAR DOOR	Bent	1,181.75 FL	*1,181.75 FL
2	1		*RH REAR DOOR HINGE TOP	Repair	78.34 FL	*- FL
3	1		*RH REAR DOOR HINGE BOTTOM	Repair	78.34 FL	*- FL
4	1		*RH REAR DOOR LOCK	Repair	411.70 FL	*- FL
5	1		*RH REAR DOOR CHECKER	Serviceable	156.79 FL	*- FL
6	1		*RH REAR DOOR WEATHERSTRIP	Serviceable	178.40 FL	*- FL
7	1		*RHR DOOR GLASS OUTER MOULDING	Serviceable	111.61 FL	*- FL
8	1		*RHR POWER WINDOW MOTOR	Serviceable	511.69 FL	*- FL
9	1		*RHR POWER WINDOW REGULATOR	Serviceable	177.64 FL	*- FL
10	1		*RH SIDE SKIRT	Dented	721.50 FL	*721.50 FL
11	10		*RH SIDE SKIRT CLIP	Necessary	45.00 FL	*45.00 FL
					Sub Total (\$\$)	3,652.76 1,948.25
					- List Item Discount on L Items 25.00/25.00% (\$\$)	913.19 487.06
					Total Parts (\$\$)	2,739.57 1,461.19

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (RH REAR DOOR, RHR FENDER, RH SIDE SKIRT)	New	1,000.00	300.00
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (RH REAR DOOR, RHR FENDER, RH SIDE SKIRT)	New	800.00	400.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO DO WHEEL ALIGNMENT	New	120.00	0.00
5	TO TUFF COAT	New	100.00	30.00
6	TO REMOVE & REFIT DOOR TRIM, DOOR GLASS, WINDOW REGULATOR, DOOR LOCK TO ASSIST WORK LOAD	New	150.00	60.00
7	TO DO ART WORK	New	600.00	0.00
Gross Labour Cost (S\$)			2,820.00	810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >