

ASS. REC. BY:

REF: CS/CTI18021424/T1sd3n24 Special Instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

27/11/18 @ 12:36pm

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SL57835U

Insured:

SLV4486Y

at Workshop m/s

SK. Automobile

Tel:

6789 5155

of

1 Soon Lee Street #04-44/45

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/11/18

CA / REV / REP. / REV 24 HRS

cup

28/11/18

H.O.D. Endorsement:

Date/Time:

1:45pm @ 27/11/18

Person Contacted:

Huey Lee

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLV7835U - NBA/CTI18021206/Y

DUA: 21/11/18

SLV4486Y - NBA/CTI18021206/Y

DUA: 21/11/18

SL57835U - NBA/CTI18021206/Y

DUA: 21/11/18

Tayfikh


REF:

CT1

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To: Impact Vehicle No: _____
 at Workshop no: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Express: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

With No: SLV78354 Vt Page: 207 Oct
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or
 Make: Mazda. 5
 Colour: Red A/C: Insured / Std / NI / NA
 Sp. Reading: 26105 T/Radio: Insured / Std / NI / NA

Eng/Ho: _____
 C/No: 5M6W107110126.57

Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16
 R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front: 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 28/11/18

Survey held at: SK AutoDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time: 14/6 Action / Instruction: 686730R - 1 soon let st #04-44
4/5/5100, 6 days - Confirm with Au Xing
(# 12,022.04 Red - 70%)

RECEIVED 19 JUN 2019

Date/Time: File Pass to?

19/06/19

1)

- Typist

Date/Time: File Return to?

2)



Prell. Report



Final Report

Days Of Repair: 6Resurvey No. of Trip: 1

Survey Fee:

Transportation:

1. S-R

2. TRUCK

3. QUOTE

4. TOTAL

5. TOTAL

Add Fee:



Site Insp: \$



Interview: \$



Tech. Unit: \$



Workshop: \$

Report Format:

Lump Sum / L.B. \$ 5,100/- H/S

220

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Tuesday, 27 November 2018 12:36 PM
To: SK Admin
Cc: assignments; Admin A; Lucas Lee
Subject: CTP REF NO. SLV4486Y SK REF NO. SLS7835U - ACCIDENT INVOLVING SLV4486Y AND SLV7835U ON 21 NOVEMBER 2018

Dear Sir,

We refer to the above matter and our telephone conversation a moment ago.

As spoken, you have requested for LKK to survey your vehicle.

Aside to LKK: Please liaise with Ms Huey Lee from SK @ 6789-5155 for the PRS.

Thank you.

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insura



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Mazda 5

Price Range

Depreciation

2017

Vehicle Type



Home » Used Cars » Direct Owners » Mazda 5 2.0A Sunroof

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Vehicle Number Plates

BUY & SELL
Your AUSPICIOUS
& UNIQUE Vehicle No.

Do you know? Who are Singapore's
BIGGEST PLAYER
with the most vehicle plate numbers for sale?

Click here to see all Auctions Numbers

Mazda 5 2.0A Sunroof

Overview

Financial

Accessories

Similar

Research

Photos

Map

DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price **\$93,800 + Doc = \$94,600.00**

Depreciation \$9,680 /yr

View models with similar depreciation

Reg Date 08-Sep-2017

(Byrs Smiths 11days COE left)

Manufactured 2017

Mileage 18,000 km (14.8k /yr)

Transmission Auto

Engine Cap 1,998 cc

Road Tax \$1,210 /yr

Power 111.0 kW (148 bhp)

View specs of the Mazda 5 (2012-2016)

Curb Weight 1,532 kg

Features Reliable 2.0L 4 Cylinders Inline DOHC SKYACTIV-G Engine Family Car, Sunroof, 6 Speed Auto, Smart Key, Multi Steering Wheel, ABS And Airbags.

Accessories Pioneer Head Set, Front And Back Camera, In Car DVD And Navigation, Auto Door, Unuse Original Car Mat Will Be Provided For The Next Car Owner

Description Nice Number 1151. Well Maintain Seldom Drive With Low Mile Age. Accident Free Car. Second Family Car For Sales. Next Car Servicing 25K Mileage By Agent. Under Warranty By Eurokars. Made In Japan MPV. Original Condition With Well Maintained Exterior And Interior. Feel Free To Contact Me For Viewing. Price Negotiable. No Agent Please.

COE \$52,751

OMV \$17,527

ARF \$17,527

Dereg Value \$59,487 as of today (change)

No. of Owners 1

Type of Veh MPV

Category PARF Car, Direct Owner Sale

Availability Available

DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

Printed on: 21-Nov-2018 | Last Updated on: 21-Nov-2018

Tags: Mazda 5, mazda 5, 2017 Mazda 5, 2017 mazda 5, Mazda, Mazda 5, mazda 5, Used Mazda

Highly Recommended

Transfer Fee

\$25



Patterned steering wheel

Price Analysis

Vehicle Information

Contact Person(s) Terence Leong

Contact No. 92322126

Enquiry ☐ Contact Seller

USEFUL FORMS

» Indemnity form » Sales agreement

» Receipt » Hand-over form

» Ownership Transfer » M01

Instructions on how to complete a seller to end-consumer deal

Regardless of buying or selling, we'll handle your paperwork, loans & insurance for FREE.



Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Request Evaluation



Find out the market value for your car. Get a free Car Valuation.

Request Valuation

BLACK FRIDAY
ONLINE EXCLUSIVE

RECEIVE UP TO
\$S\$170
CAPITAL

Offer ends

Learn

Terms & Conditions

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 3912D

Vehicle Details

Vehicle No.: SL57835U
Vehicle to be Exported: No
Intended Deregistration Date: 22 Nov 2018
Vehicle Make: MAZDA
Vehicle Model: MAZDA5 WAGON 2.0 AT EU6
Primary Colour: Red
Manufacturing Year: 2017
Engine No.: PE10520543
Chassis No.: JM6CW1071H0126157
Maximum Power Output: 111.0 kW (148 bhp)
Open Market Value: \$17,341.00
Original Registration Date: 04 Oct 2017
First Registration Date: 04 Oct 2017
Transfer Count: 0
Actual ARF Paid: \$17,341.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 03 Oct 2027
PARF Rebate Amount: \$13,005.00

Intended COE Rebate Details

COE Expiry Date: 03 Oct 2027
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$49,189.00
COE Rebate Amount: \$43,599.00
Total Rebate Amount: \$56,604.00

The information contained herein is correct as at 22 Nov 2018

OK

\$ 94,600.00

\$ 56,604.00

\$ 37,996.00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/11/2018 14:50
Date Of Accident	21/11/2018 18:30
Exact Location Of Accident	CLEMENTI RD TOWARDS BUKIT TIMAH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS7835U
Insured/Policyholder	
Name Of Registered Owner	SIM CHUE HIN
NRIC No	S1823912D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97608195
Alternative Phone No	OFFICE-97608195

Vehicle Particulars

Manufacturer	MAZDA
Model	5-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT108105
Cover Note Number	

Driver

Name of Driver	SIM CHUE HIN
NRIC No	S1823912D
Date Of Birth	14/09/1967
Occupation	INDOOR
Date Of Driving Pass	17/08/1983
Driving Experience	35 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97608195
Fax Number	
Contact Number	OFFICE-97608195
Email Address	NOEMAIL

Address	BLK 179 LOMPANG RD #09-16
Postcode	870179
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 21/11/2018 AT 0630PM, I WAS DRIVING MY VEHICLE A (SLS7835U) CLEMENTI ROAD TOWARDS BUKIT TIMAH. THE TRAFFIC WAS HEAVY AND SLOW MOVING. VEHICLE INFRONT STOPPED AND I FOLLOW MY CAR WAS STATIONARY. WHEN SUDDENLY I FELT AN IMPACT IN THE REAR. I ALIGHTED AND FOUND VEHICLE B (SLV4486Y) HIT ON MY REAR. CAUSED DAMAGED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV4486Y
Vehicle Make/Model/Colour	
Details Of Properties	VEH B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police, for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name: QUEK KIM SENG
 NRIC/PIN No.: S8013338C

SKETCH PLAN



A -> SL8783SU

B -> SLV4486Y

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 21/11/2018 at 06:30pm, I was driving my vehicle A (SL8783SU) Clementi road towards Bukit Merah. The traffic was heavy and slow-moving. Vehicle in front stopped and I follow my car was stationary when suddenly I felt an impact in the rear. I alighted and found vehicle B (SLV4486Y) hit on my rear. Caused damaged.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
Date & Time:

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4 #03-01
Vicom Inspection Centre
Singapore 415933

Tel: 6789 5155 Fax : 6783 5155

TO	: CHINA TAIPING	DATE	: 26-Nov-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SLS7835U
ADDRESS	:	MODEL	: MAZDA 5
TEL. NO.	:	CHASSIS NO	:
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>		DATE	:
		TIME	:
THIRD PARTY REQUESTOR / CONTACT : XIONG 8121 0478			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER	1	\$ 1,845.00	\$ 1,845.00
2	REAR BUMPER REFLECTOR	2	\$ 154.00	\$ 308.00
3	REAR BUMPER CORNER RETAINER	2	\$ 112.40	\$ 224.80
4	REAR BUMPER SIDE RETAINER	2	\$ 124.20	\$ 248.40
5	REAR BUMPER REINFORCEMENT	1	\$ 215.30	\$ 215.30
6	TAILAMP	2	\$ 412.00	\$ 824.00
7	TAIL GATE	1	\$ 2,827.50	\$ 2,827.50
8	TAIL GATE INNER TRIM BOARD	1	\$ 589.20	\$ 589.20
9	TAIL GATE DAMPER	2	\$ 298.60	\$ 597.00
10	TAIL GATE REFLECTOR	2	\$ 312.00	\$ 624.00
11	TAIL GATE STOPPER	2	\$ 14.70	\$ 29.40
12	TAIL GATE LOWER LOCK	1	\$ 31.20	\$ 31.20
13	TAIL GATE TOP LOCK	1	\$ 286.70	\$ 286.70
14	TAIL AGTE WEATHERSTRIP	1	\$ 126.25	\$ 126.25
15	TAIL GATE LOGO	1	\$ 57.60	\$ 57.60

42 / 915.40
 X n7
 X n7
 45.20
 412
 412
 1559
 411.40
 X
 X
 X
 X
 11
 11
 11

16	TAIL GATE EMBLEM 'MAZDA'	1	\$ 30.30	\$ 30.30	nd ✓
17	TAIL GATE EMBLEM '5'	1	\$ 25.80	\$ 25.80	nd ✓
18	REAR FENDER INNER COWLING	2	\$ 96.60	\$ 193.20	X } nd ✓
19	REAR FENDER INNER TRIM	2	\$ 624.00	\$ 1,248.00	X } nd ✓
20	REAR END PANEL	1	\$ 451.50	\$ 451.50	nd ✓
21	REAR END PANEL TOP GARNISH	1	\$ 249.20	\$ 249.20	nd ✓
22	REAR SPARE TYRE BOLT	1	\$ 42.60	\$ 42.60	X } nd ✓
23	REAR SPARE TYRE COVER TRAY TOP BOARD	1	\$ 438.80	\$ 438.80	X } nd ✓
24	REAR SPARE TYRE TOOL BOARD	1	\$ 428.00	\$ 428.00	X } nd ✓
25	REAR FLOOR PANEL	1	\$ 1,188.00	\$ 1,188.00	nd ✓
26	REAR EXHAUST PIPE	1	\$ 993.00	\$ 993.00	nd ✓
27	REAR EXHAUST MOUNTING	2	\$ 37.40	\$ 74.80	X nd ✓

TOTAL PRICE \$ 14,197.55
 LESS 20% \$ 2,839.51
SUB TOTAL PRICE \$ 11,358.04

4831.05
 3864.84

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE	1	\$ 50.00	\$ 50.00	456 ✓
2	REAR BUMPER CLIP	4	\$ 6.50	\$ 26.00	nd ✓
3	TAIL LAMP CLIP	2	\$ 8.00	\$ 16.00	nd ✓
4	TAIL GATE WINDSCREEN INNER SHIELD	1	\$ 60.00	\$ 60.00	40 nd ✓
5	TAIL GATE WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00	nd ✓
6	REAR FENDER INNER TRIM CLIPS	18	\$ 6.50	\$ 117.00	X } nd ✓
7	REAR END PANEL TOP GARNISH CLIPS	6	\$ 6.50	\$ 39.00	X } nd ✓
8	REAR END PANEL INSULATION SEAL	1	\$ 120.00	\$ 120.00	X } nd ✓
9	REAR FLOOR PANEL INSULATION SEAL	1	\$ 150.00	\$ 150.00	X } nd ✓
10	REAR EXHAUST CHROME PIPE	1	\$ 180.00	\$ 180.00	nd ✓
11	REVERSE SENSOR	1	\$ 220.00	\$ 220.00	200 nd ✓
TOTAL				\$ 1,074.00	407

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$1,500.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$1,500.00	800
3	TUFF COAT	\$250.00	340
4	WIRING CHECK	\$50.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$300.00	60

6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$80.00	30
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$150.00	30
8	REAR CHASSIS ALIGNMENT	\$250.00	X 77
9	TRANSFER TAILGATE MECHANISM	\$80.00	60
10	REMOVE AND REFIX TAILGATE WINDSCREEN	\$120.00	✓
11	CONDUCT WATER LEAKAGE TEST	\$80.00	20
12	REMOVE AND REFIX REAR EXHAUST PIPE	\$150.00	60
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$180.00	100

2150

TOTAL

\$4,690.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 12,432.04
TOTAL LABOUR COST : \$ 4,690.00
TOTAL REPAIR COST : \$ 17,122.04

5864.84
407
2150

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

6421.84
1/595100
6 days

[Signature]
3/12/18
Taphin 97495749
- WP
28/11/18 R645
Resurvey after repair
6 days.
sure@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18021424/T1SD3N2

Date: 21/06/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3005301800
Claimant Vehicle No :	SLS7835U	Insured Vehicle No :	SLV4486Y
Date of Loss:	21/11/2018	Nature of Claim:	TP
		Claim No:	SNM18D05509C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS7835U	Engine No:	PE10520543
Make & Model:	MAZDA 5, 2.0 (A)	Chassis No:	JM6CW1071H0126157
Reg. Date:	04/10/2017 (Man. Year: 2017)	Odometer:	26105 km
Colour:	Red		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,432.04	4,271.84	8,160.20	65.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,690.00	2,150.00	2,540.00	54.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,122.04	6,421.84	10,700.20	62.49
Approved Total (Overridden) (S\$)		5,100.00		
(S\$)	17,122.04	5,100.00	12,022.04	70.21
+ GST 7.00/7.00% (S\$)	1,198.54	357.00	841.54	70.21
Nett Amount (S\$)	18,320.58	5,457.00	12,863.58	70.21

INSPECTION

Date of Assignment:	05/12/2018	
Date Inspected:	28/11/2018 Inspected At:	1 Soon Lee Street # 04-44/45 Repairer: SK Automobile Pte Ltd (Toh Guan) 48 Toh Guan Road East #01-121, Enterprise Hub Singapore 608586

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2019)
Parts:	M1-MPV	MAZDA 5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS7835U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,845.00 FL	*915.40 FL
2	2		*REAR BUMPER REFLECTOR	Not Necessary	308.00 FL	*- FL
3	2		*REAR BUMPER CORNER RETAINER	Not Necessary	224.80 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER	Necessary	248.40 FL	*90.60 FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	215.30 FL	*215.30 FL
6	1		*TAILLAMP	N/s Cracked/O/s Not Necessary	824.00 FL	*412.00 FL
7	1		*TAIL GATE	Bent	2,827.50 FL	*1,559.00 FL
8	1		*TAIL GATE INNER TRIM BOARD	Cracked	589.20 FL	*411.40 FL
9	2		*TAIL GATE DAMPER	Not Necessary	597.00 FL	*- FL
10	2		*TAIL GATE REFLECTOR	Not Necessary	624.00 FL	*- FL
11	2		*TAIL GATE STOPPER	Not Necessary	29.40 FL	*- FL
12	1		*TAIL GATE LOWER LOCK	Not Necessary	31.20 FL	*- FL
13	1		*TAIL GATE TOP LOCK	Dented	286.70 FL	*286.70 FL
14	1		*TAIL GATE WEATHERSTRIP	Cut	126.25 FL	*126.25 FL
15	1		*TAIL GATE LOGO	Necessary	57.60 FL	*57.60 FL
16	1		*TAIL GATE EMBLEM MAZDA	Necessary	30.30 FL	*30.30 FL
17	1		*TAIL GATE EMBLEM 5	Necessary	25.80 FL	*25.80 FL
18	2		*REAR FENDER INNER COWLING	Not Necessary	193.20 FL	*- FL
19	2		*REAR FENDER INNER TRIM	Not Necessary	1,248.00 FL	*- FL
20	1		*REAR END PANEL	Bent	451.50 FL	*451.50 FL
21	1		*REAR END PANEL TOP GARNISH	Deformed	249.20 FL	*249.20 FL
22	1		*REAR SPARE TYRE BOLT	Not Necessary	42.60 FL	*- FL
23	1		*REAR SPARE TYRE COVER TRAY TOP BOARD	Not Necessary	438.80 FL	*- FL
24	1		*REAR SPARE TYRE TOOL BOARD	Not Necessary	428.00 FL	*- FL
25	1		*REAR FLOOR PANEL	Repair	1,188.00 FL	*- FL
26	1		*REAR EXHAUST PIPE	Repair	993.00 FL	*- FL
27	2		*REAR EXHAUST MOUNTING	Not Necessary	74.80 FL	*- FL
28	1		*REAR NUMBER PLATE	Bent	50.00 FS	*45.00 FS
29	4		*REAR BUMPER CLIP	Necessary	26.00 FS	*26.00 FS
30	1		*TAIL LAMP CLIP (4 Pcs)	Necessary (2 Pcs only)	32.00 FS	*16.00 FS
31	1		*TAIL GATE WINDSCREEN INNER SHIELD	Necessary	60.00 FS	*40.00 FS
32	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	80.00 FS	*80.00 FS
33	18		*REAR FENDER INNER TRIM CLIPS	Not Necessary	117.00 FS	*- FS
34	6		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	39.00 FS	*- FS
35	1		*REAR END PANEL INSULATION SEAL	Not Necessary	120.00 FS	*- FS
36	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
37	1		*REAR EXHAUST CHROME PIPE	Not Necessary	180.00 FS	*- FS
38	1		*REVERSE SENSOR	Not Working	220.00 FS	*200.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$) 15,271.55 5,238.05

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 20.00/20.00% (S\$)					2,839.51	966.21
Total Parts (S\$)					12,432.04	4,271.84
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,500.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,500.00	800.00
3	TUFF COAT	New	250.00	40.00
4	WIRING CHECK	New	50.00	30.00
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	300.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	30.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	150.00	30.00
8	REAR CHASSIS ALIGNMENT	New	250.00	0.00
9	TRANSFER TAILGATE MECHANISM	New	80.00	60.00
10	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
11	CONDUCT WATER LEAKAGE TEST	New	80.00	20.00
12	REMOVE AND REFIX REAR EXHAUST PIPE	New	150.00	60.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	100.00
Gross Labour Cost (\$\$)			4,690.00	2,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >