

ASS. REC. BY:

REF:

CS/CTI18021426/Tttd361

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

27/11/18 @ 12.27

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH 291K

Insured:

GBE 2724G

at Workshop m/s

Mora Automotive

Tel:

62723892

of

Blk 1008, Bkt Merah Leine 3 #01-04

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/11/18

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

2.05pm @ 27/11/18

Person Contacted:

Nabilah

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

GBH 291K - X

GBE 2724G - X

Part by Part \$7620/- (Red: 1278; 14%)

Taufikh

REF:

CTI

CHRONICLE

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____
at Workshop n/s _____
of _____
Insured _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: G5H 291K Yr Regn: 2017 Dec
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____
Make: Maxus G60 C.C. 1850
Colour: Silver A/C: Insured / Std / NI / NA
Sp. Reading: 24077 T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: LSK G 46 L2H A06/187

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/70R16
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Hankook

Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.I. 30/11/18

Survey held at Mova Knyong

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

rear o/s
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 17 DEC 2018

14/12/2018

Date/Time: File Pass to?

H 12/12/18

Date/Time: File Return to?

TJ

Report Format :

Lump Sum / L.B. / IS

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Insp (\$)
☐ Weekend (\$)

Survey Fee:

Transportation:

Fuel & P.P. (\$)

Picture

Others

TOTAL

220

220

TP
7620

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Tuesday, 27 November 2018 12:27 PM
To: nitha
Cc: assignments; Admin A; Lucas Lee
Subject: CTP REF NO. GBE2724G M REF : GBH291K - ACCIDENT INVOLVING GBE2724G AND GBH291K ON 20 NOVEMBER 2018

Dear Sir,

We refer to the above matter and our telephone conversation a moment ago.

As spoken, you have requested for LKK to survey your vehicle.

Aside to LKK: Please liaise with Ms Nitha from Mova @ 6272-3892 for the PRS.

Thank you.

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insura

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/11/2018 16:44
Date Of Accident	20/11/2018 13:35
Exact Location Of Accident	UBI ROAD (CROSS JUNCTION)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH291K
Insured/Policyholder	
Name Of Registered Owner	EXCELSIOR ENGINEERING PTE LTD
Co Reg No	198500183E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62661836

Vehicle Particulars

Manufacturer	MAXUS
Model	G10 VAN 6AT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VFX/P2026500
Cover Note Number	

Driver

Name of Driver	MUHAMMAD RASUL BIN JAMIN
NRIC No	S8314806C
Date Of Birth	08/05/1983
Occupation	OUTDOOR
Date Of Driving Pass	18/09/2017
Driving Experience	1 YEAR AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87523448
Fax Number	
Contact Number	
EMail Address	MUHO.RASULJAMIN9122@GMAIL.COM

Address	APT BLK 618SENJA ROAD #03-72
Postcode	670618
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	JURONG NPP
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE POLICE REPORT T/20181121/2052

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE2724G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name

MUHAMMAD RASUL BIN JAMIN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan

21-11-18:14:30

1/2

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time: 21/11 1320H


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



21-11-18:14:30

224

US 1201

US 1 AVE 2

GBH 291K

GBE 272AM

[illegible]

I/We declare the foregoing particulars are true in every respect.

ced

[Signature]

Wf



Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 100B,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-008864-2

Estimate

22/11/2018

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1

Veh # :- GBH291K

Veh Model :- MAXUS G10 VAN 6AT

Estimate# :- CK418309

Claim # :-

ACC. Date :- 20/11/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

SPECIAL NET ITEMS :

1.	TAILGATE	1	PC	3,850.00	bt	3,850.00
2.	TAILGATE GLASS MOULDING	1	PC	125.00	ad	125.00
3.	TAILGATE GLASS SEALANT	1	PC	40.00	ad	40.00
4.	TAILGATE LOGO	1	PC	45.00	ad	45.00
5.	TAILGATE EMBLEM - SAIK MOTOR	1	PC	40.00	ad	40.00
6.	TAILGATE EMBLEM - MAXUS	1	PC	35.00	ad	35.00
7.	TAILGATE EMBLEM - GIO	1	PC	32.00	ad	32.00
8.	TAILGATE STICKER - C&C	1	PC	20.00	ad	20.00
9.	TAILGATE STICKER - 70KM/H	1	PC	10.00	ad	10.00
10.	TAILGATE STICKER - 8PAX	1	PC	10.00	ad	10.00
11.	TAILGATE REFLECTOR RH	1	PC	218.00	ad	218.00
12.	TAILGATE GARNISH - CHECK	1	PC			
13.	TAILGATE LOCK	1	PC	98.00	X R	98.00
14.	TAILGATE WEATHERSTRIP	1	PC	125.00	ad	125.00
15.	TAILGATE INNER TRIM - CHECK	1	PC			
16.	TAILGATE ASY RH <i>Tailamp assy RH</i>	1	PC	285.00	ad	285.00
17.	REAR FENDER RH (REPAIR)	1	PC			
18.	REAR END PANEL	1	PC	735.00	Rx	735.00
19.	REAR END PANEL TOP GARNISH - CHECK	1	PC			
20.	REAR BUMPER	1	PC	385.00	ad	385.00
21.	REAR BUMPER REFLECTOR RH	1	PC	55.00	ad	55.00
22.	REAR BUMPER RETAINER RH & LH	2	PC	15.00	ad	30.00
23.	REAR BUMPER CLIPS	10	PC	5.00	ad	50.00
24.	REVERSE SENSOR	1	PC	280.00	200	280.00

SPECIAL NET TOTAL S\$

6,468.00

LABOUR :

TO CUT/WELD REAR EDN PANEL, KNOCK AND
STRAIGHTEN REAR FENDER RH. REMOVE & REPLACE
ACCIDENT DAMAGED PARTS. REALIGN ALL
CONNECTION

600 700.00

SPRAY PAINT TAILGATE , REAR FENDER RH, REAR
END PANEL, REAR BUMPER

600 700.00

REMOVE & REPLACE TAILGATE GLASS

✓ 120.00

REMOVE & REPLACE TAILGATE MECHANISM AND
CHECK LOCKING SYSTEM

50 60.00

REMOVE & REPLACE REAR FENDER INNER TRIM RH,
GARNISH, COVERING

40 60.00

REMOVE & REPLACE REVERSE SENSOR AND CHECK
FUNCTION

30 50.00

TO APPLY SEAL ON WELDING JOINT

40 80.00

RUST PROOF AFFECTED AREAS

30 80.00

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

22/11/2018

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1 133262

Veh # :- GBH291K

Veh Model :- MAXUS G10 VAN 6AT

Estimate# :- CK418309

Claim # :-

ACC. Date :- 20/11/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	LABOUR TOTAL S\$			1,850.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 8,318.00

GST @ 7 % 582.26

AMOUNT DUE S\$ 8,900.26

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

8898

Tanjah 97495749
WP

30/11/18 @ 230 pm

5 days

Resurvey before paint.

sur@kkanato.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 100B,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

22/11/2018

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1

Veh # :- GBH291K

Veh Model :- MAXUS G10 VAN 6AT

Estimate# :- CK418309

Claim # :-

ACC. Date :- 20/11/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

SPECIAL NET ITEMS :

1.	TAILGATE	1	PC	3,850.00	bt 3,850.00 ✓
2.	TAILGATE GLASS MOULDING	1	PC	125.00	ad 125.00 ✓
3.	TAILGATE GLASS SEALANT	1	PC	40.00	ne 40.00 ✓
4.	TAILGATE LOGO	1	PC	45.00	nee 45.00 ✓
5.	TAILGATE EMBLEM - SAIK MOTOR	1	PC	40.00	sd 40.00 ✓
6.	TAILGATE EMBLEM - MAXUS	1	PC	35.00	ra 35.00 ✓
7.	TAILGATE EMBLEM - GIO	1	PC	32.00	ne 32.00 ✓
8.	TAILGATE STICKER - C&C	1	PC	20.00	ne 20.00 ✓
9.	TAILGATE STICKER - 70KM/H	1	PC	10.00	ne 10.00 ✓
10.	TAILGATE STICKER - 8PAX	1	PC	10.00	ne 10.00 ✓
11.	TAILGATE REFLECTOR RH	1	PC	218.00	na 218.00 ✓
12.	TAILGATE GARNISH - CHECK	1	PC		
13.	TAILGATE LOCK	1	PC	98.00	na x 98.00 x na
14.	TAILGATE WEATHERSTRIP	1	PC	125.00	ad 125.00 ✓
15.	TAILGATE INNER TRIM - CHECK	1	PC		
16.	TAILGATE ASY RH <i>Tail lamp assy RH</i>	1	PC	285.00	ad 285.00 ✓
17.	REAR FENDER RH (REPAIR)	1	PC		
18.	REAR END PANEL	1	PC	735.00	Rx 735.00 x
19.	REAR END PANEL TOP GARNISH - CHECK	1	PC		
20.	REAR BUMPER	1	PC	385.00	ne 385.00 ✓
21.	REAR BUMPER REFLECTOR RH	1	PC	55.00	na 55.00 ✓
22.	REAR BUMPER RETAINER RH & LH	2	PC	15.00	na 30.00 R440
23.	REAR BUMPER CLIPS	10	PC	5.00	ne 50.00 ✓
24.	REVERSE SENSOR	1	PC	280.00	na 280.00 ✓

SUPPLEMENTARY:

SPECIAL NET TOTAL S\$ *IPC REAR BUMPER REINFORCEMENT - \$580.00* *bt (na)* *1) 6120.00* 6,468.00

LABOUR :

TO CUT/WELD REAR EDN PANEL, KNOCK AND
STRAIGHTEN REAR FENDER RH, REMOVE & REPLACE
ACCIDENT DAMAGED PARTS, REALIGN ALL
CONNECTION

600 700.00

SPRAY PAINT TAILGATE , REAR FENDER RH, REAR
END PANEL, REAR BUMPER

600 700.00

REMOVE & REPLACE TAILGATE GLASS

✓ 120.00

REMOVE & REPLACE TAILGATE MECHANISM AND
CHECK LOCKING SYSTEM

50 60.00

REMOVE & REPLACE REAR FENDER INNER TRIM RH,
GARNISH, COVERING

40 60.00

REMOVE & REPLACE REVERSE SENSOR AND CHECK
FUNCTION

30 50.00

TO APPLY SEAL ON WELDING JOINT

#230 80.00

RUST PROOF AFFECTED AREAS

30 80.00

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 100B,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088664-2

Estimate

22/11/2018

CHINA TAIPING INSURANCE (S) PTE LTD
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909.

Attention :- XA017

Page # :- 1 133262
Veh # :- GBH291K
Veh Model :- MAXUS G10 VAN 6AT
Estimate# :- CK418309
Claim # :-
ACC. Date :- 20/11/18
Terms :- C.O.D Days
Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	LABOUR TOTAL S\$			> 1500.00 1,850.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 8,318.00

GST @ 7 % 582.26

AMOUNT DUE S\$ 8,900.26

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

1) PARTS 6120.00
2) LABOUR 1500.00
7620.00 PRP

Please advice. Thank You
Bert Leau.

Tanjin 97495749
'wp'

30/11/18 @ 230 pm
5 days

Resing before paint.
suo@hkauto.com



Automotive Pte Ltd

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel : (65) 6272 3892
Fax : (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

SUPPLEMENTARY

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Page : 1
Veh No : GBH291K
Model : MAXUS G10 VAN 4AT
Acc Date : 20-Nov-18
Incharge : BILLY

No	Description	Qty	U.Price	Amt \$
	<u>SPECIAL NET ITEMS:</u>			
1	REAR BUMPER REINFORCEMENT	1	\$ 580.00	\$ 580.00
	SPECIAL NET TOTAL S\$			\$ 580.00

NON-TAX AMOUNTS	\$580.00
GST @ 7%	\$40.60
AMOUNT DUE	<u>\$620.60</u>

Customer's Signature/Co. Stamp

MOVA AUTOMOTIVE PTE LTD

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Nov 2018		28 Nov 2018 16:18 Edit Adj Rpt	S\$7,620.00 Edit Estimates	S\$7,620.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	MENG HIOK MARKETING , Co. Reg. No.: 53029494W		
Main Claimant:	EXCELSIOR ENGINEERING PTE LTD , Co. Reg. No.: 198500183E		
Vehicle Reg. No.:	GBH291K	Date of Loss:	20/11/2018 13:00 - :59 [10 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D05446C02	Policy/Cover Note No.:	DMCVSN1665321802 (Comprehensive)
Vehicle Reg. No. (Insured):	GBE2724G	Policy No. (Claimant):	VFX/P2026500
		Excess:	S\$0.00
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3, 159722 Bukit Merah - Tel: 62723892/64763333		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 07/12/2018]		
Driver/Custodian (Insured):	LOH SIAW MENG (63 / Male), NRIC: S1129634C, Tel: +6594523461		
Adj Asg. Remarks:	EST \$8900.26, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.
















































ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBH291K (SNM18D05446C02)
[GBE2724G]
TP
EXCELSIOR ENGINEERING PTE LTD
Nov 20 2018 1:00PM
[MENG HIOK MARKETING]
Mova Automotive Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Video				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print	
1	21/11/18 17:25	Video - Accident [Linked Accident Report Documents]	Load MP4	<input checked="" type="checkbox"/>	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print	
1	21/11/18 17:25	Accident Statement	Load HTM	<input checked="" type="checkbox"/>	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print	
1	21/11/18 17:24	INSURANCE CERT [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>	
2	21/11/18 17:24	DL& IC [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>	
3	21/11/18 17:24	Police Report [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>	
4	21/11/18 17:24	Police Report [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>	
5	21/11/18 17:24	Police Report [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>	
6	21/11/18 17:24	Medical Certificate [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>	
7	21/11/18 17:24	Medical Invoice [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>	
8	21/11/18 17:24	ACCIDENT PHOTO [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	14/12/18 17:23	General View	Load JPG	<input checked="" type="checkbox"/>	
2	14/12/18 17:23	General View	Load JPG	<input checked="" type="checkbox"/>	
3	14/12/18 17:23	General View	Load JPG	<input checked="" type="checkbox"/>	
4	14/12/18 17:23	General View	Load JPG	<input checked="" type="checkbox"/>	
5	14/12/18 17:23	General View	Load JPG	<input checked="" type="checkbox"/>	
6	14/12/18 17:23	General View	Load JPG	<input checked="" type="checkbox"/>	
7	14/12/18 17:23	General View	Load JPG	<input checked="" type="checkbox"/>	
8	14/12/18 17:23	General View	Load JPG	<input checked="" type="checkbox"/>	
9	14/12/18 17:23	General View	Load JPG	<input checked="" type="checkbox"/>	
10	14/12/18 17:23	General View	Load JPG	<input checked="" type="checkbox"/>	
11	14/12/18 17:23	General View	Load JPG	<input checked="" type="checkbox"/>	
12	14/12/18 17:23	General View	Load JPG	<input checked="" type="checkbox"/>	
13	14/12/18 17:23	General View	Load JPG	<input checked="" type="checkbox"/>	
14	14/12/18 17:23	General View	Load JPG	<input checked="" type="checkbox"/>	
15	14/12/18 17:23	General View	Load JPG	<input checked="" type="checkbox"/>	
16	14/12/18 17:23	General View	Load JPG	<input checked="" type="checkbox"/>	
17	14/12/18 17:23	General View	Load JPG	<input checked="" type="checkbox"/>	
18	14/12/18 17:23	General View	Load JPG	<input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
19	14/12/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
20	14/12/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
21	14/12/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
22	14/12/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
23	14/12/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
24	14/12/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
25	14/12/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
26	14/12/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
27	14/12/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
28	14/12/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
29	14/12/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
30	14/12/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
31	14/12/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
32	14/12/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
33	14/12/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
34	14/12/18 17:23	General View	 Load JPG	<input checked="" type="checkbox"/>
35	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	14/12/18 17:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/11/18 16:18	EST REPAIR	Load PDF	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
2	28/11/18 16:18	TP GIA	Load PDF	
3	28/11/18 16:18	OI GIA	Load PDF	
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	21/11/18 17:18	Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	21/11/18 17:18	Sketch Plan #2 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/12/18 10:18	Supplementary	Load PDF	

Linked Accident Report Documents

			View View in Browser	
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	21/11/18 17:25	Video - Accident	Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	21/11/18 17:25	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	21/11/18 17:24	INSURANCE CERT	Load JPG	<input checked="" type="checkbox"/>
2	21/11/18 17:24	DL& IC	Load JPG	<input checked="" type="checkbox"/>
3	21/11/18 17:24	Police Report	Load JPG	<input checked="" type="checkbox"/>
4	21/11/18 17:24	Police Report	Load JPG	<input checked="" type="checkbox"/>
5	21/11/18 17:24	Police Report	Load JPG	<input checked="" type="checkbox"/>
6	21/11/18 17:24	Medical Certificate	Load JPG	<input checked="" type="checkbox"/>
7	21/11/18 17:24	Medical Invoice	Load JPG	<input checked="" type="checkbox"/>
8	21/11/18 17:24	ACCIDENT PHOTO	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	21/11/18 17:18	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	21/11/18 17:18	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118021426/T1TD3E2

Date: 18/12/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN1665321802

Claimant Vehicle
No: GBH291KInsured Vehicle
No: GBE2724G

Date of Loss: 20/11/2018

Nature of Claim: TP

Claim
No: SNM18D05446C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBH291K

Make & Model: MAXUS G10, 1.9 (A)

Engine No: 19D4N1RYH410K117

Reg. Date: 28/12/2017 (Man. Year: 2017)

Chassis No: LSKG4GL12HA061687

Colour: Silver

Odometer: 24077 km

Engine Capacity: 1850 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/70 R16

Rear Tyre Size: 215/70 R16

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,048.00	6,120.00	928.00	13.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,500.00	350.00	18.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,898.00	7,620.00	1,278.00	14.36
+ GST 7.00/7.00% (S\$)	622.86	533.40	89.46	14.36
Nett Amount (S\$)	9,520.86	8,153.40	1,367.46	14.36

INSPECTION

Date of Assignment: 28/11/2018

Date Inspected: 30/11/2018 Inspected At:

Mova Automotive Pte Ltd (Bukit Merah)
Blk 1008, #01-04/06/08/94, Bukit Merah
Lane 3
Singapore 159722

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Dec 2018)
Parts:	143	MAXUS G10 1.9 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH291K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	3,850.00 FS	*3,850.00 FS
2	1		*TAILGATE GLASS MOULDING	Necessary	125.00 FS	*125.00 FS
3	1		*TAILGATE GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
4	1		*TAILGATE LOGO	Necessary	45.00 FS	*45.00 FS
5	1		*TAILGATE EMBLEM - SAIK MOTOR	Necessary	40.00 FS	*40.00 FS
6	1		*TAILGATE EMBLEM - MAXUS	Necessary	35.00 FS	*35.00 FS
7	1		*TAILGATE EMBLEM - GIO	Necessary	32.00 FS	*32.00 FS
8	1		*TAILGATE STICKER - C&C	Necessary	20.00 FS	*20.00 FS
9	1		*TAILGATE STICKER - 70KM/H	Necessary	10.00 FS	*10.00 FS
10	1		*TAILGATE STICKER - 8PAX	Necessary	10.00 FS	*10.00 FS
11	1		*TAILGATE REFLECTOR RH	Cracked	218.00 FS	*218.00 FS
12	1		*TAILGATE GARNISH (NPA)	Repair	0.00 FS	*- FS
13	1		*TAILGATE LOCK	Repair	98.00 FS	*- FS
14	1		*TAILGATE WEATHERSTRIP	Cut	125.00 FS	*125.00 FS
15	1		*TAILGATE INNER TRIM (NPA)	Not Necessary	0.00 FS	*- FS
16	1		*TAILGATE ASSY RH	Cut	285.00 FS	*285.00 FS
17	1		*REAR FENDER RH (NPA)	Repair	0.00 FS	*- FS
18	1		*REAR END PANEL	Repair	735.00 FS	*- FS
19	1		*REAR END PANEL TOP GARNISH (NPA)	Not Necessary	0.00 FS	*- FS
20	1		*REAR BUMPER	Deformed	385.00 FS	*385.00 FS
21	1		*REAR BUMPER REFLECTOR RH	Cracked	55.00 FS	*55.00 FS
22	1		*REAR BUMPER RETAINER RH & LH	N/S Not Necessary/O/SDeformed	30.00 FS	*15.00 FS
23	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
24	1		*REVERSE SENSOR	Not Working	280.00 FS	*200.00 FS
25	1		*REAR BUMPER REINFORCEMENT	Bent	580.00 FS	*580.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 7,048.00 6,120.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT / WELD REAR END PANEL, KNOCK AND STRAIGHTEN REAR FENDER RH. REMOVE & REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION	New	700.00	600.00
2	SPRAY PAINT TAILGATE, REAR FENDER RH, REAR END PANEL, REAR BUMPER	New	700.00	600.00
3	REMOVE & REPLACE TAILGATE GLASS	New	120.00	120.00
4	REMOVE & REPLACE TAILGATE MECHANISM AND CHECK LOCKING SYSTEM	New	60.00	50.00
5	REMOVE & REPLACE REAR FENDER INNER TRIM RH, GARNISH, COVERING	New	60.00	40.00
6	REMOVE & REPLACE REVERSE SENSOR AND CHECK FUNCTION	New	50.00	30.00
7	TO APPLY SEAL ON WELDING JOINT	New	80.00	30.00
8	RUST PROOF AFFECTED AREAS	New	80.00	30.00
Gross Labour Cost (S\$)			1,850.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >