

22/03/2003

ASS. REC. BY:

REP:

CS/GAI18021431/TISD30

Special Instruction:

Surveyor:

T. White

ASSIGNMENT (Office)

From (Person):

Kelvyn Ngiran

of

GAI

Date/Time:

27/11/18 @ 2:06pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLL9565Y

Insured:

GY4978M

at Workshop m/s

Glocke Werke

Tel:

8112 6485

of

48 toh Guan Rd East #07-97

Policy No:

Claim No:

MOMVC000600 50302

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/11/18

CA / REV / REP. / REV 24 HRS

1up

28/11/18

H.O.D. Endorsement:

Date/Time:

2:39pm @ 27/11/18

Person Contacted:

Annabelle

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓) Estimate

27/11/18

Tdy wesp close, Repairer ask come tomorrow.

SLL9565Y-X

GY4978M-X

30/11/18

@ 17:36 p.m. revised PA to Kelvyn via email.

Taufikh

REF:

GAI

VEHICLE

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop no:

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Annabelle

Date / Time

Action / Instruction

29/3/19

Conform to \$3350, 4 days with Annabelle 4.8 for given red cost #07-97
(\$ 2,819.90 Red - 46%)

Veh No:

SLL 9565 Y

Vr Regn:

2017 March

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Heavy Shuttle

V.C.

1496

Colour:

Silver

A/C

Insured / Std / NI / NA

Sp. Reading

28623

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GK8/00491

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/57R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CST

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

mm

D.O.A.

D.O.I.

28/11/18

Survey held at

Glackewerke

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 02 APR 2019

Date/Time: File Pass to?

02/04/19

11

Date/Time: File Return to?

12

Report Format:

Lump Sum / I.B.L.

3,350/- H/S

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation

1. ... S-R

2. ...

3. ...

4. ...

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Wash and (\$

290

290

Shirley Hiew (LKK Auto)

From: Lim Annabelle <annabelle_lim90@hotmail.com>
Sent: Thursday, 21 March 2019 5:11 PM
To: Taufikh (LKKAuto)
Cc: Shirley Hiew (LKK Auto)
Subject: Re: Accident involving SLL 9565Y and GY 4978M on 20/11/18 12.20pm

Dear All,

Please proceed with the amount.

Thank you
Annabelle
GLOCKEWERKE
8112 6485

From: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Sent: Wednesday, January 16, 2019 10:24:42 AM
To: Lim Annabelle
Cc: Shirley Hiew (LKK Auto)
Subject: Re: Accident involving SLL 9565Y and GY 4978M on 20/11/18 12.20pm

Hi Annabelle,

Please refer attached.
Lumpsum\$3350, 4days.

Regards
Taufikh
Lkk Auto

Nivitha (LKK Auto)

From: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Sent: Tuesday, 27 November 2018 2:06 PM
To: Admin-D (LKKAuto); 'Admin A'
Subject: Our ref:MOMVC00000050302 ACCIDENT ON 20.11.2018 BETWEEN SLL 9565Y AND insd GY 4978M ALONG THE SERVICE ROAD AT ENTERPRISE HUB
Attachments: SLL9565Y_GIA Report.pdf

Hi team

TP survey please. Our insured has not report.

Thanks
Kelvyna

From: gerald@singhnco.com <gerald@singhnco.com>
Sent: Tuesday, November 27, 2018 12:00 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Cc: annabelle_lim90@hotmail.com
Subject: [External] RE: ACCIDENT ON 20.11.2018 BETWEEN SLL 9565Y AND insd GY 4978M ALONG THE SERVICE ROAD AT ENTERPRISE HUB
Importance: High

Our Ref: SC.GMW.2051.18.05
Your Ref: GY 4978M

APPOINTMENT OF SURVEYOR FOR PRE-REPAIR INSPECTION

Dear Kelvyna,

**CLAIM BY SEE CHYE HENG ROLAND, NRIC NO. S8947623B
THE OWNER OF SLL 9565Y AGAINST OWNER/DRIVER OF GY 4978M**

We refer to your email of 26 November 2018.

Our instructions are to agree to the appointment of No. 5 on your list LKK Auto Consultants for the conduct of the PRI.

As previously stated in our earlier email, our client's motorcar is presently located at the repairer's workshop,

Glockewerke
c/o 48, Toh Guan East, #07-97
Enterprise Hub
Singapore 608586
Tel: 81126485
Email: annabelle_lim90@hotmail.com
Attn: Annabelle Lim

And, you may contact Annabelle Lim who has been copied on this email directly to arrange for the PRI.

Yours faithfully,

Gerald Martin Wee

SINGH & CO.

77, High Street, #10-09,
High Street Plaza,
Singapore 179433.

Tel: +65 6338 3766

Fax: +65 6338 3762

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 30 November 2018 5:36 PM
To: 'Ngian, Kelvyna'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: Our ref:MOMVC00000050302 ACCIDENT ON 20.11.2018 BETWEEN SLL 9565Y AND insd GY 4978M ALONG THE SERVICE ROAD AT ENTERPRISE HUB
Attachments: SLL 9565Y - Preli Advise.pdf

Dear Kelvyna,

Enclosed preliminary revised of vehicle SLL 9565Y.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 27 November 2018 2:41 PM
To: 'Ngian, Kelvyna' <Kelvyna.Ngian@sg.gaig.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: Our ref:MOMVC00000050302 ACCIDENT ON 20.11.2018 BETWEEN SLL 9565Y AND insd GY 4978M ALONG THE SERVICE ROAD AT ENTERPRISE HUB

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer arrange survey on 28/11/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ngian, Kelvyna [mailto:Kelvyna.Ngian@sg.gaig.com]
Sent: Tuesday, 27 November 2018 2:06 PM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>
Subject: Our ref:MOMVC00000050302 ACCIDENT ON 20.11.2018 BETWEEN SLL 9565Y AND insd GY 4978M ALONG THE SERVICE ROAD AT ENTERPRISE HUB

Hi team

TP survey please. Our insured has not report.

Thanks
Kelvyna

From: gerald@singhnco.com <gerald@singhnco.com>

Sent: Tuesday, November 27, 2018 12:00 PM

To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>

Cc: annabelle_lim90@hotmail.com

Subject: [External] RE: ACCIDENT ON 20.11.2018 BETWEEN SLL 9565Y AND insd GY 4978M ALONG THE SERVICE ROAD AT ENTERPRISE HUB

Importance: High

Our Ref: SC.GMW.2051.18.05

Your Ref: GY 4978M

APPOINTMENT OF SURVEYOR FOR PRE-REPAIR INSPECTION

Dear Kelvyna,

**CLAIM BY SEE CHYE HENG ROLAND, NRIC NO. S8947623B
THE OWNER OF SLL 9565Y AGAINST OWNER/DRIVER OF GY 4978M**

We refer to your email of 26 November 2018.

Our instructions are to agree to the appointment of No. 5 on your list LKK Auto Consultants for the conduct of the PRI.

As previously stated in our earlier email, our client's motorcar is presently located at the repairer's workshop,

Glockewerke

c/o 48, Toh Guan East, #07-97

Enterprise Hub

Singapore 608586

Tel: 81126485

Email: annabelle_lim90@hotmail.com

Attn: Annabelle Lim

And, you may contact Annabelle Lim who has been copied on this email directly to arrange for the PRI.


Yours faithfully,
Gerald Martin Wee

SINGH & CO.
77, High Street, #10-09,
High Street Plaza,
Singapore 179433.

Tel: +65 6338 3766

Fax: +65 6338 3762

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: MOMVC00000050302

Date: 30 November 2018

Our Ref: CS/GAI18021431/T1sd3

The Motor Claims Department
Great American Insurance Company

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLL 9565Y .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 28/11/2018 at the premises of M/s Glockewerke and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 6,169.90</u> .
Revised Estimate Amount	: <u>S\$ 2,792.45</u> .
"Check" Items Amount	: <u>S\$ 427.50</u> .
Market Value	: <u>S\$</u> .
LTA Reimbursement Value	: <u>S\$</u> .
Nett Value	: <u>S\$</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 4 Days

Yours faithfully,
Mohamad Taufikh
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	21/11/2018 18:25
Date Of Accident	20/11/2018 12:20
Exact Location Of Accident	48 TOH GUAN RD EAST
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLL9565Y
Insured/Policyholder	
Name Of Registered Owner	SEE CHYE HENG ROLAND
NRIC No	S7822596C
Email Address	TAZZYLL@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96427622
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	HONDA
Model	SHUTTLE-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1720481801
Cover Note Number	
Driver	
Name of Driver	CHANG BING QUAN DARYL
NRIC No	S8947623B
Date Of Birth	23/12/1989
Occupation	INDOOR
Date Of Driving Pass	26/04/2010
Driving Experience	8 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98411062
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	105A DEPOT RD #07-609
Postcode	101105
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE 20/11/2018 AT ABOUT 1220HRS, MY VEHICLE A WAS PARKED OUTSIDE UNIT #07-98 OF ENTERPRISE HUB NO.48 TOH GUAN RD EAST. SUDDENLY VEHICLE B REVERSED INTO THE REAR PORTION OF MY VEHICLE A CAUSING DAMAGE TO MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GY4978M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time



Driver's Signature
(if driver is not the policyholder)
Date & Time




Recording Centre Personnel's Signature
Name
NRIC/Pass No.

Sketch Plan Pg. 2

• SKETCH PLAN

Vehicle A - SLL9563Y
Vehicle B - GY4978M



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 20/11/2018 @ about 12.20pm. My Vehicle A was parked outside unit #07-98 of Enterprise Hub No. 48 Toh Guan Road East. Suddenly a Vehicle B reversed into the rear portion of my Vehicle A causing damages to my Vehicle.

<input type="checkbox"/> Claim own policy	
<input type="checkbox"/> Claim third party	
<input checked="" type="checkbox"/> Claim CD / TP at other workshop	Glocke Werkz
<input type="checkbox"/> For record purpose only	
Policy No	
Insurer	Chuan
Veh No	SLL9563Y

DECLARATION

We declare the foregoing particulars are true in every respect.

[Signature]

[Signature]

[Signature]

Policyholder's Signature
Date & Time

Driver's Signature
If driver is not the policyholder
Date & Time

Reporting Centre Personnel's Signature
Name
ID Card No.

Glockewerke

21 Kaki Bukit Road 4 #01-02 S417810

Hotline: +65 8112 6485

Email: Annabelle_lim90@hotmail.com

ESTIMATE

SEE CHYE HENG ROLAND
105A DEPOT RD
#07-609 Singapore 101105
Contact No.: +65 9841 1062

Date: 21/11/2018
Vehicle No.: SLL 9565 Y
Model: HONDA SHUTTLE 1.5 A
Chassis No.: GK81004491

PARTS AND LABOUR ASSESSMENT

Description of Parts	Qty	Unit Price	Total Price
Rear Bumper	1	\$1160.00	\$1160.00 <i>de✓</i>
Rear Bumper Retainer	2	\$98.00	\$196.00 <i>* new</i>
Rear Tailgate	1	\$1300.00	\$1300.00 <i>bt✓</i>
Rear Tailgate Outer Garnish	1	\$450.00	\$450.00 <i>3 bth out✓</i>
Honda Logo	1	\$50.00	\$50.00 <i>re✓</i>
Shuttle Logo	1	\$56.00	\$56.00 <i>re✓</i>
End Panel Top Garnish	1	\$165.00	\$165.00 <i>x n7.</i>
Support End Panel	1	\$560.00	\$560.00 <i>Rx</i>
End Panel Sponge	2	\$70.00	\$140.00 <i>8 n7.</i>
Tailgate Rubber Seal Garnish	1	\$165.00	\$165.00 <i>re✓</i>
Sub-Total before discount:			\$4242.00 <i>3377</i>
Discount: 20%			\$212.10 <i>20%</i>
Sub-Total:			\$4029.90 <i>2701.60</i>

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Description of Parts	Qty	Unit Price	Total Price
Rear Bumper Clips (Set)	1	\$50.00	\$50.00
Rear Tailgate Screw Clip (Set)	1	\$50.00	\$50.00
Rear End Panel Screw	1	\$20.00	\$20.00
Rear Windscreen Seal	1	\$60.00	\$60.00

Reverse Sensor 200 nm ✓

Sub-total before discount: \$180.00
 0% discount: \$0.00
 Sub-total 2: \$180.00
 320 #

LABOUR

Diagnose, replace and repair to rectify electrical system for proper functioning (Rear Tailgate Lock control system and all electrical system) : \$120.00 30.

Check rear ultrasonic sensor, reverse camera wiring : \$120.00 30.

To provide workmanship labour to remove damage parts for assessment and change to new bodyparts, repair, re-construct and re-adjust structure, body alignments and damaged consistent from the accident. : \$800.00 500.

Labour to remove and install rear windscreen from old tailgate to new tailgate. : \$120.00 ✓

To re-spray painting for change bodyparts, repair portion and where consistent from the accident. : \$800.00 500.

Labour Sub-Total : \$1840.00 1960

Parts and Labour Total : \$6169.90

Labour
 Parts - 2701.60
 3N - 320
 Labour - 1180
 4201.60
 4/58 3350 #
 4 days

3/12/18
 62563561/
 Taufik 97495749
 'wp'
 28/11/18 @ 345pm
 Sur @ lkhant.com
 4 days.
 Resurvey after repair



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY			Ref : CS/GAI18021431/T1sd3e2	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190			Date : 15-04-2019	
			Code : GAI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GY 4978M	Veh. Inspected	SLL 9565Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	MOMVC00000050302	Excess (\$)	0.00	
Assign From	KELVYNA NGIAN	Assign Date	27/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	GK81004491	Colour	SILVER	
Odometer	28623	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	CST	6 mm	
L/H Front Tyre	195/55 R15	CST	6 mm	
R/H Rear Tyre	195/55 R15	CST	6 mm	
L/H Rear Tyre	195/55 R15	CST	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/11/2018	Inspection Date	28/11/2018	
Survey held at	GLOCKEWERKE-48 TOH GUAN ROAD EAST #07-97			
Repairer	-			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 9565Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	1,160.00	1,160.00
2	REAR BUMPER RETAINER @\$98.00	NECESSARY	196.00	196.00
1	REAR TAILGATE	BENT	1,300.00	1,300.00
1	REAR TAILGATE OUTER GARNISH	CUT	450.00	450.00
1	HONDA LOGO	NECESSARY	50.00	50.00
1	SHUTTLE LOGO	NECESSARY	56.00	56.00
1	END PANEL TOP GARNISH	NOT NECESSARY	165.00	-
1	SUPPORT END PANEL	TO REPAIR SEE LABOUR	560.00	-
2	END PANEL SPONGE @\$70.00	NOT NECESSARY	140.00	-
1	TAILGATE RUBBER SEAL GARNISH	NECESSARY	165.00	165.00
	LESS 20% DISCOUNT		-848.40	-675.40
			3,393.60	2,701.60
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET REAR TAILGATE SCREW CLIP (SN)	NECESSARY	50.00	30.00
1	REAR END PANEL SCREW (SN)	NOT NECESSARY	20.00	-
1	REAR WINDSCREEN SEAL (SN)	NECESSARY	60.00	60.00
1	REVERSE SENSOR (SN)	NOT WORKING	200.00	200.00
			380.00	320.00
<u>LABOUR</u>				
	DIAGNOSE, REPLACE AND REPAIR TO RECTIFY ELECTRICAL SYSTEM FOR PROPER FUNCTIONING (REAR TAILGATE LOCK CONTROL SYSTEM AND ALL ELECTRICAL SYSTEM)		120.00	30.00
	CHECK REAR ULTRASONIC SENSOR, REVERSE CAMERA WIRING.		120.00	30.00
	TO PROVIDE WORKMANSHIP LABOUR TO REMOVE DAMAGE PARTS FOR ASSESSMENT AND CHANGE TO NEW BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ADJUST STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT FROM THE ACCIDENT. INCLUSIVE OF THE REPAIR OF SUPPORT END PANEL.		800.00	500.00

Report Ref No. CS/GAI18021431/T1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR TO REMOVE AND INSTALL REAR WINDSCREEN FROM OLD TAILGATE TO NEW TAILGATE.		120.00	120.00
	TO RE-SPRAY PAINTING FOR CHANGE BODYPARTS, REPAIR PORTION AND WHERE CONSISTENT FROM THE ACCIDENT.		800.00	500.00
			1,960.00	1,180.00
GRAND TOTAL			5,733.60	4,201.60

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,350.00
--	--	--	--	----------

Report Ref No. CS/GAI18021431/T1sd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.