

ASS. REC. BY:

REF: CS/FCI18021432/KSD3

Special Instruction:

n2

Surveyor: Kenneth ASSIGNMENT (Office)

From (Person): Karen Tan of FCI Date/Time: 245pm @ 27/11/18

Estimated Cost: Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLE 6373R Insured: SHD 4516L

at Workshop m/s: Chew Guan Motor Tel: 64841626

of: Blk 10, AMK Ind. park 2A Ave 5 #01-15

Policy No: Claim No: D18008410MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 19/11/18
(Client's Record) 28/11/18

CA / REV / REP. / REV 24 HRS Cup H.O.D. Endorsement:

Date/Time: 3:34pm @ 27/11/18 Person Contacted: Grace Vehicle: (IN) / (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SLE 6373R - X
	SHD 4516L - CS / IMI 13008627 / H / vn DOA: 10/5/2013
30/11/18	@ 17:36 p.m. revised PA to Karen Tan via email.
11/1	@ 3037.04 email
	(\$ 1,257.44 Red - 29%)

ASS. REC. BY:

REF: FCZ/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop n/s Chew Green

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: 865k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLE 6373R Yr Regn: 07, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Vezel c.c. 1800

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading: 211548 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: R43 1115604

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 5 mm

L/Bal. 7 mm L/Bal. 5 mm

D.O.A. 19/11/18 D.O.I. 28/11/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

ols FR

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>29/11</u>	<u>File pass to Catherine</u>

RECEIVED 29 NOV 2019

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: 3

1) Typist

: Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: : Site Insp (\$)

Transportation:

Report Format :

: Interview (\$)

\$ - RS. \$1

Lump Sum / I.B.s: (\$ 3,037.04 p/p)

: Tech Invs (\$)

Fixtys

: Weekend (\$)

Others

TOTAL

135
50
50+50
23
TOTAL
308



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008410MFSH

Date: 30 November 2018

Our Ref: CS/FCI18021432/Ksd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLE 6373R

Please be informed that we had conducted the inspection of the abovementioned vehicle on 28/11/2018 at the premises of M/s Chew Goon Motor and have the following to report:-

Workshop Estimate Amount	: S\$ <u>4,294.48</u>
Revised Estimate Amount	: S\$ <u>3,586.48</u>
"Check" Items Amount	: S\$ _____
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the o/s front portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 3 Days

Yours faithfully,
Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	26-11-2018	Our Ref No. D18008410MFSH
Accident Date	19-11-2018	Claim Type. Third Party
Insured Vehicle	SHD4516L	Third Party Vehicle. SLE6373R
Survey Location	BLK 10, ANG MO KIO INDUSTRIAL PARK 2A AVE 5 #01-15,16,17 & #03-05AMK AUTOPOINT	
Contact Person.	GRACE	
Contact No.	64841626/ 0	Fax No. 64840465
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHEW GOON MOTOR	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 30 November 2018 5:36 PM
To: 'Karen Tan'; 'CWS Motor Claims'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: SURVEY ASSESSMENT - D18008410MFSH/1
Attachments: SLE 6373R - Preli Advise .pdf

Dear Karen,

Enclosed preliminary revised of vehicle SLE 6373R.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 27 November 2018 3:36 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008410MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 28/11/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 27 November 2018 2:45 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008410MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	0665X
Vehicle Details	
Vehicle No.:	SLE6373R
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Nov 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	LEB5065587
Chassis No.:	RU31115604
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$24,176.00
Original Registration Date:	28 Jul 2016
First Registration Date:	28 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jul 2026
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jul 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,089.00
COE Rebate Amount:	\$43,107.00
Total Rebate Amount:	\$46,857.00

The information contained herein is correct as at 20 Nov 2018

OK

REPUBLIC OF SINGAPORE
 IDENTITY CARD NO. S1164845B



NAME
 ROGER CHEW TIANG KWEE
 周 錫 佳
 RACE
 CHINESE
 DATE OF BIRTH
 16-09-1956 M
 PLACE OF BIRTH
 SINGAPORE




REPUBLIC OF SINGAPORE DRIVING LICENCE
 S1164845B



NAME
 ROGER CHEW TIANG KWEE
 DATE OF BIRTH
 16 Sep 1956
 EXPIRES
 30 Sep 2008




0016665000

S1164845B




19 PARRY WALK
 SINGAPORE 1954

12-05-1992

YOU ARE NOT PERMITTED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

CLASS	DATE
Class 1B Motorcycles <= 200cc	28 Jan 1977
Class 2A Motorcycles between 201cc and 400cc	28 Jan 1977
Class 2 Motorcycles > 400cc	28 Jan 1977
Class 3 Motor Cars <= 5000kg with <= 7 passengers exclusive of the driver and other motor vehicles <= 2500kg	08 Feb 1978



Licence No. S1164845B

KP

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

To: First Capital Insurance Limited

Accident Date : 19.11.2018

Policy No: Third Party

Date: 26.11.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Honda Vezel" Reg. No. SLE6373R Claiming Against Your Insured Veh. No. SHD4516L			
1pc	Front Bumper		481.00 ✓
12pcs	Front Bumper Clips	3.80	45.60 ✓
1pc	Front Bumper Reinforcement		335.00 X
1pc	Front Bumper Day Lamp		976.00 ✓
1pc	Front Bumper Day Lamp Cover		103.00 ✓
1pc	Front Fender Protector		160.00 ✓
8pcs	Front Fender Protector Clips	4.00	32.00 ✓
1pc	Headlamp Assy RH (LED)		1,823.00 ✓
			<u>3,955.60</u>
	Less 20%		791.12
			<u>3,164.48</u>
	To Conduct Front Electrical Check, Locking System, Adjust, Focus Headlamp etc		30.00 201
	Labour Charge - Panel Beating, Repairing Of Headlamp Panel, Front Fender and Parts Replacement		450.00 3201
	To Respray Affected Areas		650.00 3501
		Total :	<u><u>4,294.48</u></u>

Part 327.70

1784.50

NOT WITHHOLD
Respray B4 PART
3 days
3037-04

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

KP

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: First Capital Insurance Limited

Accident Date : 19.11.2018

Policy No: Third Party

Date: 26.11.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Honda Vezel" Reg. No. SLE6373R Claiming Against Your Insured Veh. No. SHD4516L			
1pc	Front Bumper	3.80	<i>MSCM</i> 481.00 ✓
12pcs	Front Bumper Clips		<i>me</i> 45.60 ✓
1pc	Front Bumper Reinforcement		<i>me</i> 335.00 ✓
1pc	Front Bumper Day Lamp		<i>SEA</i> 976.00 ✓
1pc	Front Bumper Day Lamp Cover		<i>me</i> 103.00 ✓
1pc	Front Fender Protector		<i>MSCM</i> 160.00 ✓
8pcs	Front Fender Protector Clips	4.00	<i>me</i> 32.00 ✓
1pc	Headlamp Assy RH (LED)		<i>GA</i> 1,823.00 ✓
	Less 20%		3,955.60
			791.12
			3,164.48
	To Conduct Front Electrical Check, Locking System, Adjust, Focus Headlamp etc		30.00 <i>201</i>
	Labour Charge - Panel Beating, Repairing Of Headlamp Panel, Front Fender and Parts Replacement		450.00 <i>3201</i>
	To Respray Affected Areas		650.00 <i>3501</i>
		Total :	<u>4,294.48</u>

Pi? 327.70

1784.50

Not Withheld

Resurvey by paint

3 days

3037.04

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18021432/Ksd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 26-08-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 4516L	Veh. Inspected	SLE 6373R
Policy No.		Coverage (\$)	0.00
Claim No.	D18008410MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	27/11/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU31115604	Colour	METALLIC PEARL WHITE
Odometer	211548	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55 R17	MICHELIN	7 mm
L/H Front Tyre	215/55 R17	MICHELIN	7 mm
R/H Rear Tyre	215/55 R17	MICHELIN	5 mm
L/H Rear Tyre	215/55 R17	MICHELIN	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/11/2018	Inspection Date	28/11/2018
Survey held at	CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 6373R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	MTG CRACKED	481.00	481.00
12	FRONT BUMPER CLIPS @\$3.80	NECESSARY	45.60	45.60
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	335.00	-
1	FRONT BUMPER DAY LAMP	SCRATCHED	976.00	327.70
1	FRONT BUMPER DAY LAMP COVER	DENTED	103.00	103.00
1	FRONT FENDER PROTECTOR	MTG CRACKED	160.00	160.00
8	FRONT FENDER PROTECTOR CLIPS @\$4.00	NECESSARY	32.00	32.00
1	HEADLAMP ASSY RH (LED)	CUT	1,823.00	1,784.50
	LESS 20% DISCOUNT		-791.12	-586.76
			3,164.48	2,347.04
LABOUR				
	TO CONDUCT FRONT ELECTRICAL CHECK, LOCKING SYSTEM, ADJUST, FOCUS HEADLAMP ETC.		30.00	20.00
	LABOUR CHARGE-PANEL BEATING, REPAIRING OF HEADLAMP PANEL, FRONT FENDER AND PARTS REPLACEMENT. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT.		450.00	320.00
	TO RESPRAY AFFECTED AREAS.		650.00	350.00
			1,130.00	690.00
GRAND TOTAL			4,294.48	3,037.04
RECOMMENDED COST OF REPAIRS				3,037.04

Report Ref No. CS/FCI18021432/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.