

**CHUNNI MOTOR WORK PTE LTD****REPAIR ESTIMATE\***

K, KME

VEHICLE NO : SHC 2988B (Supplementary)

DATE : 28.11.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI IONIQ

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Fender (LH) <i>Dental</i>			\$ 490.70 ✓
	Front Fender Apron Panel (LH) <i>2 hkl</i>			\$ 756.20 ✓ X
	Front Fender Shield (LH) <i>dislodged</i>			\$ 114.70 ✓
			605.40	
	SUB TOTAL			\$ 1,361.60
	LESS 20%			\$ 272.32
	DISCOUNTED TOTAL		484.32	\$ 1,089.28
<p><i>2</i></p> <p><i>np</i></p> <p><i>LKK Auto</i></p> <p><i>28/11/2018</i></p> <p><i>[Signature]</i></p> <div style="border: 1px solid black; padding: 5px;"> <p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

### REPAIR ESTIMATE\*

DATE : 31.2.2018

**TEL : 6542 5119**

**FAX : 6542 6039**

Page 1 of 1