

22/03/2002

ASS. REC. BY:

REF:

CS/CTI 8021435/And306

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Irene Tay

of

CTI

Date/Time: 27/11/18 @ 10:19am

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGC 7256J

Insured:

YN1418C

at Workshop m/s

BK Auto mobile

Tel:

6799 5155

of

81 Kelci Bldg Ave 4 #08-45 premier

Policy No:

BMCVSN 3029961807

Claim No:

SNM18D05506C07

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/11/18

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time:

12:02pm @ 27/11/18

Person Contacted:

Huey Lee

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

SGC 7256J - NA / CTI 18021242 / 24

DOA: 22/11/18

YN1418C - NA / CTI 18021242 / 24

DOA: 22/11/18

US 62700, 14 days (Red 53.817.85, 92%)

REF:

ASSIGNMENT

27/01/06

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent?: Yes or No

GIA / PR Seen: _____

Consistent?: Yes or No

Est. Repairs: _____

14 days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No. SG67256J. Yr Regn. 2006 / Jan.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota ViosC.C. 1497Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: _____

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053HY4204171239.Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/50R15R: 195/50R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A. _____

D.O.I. 27/1/18Survey held at SK.Des. of Damages Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Claim Total Loss.

*

MV: 1512.

PV: 12.3K / LTA: \$12194

Nett: 2.7K / NV: \$2800

RECEIVED 20 FEB 2019

Date/Time. File Pass to?



Preli. Report

1) 28/2/2018

Final Report

Date/Time. File Return to?

2)

Days Of Repair: 14

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

) S + RS. \$

) Photos

) Others

TOTAL

Add Fee: ☐

Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Report Format: MER-TPLump Sum / I.B.T. (\$ 2700)

220

220

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Tuesday, 27 November 2018 10:19 AM
To: SK Admin
Cc: Admin A; assignments; Lucas Lee
Subject: CTP REF NO. SGC7256J YOUR REF NO. YN1418C - ACCIDENT INVOLVING SGC7256J AND YN1418C ON 22 NOVEMBER 2018

Dear Sir,

We refer to the above matter and our telephone conversation a moment ago.

As spoken, you have requested for LKK to survey your vehicle.

Aside to LKK: Please liaise with Mr Xiong from SK Auto for the PRS.

Thank you.

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 3002G

Vehicle Details

Vehicle No.: SGC7256J
Vehicle to be Exported: No
Intended Deregistration Date: 30 Nov 2018
Vehicle Make: TOYOTA
Vehicle Model: VIOS 1.5E A
Primary Colour: Black
Manufacturing Year: 2005
Engine No.: 1NZX366739
Chassis No.: MR053HY4204171239
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$12,903.00
Original Registration Date: 27 Jan 2006
First Registration Date: 27 Jan 2006
Transfer Count: 2
Actual ARF Paid: \$5,209.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 Jan 2021
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$28,317.00
COE Rebate Amount: \$12,194.00
Total Rebate Amount: \$12,194.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Nov 2018

**Toyota Vios 1.5A E
(COE till 07/2020)****\$13,800** \$8,400 /yr 15-Jul-2005 1,497 cc - Sedan

AA Trust Certified Pre-Owned Vehicle! Extremely Well Maintained By Reputable By Previous Regular Servicing And Maintained By Reputable Japanese Workshop! Paper Value \$11K! Full In H...

AA Trust Automotive

Posted: 21-Nov-2018

Tags: 2005 Toyota Vios, 2005 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota

**Toyota Vios 1.5A E
(COE till 11/2020)****\$16,500** \$8,240 /yr 23-Nov-2005 1,497 cc 207 k

Good Well Maintained. Single Owner. Schedule A Test Drive Today. Viewing Is Strictly Only.

Carro

Posted: 19-Nov-2018

Tags: 2005 Toyota Vios, 2005 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota

**Toyota Vios 1.5A E
(COE till 01/2021)****\$14,800** \$6,870 /yr 17-Jan-2006 1,497 cc 158 k

Drive With Assurance! All Our Quality Pre-Owned Cars Are Selling At The Most Reasonable Price Of Mind! STA/VICOM Inspection Welcome! Down Payment \$1.9k, Flexible Bank Up To ...

CarQuotz Singapore

Posted: 10-Nov-2018

Tags: 2006 Toyota Vios, 2006 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota

**Door Visor**

Basic / Mugen / Injection Type Door Visors for SALE With Installation!

More info about this product

**Toyota Vios 1.5A E
(COE till 02/2021)****\$15,000** \$6,720 /yr 15-Feb-2006 1,497 cc 140 k

Posted: 16-Nov-2018

Tags: 2006 Toyota Vios, 2006 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/11/2018 09:51
Date Of Accident	22/11/2018 07:30
Exact Location Of Accident	PAYA LEBAR ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGC7256J
Insured/Policyholder	
Name Of Registered Owner	ZAMBRI BIN CHUPRI
NRIC No	S7613002G
Email Address	ZAMBRICHUPRI76@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97727606
Alternative Phone No	OTHERS-97727606

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS 1.5E A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own Insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5086743067-01
Cover Note Number	

Driver

Name of Driver	KHAIRANI BINTE MOHD RIFIAE
NRIC No	S7532500B
Date Of Birth	22/09/1975
Occupation	INDOOR
Date Of Driving Pass	10/03/2011
Driving Experience	7 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-84990412
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 626 #02-304 PASIR RIS DRIVE 3
 Postcode 510626
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions AFTER RAIN
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 3
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

THE INCIDENT TOOK PLACE ON THE ABOVEMENTIONED LOCATION, WHILE IN THE MIDST OF TRAVELLING, THE FRONT VEHICLE-C SLT4848Y STOP. I THEN FOLLOW SUIT, THAT IS WHEN VEHICLE B- YN1418C UNABLE TO REACT ON TIME AND THUS COLLIDED ONTO MY VEHICLE REAR PORTION. THE IMPACT HAS BRING MY VEHICLE TO MOVE FORWARD AND COLLIDED ONTO THE SAID VEHICLE REAR PORTION. WHICH RESULTED MY VEHICLE TO SUSTAIN DAMAGE FRONT AND REAR.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YN1418C
 Vehicle Make/Model/Colour ISUZU NNR85UH4A
 Details Of Propertles
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLT4848Y
Vehicle Make/Model/Colour	MAZDA5 WAGON 2.0 AT EU6
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

John
Policyholder's Signature

Date & Time: 10am

22/11/18

Han
Driver's Signature

(If driver is not the policyholder)

Date & Time: 10:00am

22/11/18

IDAC KAKI BUKIT (VAC)

Reporting Centre 23 Kaki Bukit Ave 4


Name: Singapore 415933

NRIC/ID No: 67416697 Fax: 67492305

Email: vackb@singnet.com.sg

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer e-File

DECLARATION ZambriChupri76@gmail.com

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 22/11/18

Driver's Signature

(If driver is not the policyholder)

Date & Time: 10:00am

22/11/18

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4
 Reporting Centre Personnel's Singapore 419999
 Name:
 Tel: 67416697 Fax: 67492305
 NRIC/PR No.:
 Email: vackb@singnet.com.sg

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO	: CHINA TAIPING	DATE	: 22-Nov-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SGC7256J
ADDRESS	:	MODEL	: TOYOTA VIOS
TEL. NO.	:	CHASSIS NO	:
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>		DATE	:
		TIME	:
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Disltd</i>	1	\$ 573.20	\$ 573.20
2	FRONT BUMPER TOWING COVER <i>new</i>	1	\$ 47.50	\$ 47.50
3	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 185.40	\$ 185.40
4	FRONT BUMPER FOG LAMP GARNISH <i>new</i>	2	\$ 120.40	\$ 240.80
5	FRONT BUMPER REINFORCEMENT <i>Best</i>	1	\$ 275.60	\$ 275.60
6	FRONT BUMPER REINFORCEMENT MEMBER <i>new</i>	2	\$ 201.60	\$ 403.20
7	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 74.60	\$ 149.20
8	FRONT BUMPER LOWER SPLASH SHIELD <i>new</i>	1	\$ 177.30	\$ 177.30
9	FRONT GRILLE <i>Cruld</i>	1	\$ 321.00	\$ 321.00
10	FRONT GRILLE BASE <i>new</i>	1	\$ 280.60	\$ 280.60
11	FRONT GRILLE MOULDING <i>Cruld</i>	1	\$ 224.70	\$ 224.70
12	FRONT GRILLE EMBLEM <i>new</i>	1	\$ 94.80	\$ 94.80

13	BONNET <i>Disltd</i>	1	\$ 870.90	\$ 870.90	✓
14	BONNET HINGES <i>Best</i>	2	\$ 65.00	\$ 130.00	✓
15	BONNET LOCK <i>Best</i>	2	\$ 180.30	\$ 360.60	✓
16	FRONT FENDER <i>Ry</i>	2	\$ 746.80	\$ 1,493.60	+
17	FRONT FENDER EMBLEM "VVTI" <i>new</i>	2	\$ 77.50	\$ 155.00	✓
18	FRONT FENDER INNER SHIELD <i>new</i>	2	\$ 167.90	\$ 335.80	+
19	FRONT SUPPORT PANEL <i>Bruched</i>	1	\$ 340.60	\$ 340.60	✓
20	FRONT SUPPORT PANEL SIDE GUARD <i>2 AH</i>	2	\$ 94.80	\$ 189.60	+
21	HEADLAMP ASSY <i>cruched</i>	2	\$ 644.70	\$ 1,289.40	✓
22	HEADLAMP UPPER BRACKET <i>new</i>	2	\$ 170.10	\$ 340.20	+
23	A/C CONDENSER <i>Best</i>	1	\$ 887.30	\$ 887.30	✓
24	A/C CONDENSER FAN COWLING <i>2</i>	1	\$ 240.60	\$ 240.60	+
25	A/C CONDENSER FAN BLADE <i>2 AH</i>	1	\$ 221.80	\$ 221.80	+
26	A/C CONDENSER FAN MOTOR <i>new</i>	1	\$ 304.70	\$ 304.70	+
27	A/C CONDENSER RUBBER MOUNTING	2	\$ 17.80	\$ 35.60	+
28	A/C CONDENSER SUCTION PIPE	1	\$ 445.00	\$ 298.20	+
29	A/C CONDENSER DISCHARGE PIPE	1	\$ 458.00	\$ 321.50	+
30	RADIATOR <i>Best</i>	1	\$ 1,331.20	\$ 1,331.20	✓
31	RADIATOR FAN COWLING <i>cruched</i>	1	\$ 248.70	\$ 248.70	✓
32	RADIATOR FAN BLADE <i>2 AH</i>	1	\$ 226.40	\$ 226.40	+
33	RADIATOR FAN MOTOR	1	\$ 311.40	\$ 311.40	+
34	RADIATOR RUBBER MOUNTING <i>2</i>	2	\$ 18.90	\$ 37.80	+
35	RADIATOR RESERVE TANK <i>2 AH</i>	1	\$ 86.50	\$ 86.50	+
36	WINDSCREEN WASHER TANK	1	\$ 214.00	\$ 214.00	+
37	WINDSCREEN WASHER TANK MOTOR	1	\$ 84.00	\$ 84.00	+
38	HORN <i>2 AH</i>	2	\$ 199.50	\$ 399.00	+
39	ENGINE MOUNTING <i>2 AH</i>	1	\$ 689.00	\$ 689.00	+
40	REAR BUMPER <i>Disltd</i>	1	\$ 547.90	\$ 547.90	✓
41	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 87.60	\$ 175.20	+
42	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 74.60	\$ 149.20	✓
43	REAR BUMPER SIDE BRACKET <i>new</i>	2	\$ 65.30	\$ 130.60	+
44	BOOTLID <i>Disltd</i>	1	\$ 948.30	\$ 948.30	✓
45	BOOTLID HINGE <i>Best</i>	2	\$ 65.00	\$ 130.00	✓
46	BOOTLID OUTER MOULDING <i>Disltd</i>	1	\$ 188.30	\$ 188.30	✓
47	BOOTLID CYLINDER LOCK <i>new</i>	1	\$ 101.70	\$ 101.70	+
48	BOOTLID EMBLEM <i>new</i>	1	\$ 94.80	\$ 94.80	✓

49	BOOTLID EMBLEM "VIOS" <i>free</i>	1	\$ 84.60	\$ 84.60	—
50	BOOTLID EMBLEM "E"	1	\$ 74.60	\$ 74.60	—
51	BOOTLID WEATHERSTRIP <i>cut</i>	1	\$ 175.00	\$ 175.00	—
52	BOOTLID INNER LOCK <i>found</i>	1	\$ 256.40	\$ 256.40	—
53	BOOTLID STRIKER <i>Best</i>	1	\$ 34.20	\$ 34.20	—
54	REAR FENDER <i>Regis</i>	2	\$ 974.60	\$ 1,949.20	+
55	REAR FENDER INNER WHEELHOUSE RH <i>Regis</i>	2	\$ 1,124.60	\$ 2,249.20	+
56	REAR FENDER AIR VENT RH <i>3rd</i>	2	\$ 175.30	\$ 350.60	+
57	REAR WINDSCREEN RUBBER MOULDING <i>1st</i>	1	\$ 175.90	\$ 175.90	+
58	REAR DOOR RH <i>Regis</i>	1	\$ 697.30	\$ 697.30	+
59	REAR DOOR BLACK STICKER RH <i>new</i>	1	\$ 28.50	\$ 28.50	+
60	REAR END PANEL <i>Disbld</i>	1	\$ 455.60	\$ 455.60	—
61	REAR END PANEL TOP GARNISH <i>Reltd</i>	1	\$ 285.70	\$ 285.70	—
62	REAR FLOOR PANEL <i>Regis</i>	1	\$ 863.10	\$ 863.10	+
63	REAR FLOOR PANEL TOP BOARD <i>1st</i>	1	\$ 332.30	\$ 332.30	—
64	REAR FRAME CHASSIS RH <i>Regis</i>	1	\$ 1,845.00	\$ 1,845.00	+
65	REAR FENDER SIDE INNER TRIM <i>3rd</i>	2	\$ 560.90	\$ 1,121.80	+
66	REAR WHEELHOUSE LINER <i>1st</i>	2	\$ 184.30	\$ 368.60	+
67	TAILLAMP <i>could</i>	2	\$ 457.30	\$ 914.60	—
68	TAILLAMP PANEL <i>Dented</i>	2	\$ 140.70	\$ 281.40	—
69	EXHAUST PIPE SILENCER <i>2</i>	1	\$ 466.90	\$ 466.90	+
70	EXHAUST PIPE CENTER PIPE <i>1st</i>	1	\$ 647.30	\$ 647.30	+
71	EXHAUST PIPE HEAT SHIELD <i>1st</i>	1	\$ 155.30	\$ 155.30	+
72	EXHAUST MOUNTING	2	\$ 32.00	\$ 64.00	+

TOTAL PRICE \$ 30,759.80
 LESS 25% \$ 7,689.95
SUB TOTAL PRICE \$ 23,069.85

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE WITH CASING <i>could</i>	1	\$ 50.00	\$ 50.00	—
2	FRONT BUMPER CLIP SET <i>1st</i>	1	\$ 70.00	\$ 70.00	30
3	FRONT BUMPER LOWER GRILLE CLIP SET <i>1st</i>	1	\$ 38.00	\$ 38.00	+
4	FRONT GRILLE CLIP SET <i>1st</i>	1	\$ 38.00	\$ 38.00	10
5	BONNET LABEL <i>new</i>	2	\$ 15.00	\$ 30.00	+
6	RADIATOR COOLANT <i>1st</i>	3	\$ 25.00	\$ 75.00	40
7	REAR NUMBER PLATE WITH CASING <i>could</i>	1	\$ 50.00	\$ 50.00	30
8	REAR BUMPER CLIP SET <i>1st</i>	1	\$ 65.00	\$ 65.00	30

9	BOOTLID SEALANT <i>green</i>	1	\$ 80.00	\$ 80.00	+
10	BOOTLID INNER TRIM CLIP SET	1	\$ 65.00	\$ 65.00	+
11	REAR END PANEL TOP GARNISH CLIP SET <i>me</i>	1	\$ 45.00	\$ 45.00	10
12	REAR FENDER SIDE INNER TRIM CLIP SET <i>2</i>	1	\$ 90.00	\$ 90.00	+
13	REAR WHEELHOUSE LINER CLIP SET	1	\$ 90.00	\$ 90.00	+
14	REAR WINDSCREEN INNER SEAL	1	\$ 110.00	\$ 110.00	+
15	REAR WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00	+
16	REAR FENDER SEALANT <i>HP</i>	2	\$ 301.00	\$ 602.00	+
17	REAR END PANEL SEALANT <i>me</i>	1	\$ 90.00	\$ 90.00	+
18	REAR FLOOR PANEL SEALANT	1	\$ 90.00	\$ 90.00	+
19	REAR FLOOR PANEL INSULATOR	1	\$ 250.00	\$ 250.00	+
20	REAR TAILLAMP PANEL SEALANT	1	\$ 90.00	\$ 90.00	T
21	REAR CHASSIS FRAME SEALANT	1	\$ 90.00	\$ 90.00	+

SUB TOTAL PRICE \$ 2,188.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	CUT OFF AND REPLACE FRONT SUPPORT PANEL. RESTRUCTURE FRONT CRASH MANAGEMENT COMPONENT AND RENEW OTHER DAMAGE PARTS.	\$ 1,600.00	<i>800</i>	
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA.	\$ 1,200.00	<i>800</i>	
3	ADJUST AND FOCUS FRONT LIGHTING SYSTEM. PERFORM HEADLAMP ADJUSTMENT TO POSITION	\$ 80.00	<i>30</i>	
4	REMOVE AND INSTALL RADIATOR ASSY. PERFORMED RADIATOR PRESSURE TEST	\$ 120.00	<i>60</i>	
5	DISMENTLE AND REPLACE A/C CONDENSER ASSY. REFILL, RECHARGE A/C REFRIGERANT GAS AND PERFORM PRESSURE TEST.	\$ 150.00	<i>60</i>	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	CUT OFF AND REPLACE REAR END PANEL, FLOOR PANEL AND REAR LHS FRAME. STRAIGHTEN, REALIGN REAR CHASSIS FRAME AND RENEW OTHER DAMAGE PARTS.	\$ 2,200.00	<i>1100</i>	
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA.	\$ 1,800.00	<i>1200</i>	

3	DISMENTLE AND INSTALL EXHAUST PIPE SYSTEM TO ENABLE REPAIRS.	\$ 120.00	X	
4	REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS. PERFORM DISTANCE SENSORY TESTING.	\$ 150.00	50.	
5	RENEW REAR FLOOR INSULATOR.	\$ 180.00	X.	
6	PERFORM REAR LIGHTING WIRING CHECK AND TEST FUCTION.	\$ 80.00	30.	
7	TRANSFER REAR RHS DOOR ATTACHMENT AND MECHANISM INTO NEW DOOR PANEL.	\$ 200.00	X	
8	REMOVE AND INSTALL REAR WINDSCREEN GLASS.	\$ 180.00	X	
9	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA.	\$ 100.00	X	
10	TRANSFER REAR BOOTLID ATTACHMENT AND MECHANISM INTO NEW TAILGATE ASSY.	\$ 200.00	X	
10	REMOVE AND INSTALL FUEL TANK AND FUEL PIPING TO ENABLE REPAIRS.	\$ 200.00	X	
10	PERFORMED DIAGNOSTIC CHECK.	\$ 150.00	X	
13	DISMENTLE AND REPLACE REAR UNDER-CARRIAGE COMPONENTS.	\$ 200.00	X	
14	WHEEL ALIGNMENT.	\$ 150.00	X	
15	DISMENTLE AND INSTALL REAR SEATS, SPEAKER BOARD AND BOOTLID TRIMMING.	\$ 200.00	60.	

TOTAL

\$ 9,260.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 25,257.85

TOTAL LABOUR COST : \$ 9,460.00

TOTAL REPAIR COST : \$ 34,717.85

34,717.85

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Nett Value : \$27K ✓

14 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Nov 2018		06 Dec 2018 13:43 Edit Adj Rpt	S\$2,700.00 Edit Estimates	S\$2,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: DNET CONTRACT SERVICES PTE LTD , Co. Reg. No.: 201305143N									
Main Claimant: ZAMBRI BIN CHUPRI , ID: S7613002G									
Vehicle Reg. No.:	SGC7256J	Date of Loss:	22/11/2018 07:00 - :59 [153 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D05506C02	Policy/Cover Note No.:	DMCVSN3029961802 (Comprehensive)						
Vehicle Reg. No. (Insured):	YN1418C	Policy No. (Claimant):	5086743067-01						
		Excess:	S\$0.00						
Repairer:	SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre, 415933 Kaki Bukit - Tel: 67895155								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 17/12/2018]								
Driver/Custodian (Insured):	RAJANGAM AYYAPPAN (35 / Male), NRIC: G2165753R, Tel: +6583023007 Email: NOEMAIL								
Adj Asg. Remarks:	NO EST, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									















































Claim Documents





*SGC7256J (SNM18D05506C02)
 [YN1418C]
 TP
 ZAMBRI BIN CHUPRI
 Nov 22 2018 7:00AM
 [DNET CONTRACT SERVICES PTE LTD]
 SK Automobile Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

















View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	22/11/18 10:32	Accident Statement	Load HTM	
2	23/11/18 12:48	Addendum Sheet	Load TIF	
3	23/11/18 12:48	Accident Statement Addm. #1	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	22/11/18 10:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	22/11/18 10:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	22/11/18 10:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	22/11/18 10:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	22/11/18 10:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	22/11/18 10:12	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/02/19 09:32	General View	Load JPG	<input checked="" type="checkbox"/>
2	28/02/19 09:32	General View	Load JPG	<input checked="" type="checkbox"/>
3	28/02/19 09:32	General View	Load JPG	<input checked="" type="checkbox"/>
4	28/02/19 09:32	General View	Load JPG	<input checked="" type="checkbox"/>
5	28/02/19 09:32	General View	Load JPG	<input checked="" type="checkbox"/>
6	28/02/19 09:32	General View	Load JPG	<input checked="" type="checkbox"/>
7	28/02/19 09:32	General View	Load JPG	<input checked="" type="checkbox"/>
8	28/02/19 09:32	General View	Load JPG	<input checked="" type="checkbox"/>
9	28/02/19 09:32	General View	Load JPG	<input checked="" type="checkbox"/>
10	28/02/19 09:32	General View	Load JPG	<input checked="" type="checkbox"/>
11	28/02/19 09:32	General View	Load JPG	<input checked="" type="checkbox"/>
12	28/02/19 09:32	General View	Load JPG	<input checked="" type="checkbox"/>
13	28/02/19 09:32	General View	Load JPG	<input checked="" type="checkbox"/>
14	28/02/19 09:32	General View	Load JPG	<input checked="" type="checkbox"/>
15	28/02/19 09:32	General View	Load JPG	<input checked="" type="checkbox"/>
16	28/02/19 09:32	General View	Load JPG	<input checked="" type="checkbox"/>
17	28/02/19 09:32	General View	Load JPG	<input checked="" type="checkbox"/>
18	28/02/19 09:32	General View	Load JPG	<input checked="" type="checkbox"/>
19	28/02/19 09:32	General View	Load JPG	<input checked="" type="checkbox"/>
20	28/02/19 09:32	General View	Load JPG	<input checked="" type="checkbox"/>
21	28/02/19 09:32	General View	Load JPG	<input checked="" type="checkbox"/>
22	28/02/19 09:32	General View	Load JPG	<input checked="" type="checkbox"/>
23	28/02/19 09:32	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
24	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
25	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
26	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
27	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
28	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
29	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
30	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
31	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
32	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
33	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
34	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
35	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
36	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
37	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
38	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
39	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
40	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
41	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
42	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
43	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
44	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
45	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
46	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
47	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
48	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
49	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
50	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
51	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
52	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
53	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
54	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
55	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
56	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
57	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
58	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
59	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
60	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
61	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
62	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
63	28/02/19 09:32	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/12/18 13:42	PRS	 Load PDF	
2	06/12/18 13:42	TP GIA	 Load PDF	
3	06/12/18 13:42	OI GIA	 Load PDF	
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	22/11/18 10:31	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	23/11/18 12:48	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
3	23/11/18 12:48	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
4	23/11/18 12:48	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
5	23/11/18 12:48	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
6	23/11/18 12:48	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
7	23/11/18 12:48	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	22/11/18 10:32	Accident Statement	 Load HTM	
2	23/11/18 12:48	Addendum Sheet	 Load TIF	
3	23/11/18 12:48	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	22/11/18 10:12	Accident Photo	 Load JPG <input checked="" type="checkbox"/>	
2	22/11/18 10:12	Accident Photo	 Load JPG <input checked="" type="checkbox"/>	
3	22/11/18 10:12	Accident Photo	 Load JPG <input checked="" type="checkbox"/>	
4	22/11/18 10:12	Accident Photo	 Load JPG <input checked="" type="checkbox"/>	
5	22/11/18 10:12	Accident Photo	 Load JPG <input checked="" type="checkbox"/>	
6	22/11/18 10:12	Accident Photo	 Load JPG <input checked="" type="checkbox"/>	
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	22/11/18 10:31	Sketch Plan	 Load TIF	
2	23/11/18 12:48	Accident Sketch Plan	 Load TIF	
3	23/11/18 12:48	Accident Sketch Plan	 Load TIF	
4	23/11/18 12:48	Accident Sketch Plan	 Load TIF	
5	23/11/18 12:48	Accident Sketch Plan	 Load TIF	
6	23/11/18 12:48	Accident Sketch Plan	 Load TIF	
7	23/11/18 12:48	Accident Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18021435/AQD3E2

Date: 04/03/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3029961802

Claimant Vehicle
No : SGC7256JInsured Vehicle
No : YN1418C

Date of Loss: 22/11/2018

Nature of Claim: TP

Claim
No: SNM18D05506C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGC7256J**

Make & Model: TOYOTA VIOS, 1.5 E (A)

Reg. Date: 27/01/2006 (Man. Year: 2005)

Colour: Black

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 1NZX366739

Chassis No: MR053HY4204171239

Odometer: 0 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50 R15

Rear Tyre Size: 195/50 R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,257.85	9,353.82	15,904.03	62.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,260.00	4,190.00	5,070.00	54.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,517.85	13,543.82	20,974.03	60.76
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	34,517.85	2,700.00	31,817.85	92.18
+ GST 7.00/7.00% (S\$)	2,416.25	189.00	2,227.25	92.18
Nett Amount (S\$)	36,934.10	2,889.00	34,045.10	92.18

INSPECTION

Date of Assignment: 06/12/2018

Date Inspected: 27/11/2018 Inspected At:

8 KAKI BUKIT AVE# 08-45 PREMIER

Repairer : SK Automobile Pte Ltd (HQ)

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$15,000.00(EST)-LTA REIMBURSEMENT VALUE: \$12,194.00=NETT VALUE: \$2,806.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Mar 2019)
Parts: 143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGC7256J)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	573.20 FL	*573.20 FL
2	1		*FRONT BUMPER TOWING COVER	Not Necessary	47.50 FL	*- FL
3	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	185.40 FL	*- FL
4	2		*FRONT BUMPER FOG LAMP GARNISH	Not Necessary	240.80 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Bent	275.60 FL	*275.60 FL
6	2		*FRONT BUMPER REINFORCEMENT MEMBER	Not Necessary	403.20 FL	*- FL
7	2		*FRONT BUMPER SIDE RETAINER	Necessary	149.20 FL	*149.20 FL
8	1		*FRONT BUMPER LOWER SPLASH SHIELD	Not Necessary	177.30 FL	*- FL
9	1		*FRONT GRILLE	Cracked	321.00 FL	*321.00 FL
10	1		*FRONT GRILLE BASE	Not Necessary	280.60 FL	*- FL
11	1		*FRONT GRILLE MOULDING	Cracked	224.70 FL	*224.70 FL
12	1		*FRONT GRILLE EMBLEM	Necessary	94.80 FL	*94.80 FL
13	1		*BONNET	Distorted	870.90 FL	*870.90 FL
14	2		*BONNET HINGES	Bent	130.00 FL	*130.00 FL
15	2		*BONNET LOCK	Damaged	360.60 FL	*360.60 FL
16	2		*FRONT FENDER	Repair	1,493.60 FL	*- FL
17	2		*FRONT FENDER EMBLEM VVTI	Necessary	155.00 FL	*155.00 FL
18	2		*FRONT FENDER INNER SHIELD	Not Necessary	335.80 FL	*- FL
19	1		*FRONT SUPPORT PANEL	Buckled	340.60 FL	*340.60 FL
20	2		*FRONT SUPPORT PANEL SIDE GUARD	Not Necessary	189.60 FL	*- FL
21	2		*HEADLAMP ASSY	Cracked	1,289.40 FL	*1,289.40 FL
22	2		*HEADLAMP UPPER BRACKET	Not Necessary	340.20 FL	*- FL
23	1		*A/C CONDENSER	Bent	887.30 FL	*887.30 FL
24	1		*A/C CONDENSER FAN COWLING	Not Necessary	240.60 FL	*- FL
25	1		*A/C CONDENSER FAN BLADE	Not Necessary	221.80 FL	*- FL
26	1		*A/C CONDENSER FAN MOTOR	Not Necessary	304.70 FL	*- FL
27	2		*A/C CONDENSER RUBBER MOUNTING	Not Necessary	35.60 FL	*- FL
28	1		*A/C CONDENSER SUCTION PIPE	Not Necessary	298.20 FL	*- FL
29	1		*A/C CONDENSER DISCHARGE PIPE	Not Necessary	321.50 FL	*- FL
30	1		*RADIATOR	Bent	1,331.20 FL	*1,331.20 FL
31	1		*RADIATOR FAN COWLING	Cracked	248.70 FL	*248.70 FL
32	1		*RADIATOR FAN BLADE	Not Necessary	226.40 FL	*- FL
33	1		*RADIATOR FAN MOTOR	Not Necessary	311.40 FL	*- FL
34	2		*RADIATOR RUBBER MOUNTING	Not Necessary	37.80 FL	*- FL
35	1		*RADIATOR RESERVE TANK	Not Necessary	86.50 FL	*- FL
36	1		*WINDSCREEN WASHER TANK	Not Necessary	214.00 FL	*- FL
37	1		*WINDSCREEN WASHER TANK MOTOR	Not Necessary	84.00 FL	*- FL
38	2		*HORN	Not Necessary	399.00 FL	*- FL
39	1		*ENGINE MOUNTING	Not Necessary	689.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR BUMPER	Distorted	547.90 FL	*547.90 FL
41	2		*REAR BUMPER REFLECTOR	Not Necessary	175.20 FL	*- FL
42	2		*REAR BUMPER SIDE RETAINER	Necessary	149.20 FL	*149.20 FL
43	2		*REAR BUMPER SIDE BRACKET	Not Necessary	130.60 FL	*- FL
44	1		*BOOTLID	Distorted	948.30 FL	*948.30 FL
45	2		*BOOTLID HINGE	Bent	130.00 FL	*130.00 FL
46	1		*BOOTLID OUTER MOULDING	Deformed	188.30 FL	*188.30 FL
47	1		*BOOTLID CYLINDER LOCK	Not Necessary	101.70 FL	*- FL
48	1		*BOOTLID EMBLEM	Necessary	94.80 FL	*94.80 FL
49	1		*BOOTLID EMBLEM VIOS	Necessary	84.60 FL	*84.60 FL
50	1		*BOOTLID EMBLEM E	Necessary	74.60 FL	*74.60 FL
51	1		*BOOTLID WEATHERSTRIP	Cut	175.00 FL	*175.00 FL
52	1		*BOOTLID INNER LOCK	Jammed	256.40 FL	*256.40 FL
53	1		*BOOTLID STRIKER	Bent	34.20 FL	*34.20 FL
54	2		*REAR FENDER	Repair	1,949.20 FL	*- FL
55	2		*REAR FENDER INNER WHEELHOUSE RH	Repair	2,249.20 FL	*- FL
56	2		*REAR FENDER AIR VENT RH	Not Necessary	350.60 FL	*- FL
57	1		*REAR WINDSCREEN RUBBER MOULDING	Not Necessary	175.90 FL	*- FL
58	1		*REAR DOOR RH	Repair	697.30 FL	*- FL
59	1		*REAR DOOR BLACK STICKER RH	Not Necessary	28.50 FL	*- FL
60	1		*REAR END PANEL	Distorted	455.60 FL	*455.60 FL
61	1		*REAR END PANEL TOP GARNISH	Deformed	285.70 FL	*285.70 FL
62	1		*REAR FLOOR PANEL	Repair	863.10 FL	*- FL
63	1		*REAR FLOOR PANEL TOP BOARD	Torn	332.30 FL	*332.30 FL
64	1		*REAR FRAME CHASSIS RH	Repair	1,845.00 FL	*- FL
65	2		*REAR FENDER SIDE INNER TRIM	Not Necessary	1,121.80 FL	*- FL
66	2		*REAR WHEELHOUSE LINER	Not Necessary	368.60 FL	*- FL
67	2		*TAILLAMP	Cracked	914.60 FL	*914.60 FL
68	2		*TAILLAMP PANEL	Dented	281.40 FL	*281.40 FL
69	1		*EXHAUST PIPE SILENCER	Not Necessary	466.90 FL	*- FL
70	1		*EXHAUST PIPE CENTER PIPE	Not Necessary	647.30 FL	*- FL
71	1		*EXHAUST PIPE HEAT SHIELD	Not Necessary	155.30 FL	*- FL
72	2		*EXHAUST MOUNTING	Not Necessary	64.00 FL	*- FL
73	1		*FRONT NUMBER PLATE WITH CASING	Cracked	50.00 FS	*50.00 FS
74	1		*SET FRONT BUMPER CLIP	Necessary	70.00 FS	*30.00 FS
75	1		*SET FRONT BUMPER LOWER GRILLE CLIP	Not Necessary	38.00 FS	*- FS
76	1		*SET FRONT GRILLE CLIP	Necessary	38.00 FS	*10.00 FS
77	2		*BONNET LABEL	Not Necessary	30.00 FS	*- FS
78	1		*RADIATOR COOLANT (3PCS)	Necessary	75.00 FS	*40.00 FS
79	1		*REAR NUMBER PLATE WITH CASING	Cracked	50.00 FS	*30.00 FS
80	1		*SET REAR BUMPER CLIP	Necessary	65.00 FS	*30.00 FS
81	1		*BOOTLID SEALANT	Not Necessary	80.00 FS	*- FS
82	1		*SET BOOTLID INNER TRIM CLIP	Not Necessary	65.00 FS	*- FS
83	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	45.00 FS	*10.00 FS
84	1		*SET REAR FENDER SIDE INNER TRIM CLIP	Not Necessary	90.00 FS	*- FS
85	1		*SET REAR WHEELHOUSE LINER CLIP	Not Necessary	90.00 FS	*- FS
86	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	110.00 FS	*- FS
87	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
88	2		*REAR FENDER SEALANT	Not Necessary	602.00 FS	*- FS
89	1		*REAR END PANEL SEALANT	Not Necessary	90.00 FS	*- FS
90	1		*REAR FLOOR PANEL SEALANT	Not Necessary	90.00 FS	*- FS
91	1		*REAR FLOOR PANEL INSULATOR	Not Necessary	250.00 FS	*- FS
92	1		*REAR TAILLAMP PANEL SEALANT	Not Necessary	90.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
93	1		*REAR CHASSIS FRAME SEALANT	Not Necessary	90.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					32,947.80	12,405.10
- List Item Discount on L Items 25.00/25.00% (S\$)					7,689.95	3,051.28
Total Parts (S\$)					25,257.85	9,353.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT OFF AND REPLACE FRONT SUPPORT PANEL. RESTRUCTURE FRONT CRASH MANAGEMENT COMPONENT AND RENEW OTHER DAMAGE PARTS	New	1,600.00	800.00
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA	New	1,200.00	800.00
3	ADJUST AND FOCUS FRONT LIGHTING SYSTEM. PERFORM HEADLAMP ADJUSTMENT TO POSITION	New	80.00	30.00
4	REMOVE AND INSTALL RADIATOR ASSY. PERFORMED RADIATOR PRESSURE TEST	New	120.00	60.00
5	DISMENTLE AND REPLACE A/C CONDENSER ASSY. REFILL, RECHARGE A/C REFRIGERANT GAS AND PERFORM PRESSURE TEST	New	150.00	60.00
6	CUT OFF AND REPLACE REAR END PANEL, FLOOR PANEL AND REAR LHS FRAME, STRAIGHTEN, REALIGN REAR CHASSIS FRAME AND RENEW OTHER DAMAGE PARTS	New	2,200.00	1,100.00
7	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA	New	1,800.00	1,200.00
8	DISMENTLE AND INSTALL EXHAUST PIPE SYSTEM TO ENABLE REPAIRS	New	120.00	0.00
9	REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS. PERFORM DISTANCE SENSORY TESTING	New	150.00	50.00
10	RENEW REAR FLOOR INSULATOR	New	180.00	0.00
11	PERFORM REAR LIGHTING WIRING CHECK AND TEST FUCTION	New	80.00	30.00
12	TRANSFER REAR RHS DOOR ATTACHMENT AND MECHANISM INTO NEW DOOR PANEL	New	200.00	0.00
13	REMOVE AND INSTALL REAR WINDSCREEN GLASS	New	180.00	0.00
14	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA	New	100.00	0.00
15	TRANSFER REAR BOOTLID ATTACHMENT AND MECHANISM INTO NEW TAILGATE ASSY	New	200.00	0.00
16	REMOVE AND INSTALL FUEL TANK AND FUEL PIPING TO ENABLE REPAIRS	New	200.00	0.00
17	PERFORMED DIAGNOSTIC CHECK	New	150.00	0.00
18	DISMENTLE AND REPLACE REAR UNDER-CARRIAGE COMPONENTS	New	200.00	0.00
19	WHEEL ALIGNMENT	New	150.00	0.00
20	DISMENTLE AND INSTALL REAR SEATS, SPEAKER BOARD AND BOOTLID TRIMMING	New	200.00	60.00
Gross Labour Cost (\$\$)			9,260.00	4,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >