

A9S REC. BY:

REF:

09/FCI/8021437/179d3/72

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person): Eileen Lee

of

FCI

Date/Time: 12.17pm @ 24/11/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMD 922P

Insured:

SHC30885

at Workshop m/s

BW Workshop

Tel:

66920125

of

30 ubi Rd 4

Policy No:

Claim No:

D18008284MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/11/2018

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement:

Date/Time: 1.33pm @ 27/11/18

Person Contacted:

Sya Lirah

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SMD 922P - X

SHC30885-NA/MSG/3019265/m2

D.O.A. 16/10/13

03/12/18 @ 2.54pm Informed Eileen Lee by email, we are pending estimate from repairer.

28/12/18 @ 4.53pm revised to Eileen Lee by email.

LS \$1850, 5 days (Fed \$4697.70, 72%).

REF: FCI

ASSIGNMENT

From: Date: 30/11/18

Estimated Cost:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMD922P

at Workshop m/s: BW Workshop
30 ubi Road 4

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: 11am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (DS)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMD922P Yr Regn: 2018 July.

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Freed Hybrid c.c 1496

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 6856 T/Radio: Insured / Std / NI / NA

Eng/No:

Ci/No: 6BT1068915

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ Rim / STD A/Rim or

Tyre Size: F: 185/65 R15

R: 185/65 R15

BS / ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.I. 30/11/18

Survey held at: BW.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cap.

RECEIVED 31 DEC 2018

Date/Time, File Pass to?

1) 28/12 2018 ☐ : Preli. Report

Date/Time, File Return to?

2) ☐ : Final Report

Report Format:

Lump Sum / I.B.I: (\$) 7P 1850

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation

) \$ + RS. \$

) Photos

) Others

TOTAL

145
50
50
19
264



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008284MFSH

Date: 28 December 2018

Our Ref: CS/FCI18021437/Aqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMD 922P

Please be informed that we had conducted the inspection of the abovementioned vehicle on 30/11/2018 at the premises of M/s BW WORKSHOP, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>6,547.20</u>
Revised Estimate Amount	: S\$ <u>1,850.00 (Lump Sum)</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	21-11-2018	Our Ref No. D18008284MFSH
Accident Date	20-11-2018	Claim Type. Third Party
Insured Vehicle	SHC3088S	Third Party Vehicle. SMD922P
Survey Location	30 UBI ROAD 4	
Contact Person.	NUR SYAFIRAH	
Contact No.	62920125/ 62920125	Fax No. 68582120
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	BW WORKSHOP SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 28 December 2018 4:53 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008284MFSH/1
Attachments: CSFCI18021437Aqd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SMD 922P.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Monday, 3 December 2018 2:54 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008284MFSH/1

Dear Eileen,

Please be informed that we have inspected the vehicle SMD 922P.

We are pending estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 27 November 2018 3:02 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008284MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 3 December 2018 2:54 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008284MFSH/1

Dear Eileen,

Please be informed that we have inspected the vehicle SMD 922P.

We are pending estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 27 November 2018 3:02 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008284MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 27 November 2018 12:17 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008284MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

BW WORKSHOP SERVICES PTE LTD

30 UBI ROAD 4 SINGAPORE 408615

TEL: 62898800 FAX: 68582120

GST REG NO. 201504834E

QUOTATION

MS First Capital Insurance Limited
THIRD PARTY CLAIM: SHC3088S
DATE OF ACCIDENT: 20.11.18

NO. : 18110004
CURRENCY : \$
PAGE :
DATE : 30/11/2018

Xiao Chen

QTY	DESCRIPTION	VEH NO.	
		SMD922P HONDA FREED	
		Unit Price	AMOUNT
1PC	REAR BUMPER <i>Defend</i>		\$ 1,150.00
10PCS	REAR BUMPER CLIP <i>per</i>	\$ 4.50	\$ 45.00
2PCS	REAR BUMPER SIDE HOLDER LH & RH(SLEEP) <i>LH Dmg</i>	\$ 30.00	\$ 60.00
1SET	REAR BUMPER PARKING SENSOR <i>Damaged</i>		\$ 250.00
1PC	REAR BUMPER SPLASH GUARD LH <i>LH Dmg</i>		\$ 85.00
1PC	REAR AIR GUARD LH <i>Crushed</i>		\$ 45.00
2PCS	REAR BUMPER SIDE RETAINER LH & RH <i>LH Dmg</i>	\$ 24.00	\$ 48.00
1PC	REAR BOOT LAMP RH <i>LH Dmg</i>		\$ 360.00
1PC	REAR BRAKE LAMP RH <i>for new</i>		\$ 580.00
1PC	REAR BOOT INNER TRIM <i>3 new</i>		\$ 168.00
10PCS	REAR BOOT INNER TRIM CLIP <i>3 new</i>	\$ 4.50	\$ 45.00
1PC	REAR END PANEL <i>Repair</i>		\$ 623.00
1SET	REAR SPORT RIM <i>new</i>		\$ 650.00

TOTAL	4,109.00
LABOUR CHARGE	3,260.00
DISCOUNT (only Parts)	20%
TOTAL:	6,547.20
GST 7%	458.30
TOTAL	7,005.50

1279 S.N: 200
102320

LABOUR:

- 1 TO CUT & WELD REAR END PANEL ,PULLING CHASSIS MEMBER AND REPAIR THE ACCIDENT PORTION -~~\$1500.00~~ 400
- 2 TO RESPRAY PAINT ON ACCIDENT PORTION (LOWER PANEL, END PANEL, SIDE FENDER, BUMPER) -~~\$1000.00~~ 600
- 3 TO TUFF-KOTE -~~\$180.00~~
- 4 TO REMOVE & REFIX REAR BOOT GARNISH, BOOT INNER TRIM AND BUMPER GARNISH -~~\$150.00~~ 80
- 5 WHEEL ALIGNMENT -~~\$00~~
- 6 TO REMOVE & RERIX REAR LH & RH SIDE FENDER INNER COVER -~~\$250.00~~ 80
- 7 TO REPLACE PARKING SENSOR -~~\$100.00~~ 1130

05 days.

total: 2353.20

1/2: 1850.

LIK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

INSURANCE SURVEYOR DETAIL		INSURANCE SURVEYOR DETAIL	
FULL NAME	Adrian Lj	FULL NAME	
EMAIL ADDRESS		EMAIL ADDRESS	
CONTACT NUMBER	9689375	CONTACT NUMBER	
REMARKS		REMARKS	
DATE		DATE	
30/11/18			
SIGNATURE		SIGNATURE	
H.S.			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18021437/Aqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 02-01-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3088S	Veh. Inspected	SMD 922P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008284MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	27/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FREED HYBRID	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	GB71068915	Colour	BLUE	
Odometer	6856	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	DUNLOP	6 mm	
L/H Front Tyre	185/65 R15	DUNLOP	6 mm	
R/H Rear Tyre	185/65 R15	DUNLOP	6 mm	
L/H Rear Tyre	185/65 R15	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/11/2018	Inspection Date	30/11/2018	
Survey held at	BW WORKSHOP SERVICES PTE LTD 30 UBI ROAD 4 SINGAPORE 408615			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 922P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	1,150.00	1,150.00
10	REAR BUMPER CLIP @\$4.50	NECESSARY	45.00	30.00
2	REAR BUMPER SIDE HOLDER LH & RH (SLEEP) @\$30.00	N/S DAMAGED	60.00	30.00
1	REAR BUMPER SPLASH GUARD LH	NOT NECESSARY	85.00	-
1	REAR AIR GUARD LH	CRACKED	45.00	45.00
2	REAR BUMPER SIDE RETAINER LH & RH @\$24.00	N/S DAMAGED	48.00	24.00
1	REAR BOOT LAMP RH	NOT NECESSARY	360.00	-
1	REAR BRAKE LAMP RH	NOT NECESSARY	580.00	-
1	REAR BOOT INNER TRIM	NOT NECESSARY	168.00	-
10	REAR BOOT INNER TRIM CLIP @\$4.50	NOT NECESSARY	45.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	623.00	-
1	SET REAR SPORT RIM	NOT NECESSARY	650.00	-
	LESS 20% DISCOUNT		-771.80	-255.80
			3,087.20	1,023.20
1	SET REAR BUMPER PARKING SENSOR (SN)	DAMAGED	250.00	200.00
	LESS 20% DISCOUNT		-50.00	-
			200.00	200.00
LABOUR				
	TO CUT & WELD REAR END PANEL,PULLING CHASSIS MEMBER AND REPAIR THE ACCIDENT PORTION.		1,500.00	400.00
	TO RESPRAY PAINT ON ACCIDENT PORTION. (LOWER PANEL,END PANEL,SIDE FENDER,BUMPER).		1,000.00	600.00
	TO TUFF KOTE.	NOT NECESSARY	180.00	-
	TO REMOVE & REFIX REAR BOOT,GARNISH,BOOT INNER TRIM AND BUMPER GARNISH.	NOT NECESSARY	150.00	-
	WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO REMOVE & REFIX REAR LH & RH SIDE FENDER INNER COVER.		250.00	80.00

Report Ref No. CS/FC118021437/Aqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE PARKING SENSOR.		100.00	50.00
			3,260.00	1,130.00
GRAND TOTAL			6,547.20	2,353.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,850.00

Report Ref No. CS/FCI18021437/Aqd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.