



Case Details

Case Reference Number : TAX/11/18/2090
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB765X

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-4635-ID
 Assigned By : B. Thaiyal Nayagi

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 20/11/2018 12:08 PM
 Vehicle Age(In Months) : 47

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval		
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	0	Repair ▾
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	0	0	Not Give ▾
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check ▾
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check ▾
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check ▾
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Check ▾
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Check ▾
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ▾

Total Spare Part Cost 1,475.24

Lump Sum Discount (%) 20.00

Final Spare Part Cost 1,180.19

Surveyor Total 120.00

Lump Sum Dis (%) 20

Final Sur Total 96.00

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Check ▾
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give ▾
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give ▾
Total Spare Part Cost									1,475.24		Surveyor Total	120.00	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	20	
Final Spare Part Cost									1,180.19		Final Sur Total	96.00	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR REAR PORTION	338.00	150	
Total:		338.00	150.00	


Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY REAR BUMPER	378.00	200	
2	TO RESPRAY BUMPER BEAM	180.00	0	
Total:		558.00	200.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
2	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	60	
3	TO WASH AND VACUUM	60.00	0	
Total:		260.00	60.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	1,180.19	96.00
Total Labour Cost	338.00	150.00
Total Spray Painting	558.00	200.00
Other	260.00	60.00
Overall Total	2,336.19	506.00
Lump Sum Repair Option	☒	☐
Lump Sum Total	2,350.00	506.00
Surveyor Approved Amount		506.00
No of Repair Days*	3	2
Remarks	-	resurvey after repair / lump sum
Surveyor Name		Rasul
Signature		
Survey Date	Save Clear 26/11/2018	