

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 722Z**AAD1811-242***Not Authored
C/Sing B*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 722Z

VF1ABL15AUC281261

RENAULT

LATITUDE

23.11.2018

AIG**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Bt</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>Bt 10.11</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sm</i> 113.47	X
4	1 BUMPR BRACKET SIDE RH REAR	\$	<i>Sm</i> 135.97	X
5	1 BUMPR RETAINER RH REAR	\$	<i>Sm</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>Sm</i> 43.61	X
7	1 BUMPR BRACKET SIDE LH REAR	\$	<i>Dis</i> 135.97	✓
8	1 BUMPR RETAINER LH REAR	\$	<i>Dis</i> 44.99	✓
9	1 BUMPER REFLECTOR LH	\$	<i>Bt</i> 43.61	✓
10	1 BUMPER BEAM REAR	\$	<i>Bt</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>Bt</i> 225.95	✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	X
13	1 BOOT REAR	\$	<i>Bt</i> 2,872.68	✓
14	1 BOOT FINISHER	\$	<i>Sm</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$	<i>Dis 10.11</i> 323.05	✓
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Dis</i> 493.35	✓
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sm</i> 493.35	X
18	1 BOOT BADGE 'RENAULT'	\$	<i>Sm</i> 225.36	✓
19	1 BOOT BADGE	\$	<i>Sm</i> 225.36	✓
20	1 BOOT STRUT LH	\$	<i>Sm</i> 276.08	} X
21	1 BOOT STRUT RH	\$	<i>Sm</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>Sm</i> 586.45	
25	1 BOOT SWITCH	\$	<i>Sm</i> 168.13	
26	1 BOOT LOCK	\$	<i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	
28	2 LICENCE PLATE LAMP	\$	<i>Sm</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>Sm</i> 221.81	

Trans-cab Auto Services Pte Ltd

AAD1811-242

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 722Z

30	1 FENDER PANEL REAR LH	\$	Bu 3,299.13 ✓
31	1 WHEELARCH REAR LH	\$	Sn 543.47 X
32	1 FENDER PANEL INNER TRIM REAR LH	\$	Sn 671.45 X
33	1 FUEL FLAG	\$	Sn 343.57 X
34	1 WHEEL HOUSING PANEL REAR LH	\$	R 4,682.09 X
35	1 CHASSIS PANEL REAR LH L70Y	\$	R 3,766.43 X
36	1 TAILLAMP LH	\$	CM 552.55 ✓
37	1 TAILLAMP PANEL LH	\$	R 986.70 X
38	1 TAILLAMP RH	\$	Bu 552.55 X
39	1 TAILLAMP PANEL RH	\$	R 986.70 X
40	1 OUTER PANEL REAR (End Panel)	\$	Bu 1,471.77 ✓
41	1 OUTER PANEL REAR (End Panel)TRIM	\$	Diy 404.56 ✓
42	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	Bu/Bu 2,189.88 ✓
43	1 SPARE WHEEL PANEL TRIM	\$	Sn 612.21 X
44	1 EXHAUST REAR	\$	R 7,489.05 X
45	1 EXHAUST CAP REAR	\$	R 230.49 X

TOTAL	\$	40,146.98
10%	\$	4,014.70
	\$	36,132.28

Specical Nett

1	1SET PARKING AID	\$	Short 700.00 Goosa
2	1SET REAR BUMPER CLIP	\$	na 66.00 —
3	1SET BUMPER BRACKET CTR CLIP	\$	na 33.00 —
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na 10.00 X
5	1SET BUMPR RETAINER RH CLIP RR	\$	na 20.00 X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na 10.00 X
7	1SET BUMPR RETAINER CLIP LH RR	\$	na 20.00 X
8	1SET BUMPER LOWER REAR RIVET	\$	na 22.00 X
9	1SET BUMPER LOWER REAR CLIP	\$	na 66.00 ✓
10	1 EXHAUST MOUNTING REAR	\$	Sn 17.82 X
11	1SET BOOT FINISHER CLIP	\$	na 24.20 X
12	1 BOOT STICKER "Trans-cab"	\$	na 30.00 —
13	1 BOOT STICKER "6555-3333"	\$	na 30.00 —
14	1 BOOT INNER TRIM CLIP	\$	na 45.00 X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na 35.00 X
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na 35.00 X

Trans-cab Auto Services Pte Ltd

AAD1811-242

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 722Z

17	1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i> 28.00 X
18	1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i> 28.00 X
19	1 TAILLAMP CLIP RH	\$	<i>nn</i> 5.00 X
20	1 TAILLAMP CLIP LH	\$	<i>nn</i> 5.00 —
21	2 REAR WINDSCREEN SELANT	\$	<i>nn</i> 80.00 <i>60sn</i>
22	1 WINDSCREEN MOULDING	\$	<i>nn</i> 100.00 —
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00 <i>30sn</i>
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>sn</i> 385.00 X
25	1 SPARE TYRE	\$	<i>sn</i> 330.00 X

TOTAL \$ 2,225.02

TOTAL PARTS \$ 38,357.30**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 <i>1100</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00 <i>1800</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>120</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>60</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>60</i>
To repair and realign rear exhaust pipe.	\$	170.00
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 } <i>60</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 <i>100</i>

Trans-cab Auto Services Pte Ltd**AAD1811-242**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 722Z

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$		380.00	801
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn	380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$		170.00	1201
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	nn	380.00	X

TOTAL \$ 14,340.00**Over All Total \$ 52,697.30****(LUMP SUM)****Repair Days****20 DAYS****15 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: