

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way,

AIG Building #09-16

Singapore 079120

Attn: Motor Claims Department

Date : 27/11/2018

Vehicle No : SLQ5983Z

Veh Make/Model : Toyota Prius Hybrid 1.8S

YOM : 2017

Chassis No : ZVW506080977

Date of Accident : 26/11/2018

No	Qty	Description	Amount \$
List Items:-			
1	1	Bonnet	\$ 519.70
2	1	LH head lamp	\$ 1,850.60
3	1	RH head lamp	\$ 1,850.60
4	1	Front badge	\$ 129.70
5	1	Front grille (top)	\$ 260.80
6	1	Front grille (bottom)	\$ 149.70
7	1	Front bumper	\$ 419.80
8	1	Front bumper center seal	\$ 68.90
9	1	Front bumper number plate garnish	\$ 140.60
10	1	Front bumper sponge (top)	\$ 89.80
11	1	Front bumper sponge (bottom)	\$ 120.60
12	1	Front bumper reinforcement	\$ 468.70
13	2	Front bumper side retainer	\$ 159.60
14	1	Front bumper under cover	\$ 240.60
15	1	Support panel	\$ 1,280.60
16	1	Air-con condenser	\$ 1,080.60
17	1	Rear boot lid	\$ 1,050.45
18	1	Rear boot lid windscreen glass moulding	\$ 250.60
19	1	Rear boot lid cover (bottom)	\$ 850.60
20	1	Rear boot lid logo	\$ 79.80
21	1	Rear boot lid "hybrid" emblem	\$ 80.40
22	1	Rear boot lid "PRIUS" emblem	\$ 80.40
23	2	Rear boot lid stopper	\$ 99.40
24	1	Rear boot lid lock	\$ 410.60
25	1	Rear boot lid weatherstrip	\$ 269.70
26	2	Rear boot lid number plate lamp	\$ 481.20
27	1	LH Tail lamp	\$ 339.60
28	1	RH Tail lamp	\$ 339.60
29	1	Rear bumper	\$ 389.60
30	1	Rear bumper lid	\$ 340.60
Balance b/f			\$ 13,893.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way,
AIG Building #09-16
Singapore 079120
Attn: Motor Claims Department

Date : 27/11/2018
Vehicle No : SLQ5983Z
Veh Make/Model : Toyota Prius Hybrid 1.8S
YOM : 2017
Chassis No : ZVW506080977
Date of Accident : 26/11/2018

No	Qty	Description	Amount \$
		Balance c/f	\$ 13,893.45
31	1	Rear bumper reflector (LH)	\$ Sen 389.50
32	1	Rear bumper reflector (RH)	\$ Sen 389.50
33	1	Rear bumper tow cover	\$ Mi'l 60.80
34	2	Rear bumper side retainer	\$ 221.60
35	1	Rear bumper reinforcement	\$ 280.60
36	1	End panel	\$ 419.70
37	1	End panel top garnish	\$ Sen 210.80
38	6	End panel top garnish clip	\$ Nw 88.80
		Total - List Item	\$ 15,954.75
		Less 25%	\$ 3,988.69
		Total	\$ 11,966.06
		Special Nett Items:-	
1	1	Front number plate with holder	\$ CDA 55.00
2	1	Rear number plate with holder	\$ Sen 55.00
3	2	Rear reverse sensor	\$ Del 721.40
4	10	Front bumper clips	\$ Mc 100.40
5	10	Rear bumper clip	\$ M 96.00
6	1	Rear windscreen glass gum/sealant	\$ Nw 80.00
7	1	Rear boot lid compartment sealant	\$ Nw 150.00
		Total - SN Item	\$ 1,257.80
Balance b/f			\$ 13,223.86

