



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

Page 1 / 2
CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

SELVARANI D/O VEERAPPAN
BLK 405 BUKIT BATOK WEST AVENUE 7 #03-02
SINGAPORE 650405
NGANAWEAL

Attention : Motor Claim Department

Contact : 96842907

Estimate : ES003334

Date : 27/11/2018
Vehicle Num. : SJP3167E
Make/Model : MAZDA 3 SP
Chassis/Eng# : JM6BK106280449609
Accident Date : 26/11/2018
Claim No. :
Reference : TP NTUC VS III
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	BOOTLID LOGO		42.50
2.	1	BOOTLID EMBLEM 'MAZDA 3'		47.50
3.	1	REAR BUMPER		685.00
4.	1	REAR BUMPER SIDE RETAINER		32.50
5.	1	RH REAR FENDER UNDERSHIELD		55.00
6.	1	REAR END PANEL		401.00
7.	1	BOOTLID EMBLEM SP		50.00
8.	1	RH REAR FENDER AIRDUCT		58.20
List TotalS\$:				1,371.70
20.00% Discount S\$:				274.34
				1,097.36
SPECIAL NETT ITEMS :				
1.	1	RH TAILLAMP		65.00
2.	1	REAR NUMBER PLATE		40.00
3.	1	REVERSE SENSOR		200.00
4.	1	RH REAR BUMPER SPOILER		650.00
Special Nett Total S\$:				955.00
LABOUR :				
TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING				100.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ▪ No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

SELVARANI D/O VEERAPPAN
BLK 405 BUKIT BATOK WEST AVENUE 7 #03-02
SINGAPORE 650405
NGANAVAL

Attention : Motor Claim Department
Contact : 96842907

Page 2 / 2
FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES003334

Date : 27/11/2018
Vehicle Num. : SJP3167E
Make/Model : MAZDA 3 SP
Chassis/Eng# : JM6BK106280449609
Accident Date : 26/11/2018
Claim No. :
Reference : TP NTUC VS III
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER		900.00
		TO RUST PROOF ON ACCIDENT DAMAGED PARTS		150.00
		TO CUT OUT REWELD REAR END PANEL, REPAIR RH REAR FENDER		
		INNER, REAR CHASSIS INCLUDES KNOCKING & REPLACEMENT		
		OF PARTS		700.00
		Labour Total S\$:		1,850.00



E. & O.E.

Total S\$: 3,902.36

for FALCON AIR AUTO SERVICES PTE LTD

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ■ No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

11/27/2018

Insurance Particulars Enquiry By Agents Detail

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SH9563R	26 Nov 2018 / 13:50:00	Successful	105	INDIA INT'L INS PTE LTD

[Previous](#)[OK](#)

Thank you

Ng Jacqueline has successfully logged out.

Your last login date and time was 27 Nov 2018, 09:35:15.

To return to ONE.MOTORING, please [click here](#)For security reasons, please **CLEAR YOUR CACHE** after each session.**Session Transaction History**

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(\$)	Log Date/Time
1	Vehicle	SH9563R	-	18.32 Insurance Enquiry (GIRO Payment)	7.49	27 Nov 2018 / 09:36:11