

FALCON-AIR AUTO SERVICES PTE LTDCO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D**FALCON-AIR**SELVARANI D/O VEERAPPAN
BLK 405 BUKIT BATOK WEST AVENUE 7 #03-02
SINGAPORE 650405
NGANAVEAL

Attention : Motor Claim Department

Contact : 96842907

Estimate : ES003334

Date : 27/11/2018
Vehicle Num. : SJP3167E
Make/Model : MAZDA 3 SP
Chassis/Eng# : JM6BK106280449609
Accident Date : 26/11/2018
Claim No. :
Reference : TP NTUC VS III
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	BOOTLID LOGO <i>NE</i>		42.50
2.	1	BOOTLID EMBLEM 'MAZDA 3' <i>NE</i>		47.50
3.	1	REAR BUMPER <i>DE</i>		685.00
4.	1	REAR BUMPER SIDE RETAINER <i>NE</i>		32.50
5.	1	RH REAR FENDER UNDERSHIELD <i>DE</i>		55.00
6.	1	REAR END PANEL <i>BI</i>		401.00
7.	1	BOOTLID EMBLEM SP <i>NE</i>		50.00
8.	1	RH REAR FENDER AIRDUCT		58.20

List TotalS\$:	1,371.70
20.00% Discount S\$:	274.34

1,097.36

SPECIAL NETT ITEMS :				
1.	1	RH TAILLAMP	65.00	<i>? price</i>
2.	1	REAR NUMBER PLATE <i>CRA</i>	40.00	
3.	1	REVERSE SENSOR <i>NE</i>	200.00	
4.	1	RH REAR BUMPER SPOILER <i>DE</i>	650.00	<i>? price</i>

Special Nett Total S\$:	955.00
--------------------------	--------

LABOUR :
TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING100.00 *40*

CONTINUE / ...


FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

SELVARANI D/O VEERAPPAN
BLK 405 BUKIT BATOK WEST AVENUE 7 #03-02
SINGAPORE 650405
NGANAVEAL

Attention : Motor Claim Department

Contact : 96842907

Estimate : ES003334

Date : 27/11/2018
Vehicle Num. : SJP3167E
Make/Model : MAZDA 3 SP
Chassis/Eng# : JM6BK106280449609
Accident Date : 26/11/2018
Claim No. :
Reference : TP NTUC VS III
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER
TO RUST PROOF ON ACCIDENT DAMAGED PARTS
TO CUT OUT REWELD REAR END PANEL, REPAIR RH REAR FENDER
INNER, REAR CHASSIS INCLUDES KNOCKING & REPLACEMENT
OF PARTS

800 ~~980.00~~80 ~~150.00~~600 ~~700.00~~

Labour Total S\$:

1,850.00

Issue
Hp 9000068
6 days
4/5
29/11/18 @ 1000hrs
Reg after repair

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: E. & O.E.

Total S\$: 3,902.36



for FALCON AIR AUTO SERVICES PTE LTD

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg