



Co. Reg: 200922097K GST Reg.No: 200922097K  
 Auto Bay @ Kaki Bukit Bldg 1 Area "D" Kaki Bukit Ave 6 #01-90 (S) 417883  
 • Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

Date: 27/11/2018

Total Pages: 2

TO: INDIA INTERNATIONAL INSURANCE PTE LTD  
 64 Cecil Street  
 #04/#05 IOB Building  
 Singapore 049711

*Ashes*

Our Customer: ENERGY PIPELINE SERVICES PTE LTD

Vehicle No: SKE3678T

Model: Toyota Corolla Altis 1.6

Manufacture Year: 2011

Date of Accident: 21/11/2018

Total Estimate Repair Days: 10

Attn: Motor Claim Department  
 Fax: 62244174

*MROS3REF104127644*

Re: Repair Estimate For Third Party Claim against: SHA7081U

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
<b>A. Spare Parts</b>					
1	Rear number plate <i>new</i>	1	\$50.00	\$50.00	+
2	Rear bumper <i>new</i>	1	\$650.20	\$650.20	✓ <i>493.60</i>
3	Rear bumper clips <i>new</i>	10	\$3.50	\$35.00	✓
4	Rear bumper retainer <i>new</i>	2	\$85.10	\$170.20	✓
5	Trunk lid <i>new</i>	1	\$690.50	\$690.50	✓
6	Trunk lid hinges <i>new</i>	2	\$110.50	\$221.00	+
7	Trunk lid lock <i>new</i>	1	\$98.20	\$98.20	✓
8	RH trunk lid lamp <i>new</i>	1	\$455.90	\$455.90	+
9	LH trunk lid lamp <i>new</i>	1	\$455.90	\$455.90	+
10	Trunk lid lock stricker <i>new</i>	1	\$45.10	\$45.10	+
11	Rear bumper parking sensor <i>new</i>	1	\$280.00	\$280.00	✓ <i>200 (SW)</i>
12	Trunk lid "DUAL" badge <i>new</i>	1	\$48.10	\$48.10	✓
13	1.6 emblem <i>new</i>	1	\$28.10	\$28.10	✓
14	VVT-I emblem <i>new</i>	1	\$39.20	\$39.20	✓
15	Trunk lid logo <i>new</i>	1	\$79.50	\$79.50	✓
16	Trunk lid "Corolla" emblem <i>new</i>	1	\$81.20	\$81.20	✓
17	Trunk lid "Altis" emblem <i>new</i>	1	\$81.20	\$81.20	✓
18	Trunk lid weatherstrip <i>new</i>	1	\$350.50	\$350.50	✓
19	Rear end panel <i>new</i>	1	\$610.20	\$610.20	✓
20	Rear end panel inner garnish <i>new</i>	1	\$210.50	\$210.50	✓
21	Rear bumper reflector <i>new</i>	2	\$58.10	\$116.20	+
22	RH taillamp <i>new</i>	1	\$519.10	\$519.10	✓ <i>374.50</i>
23	RH taillamp retainer <i>new</i>	1	\$28.20	\$28.20	+
24	LH taillamp <i>new</i>	1	\$519.10	\$519.10	✓ <i>374.50</i>
25	LH taillamp retainer <i>new</i>	1	\$28.20	\$28.20	+
26	Engine lower cross member <i>new</i>	1	\$310.20	\$310.20	✓
27	Front engine lower mounting <i>new</i>	1	\$395.20	\$395.20	✓
28	Rear bumper sponge <i>new</i>	1	\$138.50	\$138.50	✓
	<i>Rear Bumper Impact Bracket RH 85</i>				
	<i>spare tyre Top Board Best</i>				
				<b>Sub Total</b>	<b>\$6,735.20</b>
				Less 25%	\$1,683.80
				<b>Sub-Total 1</b>	<b>\$5,051.40</b>
<b>A. Spare Parts (S/Nett)</b>					
1	Sealant <i>new</i>	2	\$25.00	\$50.00	✓
				<b>Sub-Total 2</b>	<b>\$50.00</b>
				<b>Total Spare Parts</b>	<b>\$5,101.40</b>
<b>B. Labour</b>					
1	To knock and straighten both rear fender and spare tyre compartment. Cut & weld damaged panel, adjust and realign			\$1,300.00	800
2	To putty and spray RH & LH rear fender, rear end panel, spare tyre compartment, trunk lid assembly and rear bumper			\$1,200.00	800

*4198.50*  
*3146.25*  
*S.N: 200*

*25*

*spare tyre top board best new new x*



Co. Reg. No: 200922097K GST Reg. No: 200922097K  
 Auto Repair Centre Kaki Bukit Blk 1 Area "D" Kaki Bukit Ave 6 #01-90 (S) 417882  
 • Tel: 6516555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

3	To rust proof the affected areas	<del>\$80.00</del>	50
4	To transfer trunk lid fitting & fixtures. To conduct water seepage test	<del>\$180.00</del>	80
5	To check wiring and all lighting	<del>\$60.00</del>	30
<b>Total Labour</b>		<b>\$2,820.00</b>	
(* The above quoted are exclusive of GST.) <b>Total Repair Cost</b>		<b>\$7,921.40</b>	

1760

Yours faithfully,

Darla  
 f Auto N Cars Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No
Signature	

DATE	Remark From MR CHOO
27/11/2018	Please arrange for survey asap

Adrian Lij total: 5131.25  
 H/s 28/11/18 4/s: 4.11c.  
 06 days

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: