

22/03/2002

ASS. REC. BY:

REF: es/FCI18021481/Ktd3 n2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): CWS Sthelraof FCIDate/Time: 11:54am @ 28/11/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBF 6310KInsured: SHA 9514Aat Workshop m/s Siong Lee MotorTel: 64531255of 160 Sin Ming Drive # 02-07

Policy No:

Claim No: D18008427MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 25/11/18CA / REV / REP. / REV 24 HRS ^{lup}

H.O.D. Endorsement:

Date/Time: 12:22pm @ 28/11/18Person Contacted: Kwee pinVehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>GBF 6310K - x</u>
	<u>SHA 9514A - CS / QW08006281 / Ref</u>
	<u>lump sum confirm \$2450/- (Red 1963.20, 44%)</u>

JWA: 13/01/2018

ASS. REC. BY:

REF: K62Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 856k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 03 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBF 6310KYr Regn: 01, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Dynac.c. 2882Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 87220

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFAT 354 70K 20730Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: mic 195R 15x8R: Yoko 155R 13x8 (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 7 mmL/Bal. 6 mmL/Bal. 7 mmD.O.A. 23/11/18D.O.I. 28/11/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/11 File pass to Cathrine

RECEIVED 14 FEB 2019

Date/Time, File Pass to?

1) 14/2 Typist

Date/Time, File Return to?

2) _____

☐ : Prell. Report
☒ : Final ReportDays Of Repair: 3Resurvey No. of Trlp: 1Add Fee: ☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Format: TP

Lump Sum / I.B.I. (\$)

2450/-

135
50
50
20
255

MOTOR SURVEY ASSIGNMENT

Date	27-11-2018	Our Ref No. D18008427MFSH
Accident Date	25-11-2018	Claim Type. Third Party
Insured Vehicle	SHA9514A	Third Party Vehicle. GBF6310K
Survey Location	160 SING MING DRIVE #02-07 AUTOCITY	
Contact Person.	MR TAN / MS KWEE PIN	
Contact No.	6453 1255/ 64531255	Fax No. 63373700
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SIONG LEE MOTOR	Attention. NIL
Cc : TP Solicitor	CHEONGHOH LAW CORPORATION	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.



松 利 摩 哆 SIONG LEE MOTOR

Sin Ming Industrial Estate
Block 12 Sector B #01-73 Singapore 575656
Tel: 6457 0410, 6453 3478 Fax: 6552 0692

Company Reg. No.: 100838/00J

We specialise in repairing all kinds of vehicles and pre-inspection servicing.
We also undertake accident insurance claims for our customers.

28 November 2018

ATTN: MOTOR CLAIM DEPARTMENT

ATTN: TAN BROS GAS SUPPLY

H/P: 9105 5622

Dear Sirs / Madam,

**Accident Claim for Vehicle No.GBF 6310 K, Involving Vehicle No.SHA 9514 A.
Accident on 25 NOVEMBER 2018, AT ANG MO KIO AVE 8.**

With reference to the above vehicle. We hereby submit a list of parts required to be changed and append below the charges for changing and repairing ;

NO	SUPPLEMENTARY PARTS REPLACEMENT	QTY	LIST PRICE
1	FRONT BUMPER <i>566.10</i>	1PC	\$ <i>my dry</i> 799.30 <i>2</i>
2	HEADLAMP - LH	1PC	\$ <i>W</i> 633.30 <i>✓</i>
3	FRONT DOOR - LH <i>1450.50</i>	1PC	\$ <i>del/war</i> 1,587.80 <i>✓</i>
4	FRONT DOOR RUBBER - LH	1PC	\$ <i>sla</i> 128.90 <i>x</i>
5	FRONT DOOR HINGE - LH	2PCS	\$ <i>n</i> 341.36 <i>x</i>
6	FRONT STEP BOARD - LH <i>339.71</i>	1PC	\$ <i>Red/W</i> 488.35 <i>✓</i>
	TOTAL LIST PRICE		\$ 3,979.01
	LESS 20% <i>25%</i>		\$ (795.81)
	TOTAL AMOUNT		\$ 3,183.20

NO	PARTS REPLACEMENT	QTY	SPECIAL NETT PRICE
1	FRONT DOOR COMPANY LOGO - LG	1SET	\$ <i>m</i> 150.00 <i>20%</i>
2	FRONT DOOR BODY LETTERING - LH	1PC	\$ <i>m</i> 30.00 <i>20%</i>
	TOTAL SPECIAL NETT PRICE		\$ 180.00

	LABOUR :	
1	LABOUR TO SPRAY PAINT	\$ 600.00
2	LABOUR TO PANEL BEATING	\$ <i>360</i> 450.00
	TOTAL LABOUR	\$ 1,050.00
	TOTAL AMOUNT	\$ 4,413.20

THANK YOU

FROM:

SIONG LEE MOTOR

Mr Tan Leng Huat

Not with work
US, \$2450
Repair After Paint
3 days

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18021481/Ktd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 14-02-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9514A	Veh. Inspected	GBF 6310K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008427MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	28/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTFAT35Y70K207301	Colour	SILVER	
Odometer	87220	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	MICHELIN	6 mm	
L/H Front Tyre	195 R15X8	MICHELIN	6 mm	
R/H Rear Tyre	155 R13X8 (D)	YOKOHAMA	7/7 mm	
L/H Rear Tyre	155 R13X8 (D)	YOKOHAMA	7/7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/11/2018	Inspection Date	28/11/2018	
Survey held at	160 SIN MING DRIVE# 02-07			
Repairer	SIONG LEE MOTOR			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 6310K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	MTG DISTORTED	799.30	566.10
1	HEADLAMP-LH	CUT	633.30	633.30
1	FRONT DOOR-LH	DENTED / WARPED	1,587.80	1,450.50
1	FRONT DOOR RUBBER-LH	SERVICEABLE	128.90	-
2	FRONT DOOR HINGE-LH	TO REPAIR SEE LABOUR	341.36	-
1	FRONT STEP BOARD-LH	DENTED / CUT	488.35	339.71
	LESS 20% DISCOUNT		-795.81	-
	LESS 25% DISCOUNT		-	-747.40
			3,183.20	2,242.21
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT DOOR COMPANY LOGO-LG (SN)	NECESSARY	150.00	80.00
1	FRONT DOOR BODY LETTERING-LH (SN)	NECESSARY	30.00	20.00
			180.00	100.00
<u>LABOUR</u>				
	LABOUR TO SPRAY PAINT.		600.00	400.00
	LABOUR TO PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT DOOR HINGE-LH.		450.00	360.00
			1,050.00	760.00
GRAND TOTAL			4,413.20	3,102.21
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,450.00

Report Ref No. CS/FC\18021481/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.