

A.S. REC. BY:

REF:

CS/C11802/485/Dqd3

Special Instruction:

Surveyor:

Bryen

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

C11

Date/Time:

27/11/18 @ 12:15pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 352R

Insured:

GBF 2809R

at Workshop m/s

Team work

Tel:

68442475

of

53 Ubi Ave | #01-24

Policy No:

DmCVSN3066141801

Claim No:

SNM18D05500C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/11/18

CA / REV / REP. / REV 24 HRS^{1up}

H.O.D. Endorsement:

Date/Time:

2:37pm @ 27/11/18

Person Contacted:

Damen

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SLE 352R - NA/LIP1802/245/24

D.A.: 22/11/18

GBF 2809R - NA/LIP1802/245/24

D.A.: 22/11/18

Governing

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop n/s: _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 8LE 352R Yr Regn: July 2016
 Type: M.Ca / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Mitsubishi Attrage c.c. 1193Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 156574 T/Radio: Insured / Std / NI / NAEng/No: 3A92UDH3333C/No: MMBSTA13AHH001576Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/55 R15R: — " —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bridgestone

Front

Rear

R/Bal. S mm R/Bal. S mmL/Bal. S mm L/Bal. S mmD.O.A. 22/11/2018 D.O.I. 28/11/2018

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Teamwork Page ubi Rev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

China Teiping GBF2809R

20/12/19 June 2/5 37501 - with 6 days of rev
(Red to 3061.00, 45%)

RECEIVED 20 FEB 2019

Date/Time, File Pass to?

☐

: Prel. Report

11/20/2 Final☐

: Final Report

Date/Time, File Return to?

21

Days Of Repair: 6Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Photos

Fibers

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Invs (\$)☐ Weekend (\$)Report Format: MEP TP

Lump Sum / I.B.T. (\$)

3750

TOTAL

China Taiping Insurance (Singapore) Pte Ltd
105 Cecil Street #19-00
The Octagon
Singapore 069534

Vehicle number : SLE352R
Make / Model : MITSUBISHI / ATTRAGE
Chassis number : MMBSTA13AHH001576
Accident date : 27 November 2018
Reference : 1811-29

Qty Particulars

Unit Price - SGD \$

<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER <i>distorted</i>	705.00 ✓
1	REAR BUMPER TOW COVER NP	36.00 X
2	REAR BUMPER SIDE RETAINER <i>SVC</i>	36.00 X
2	REAR BUMPER REFLECTOR <i>SVC</i>	44.00 X
1	END PANEL <i>& Dented</i>	503.00 ✓
1	END PANEL KEYLESS SENSOR <i>& M4</i>	105.00 X
1	END PANEL TOP GARNISH <i>& mounting deformed</i>	75.00 ✓
2	REAR TAILLAMP <i>O/S crack N/S & mounting & crack</i>	476.00 ✓
1	BOOTLID <i>St</i>	928.00 ✓
1	BOOTLID WEATHERSTRIP <i>deformed</i>	168.00 ✓
1	BOOTLID EMBLEM <i>Rec</i>	51.00 ✓
1	BOOTLID EMBLEM - ATTERAGE <i>Rec</i>	42.00 ✓
1	BOOTLID EMBLEM - MIVEC <i>Rec</i>	49.00 ✓
1	BOOTLID LOCK <i>St & St</i>	256.00 ✓
1	BOOTLID STRIKER <i>Rec</i>	40.00 X
2	BOOTLID HINGE <i>M4</i>	192.00 X
1	SPARE TYRE TOP BOARD <i>M4</i>	185.00 X
		3891.00
	Less 10%	389.10
		3501.90
	Subtotal	3501.90
	Balance C/F	3501.90
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	3501.90
1 SET	REAR BUMPER CLIP <i>Rec</i>	50.00 30/-
1 SET	REAR REVERSE SENSOR <i>Don</i>	400.00 220/-
1	JOINT SEALANT <i>& M4</i>	150.00 X
	Subtotal	600.00
	Balance C/F	4101.90
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	4101.90
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 30/-

3253.00
2927.70

250/-

2	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	200.00	80/-
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00	40/-
4	REMOVE AND STRAIGHTEN REAR EXHAUST	150.00	NH
5	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00	60/-
6	PANEL BEATING ON AFFECTED AREAS	1000.00	700/-
7	SPRAY PAINTING ON AFFECTED AREAS	800.00	600/-
8	APPLY ANTI RUST ON AFFECTED AREAS	150.00	40/-
Subtotal		2710.00	
Grand total		6811.90	
28/11/2018 @ 1600hrs N/A Actual 1/2 hour 6 days. Tyger		4697.70 1/2 3750/-	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Tuesday, 27 November 2018 12:15 PM
To: TEAMWORK GARAGE CLAIMS
Cc: Lucas Lee; assignments; Admin A
Subject: CTP REF NO. GBF2809R TG REF : SLE352R - ACCIDENT INVOLVING GBF2809R AND SLE352R ON 22 NOVEMBER 2018

Dear Sir,

We refer to the above matter and our telephone conversation a moment ago.

As spoken, we will appoint LKK to survey your vehicle.

Aside to LKK: Please liaise with MS Letitia from Teamwork @ 6844-2475 for the PRS.

Thank you.

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/11/2018 13:41
Date Of Accident	22/11/2018 11:05
Exact Location Of Accident	KPE TWDS ECP BEFORE ENTERING KPE TUNNEL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE352R
Insured/Policyholder	
Name Of Registered Owner	ROSET LIMOUSINE SERVICES PTE LTD
Co Reg No	200406722Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	ATTRAGE 1.2 CVT
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V12322/VPZ/R00
Cover Note Number	
Driver	
Name of Driver	TAY CHENG YEW (ZHENG QINGYAO)
NRIC No	S8504545H
Date Of Birth	04/02/1985
Occupation	OUTDOOR
Date Of Driving Pass	27/04/2011
Driving Experience	7 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85777643
Fax Number	
Contact Number	OFFICE-85777643
Email Address	NOEMAIL

Address	BLK 268C COMPASSVALE LINK #04-17
Postcode	543268
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TAY KAH SIN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SENGKANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 2 SENGKANG SQUARE #01-02 SINGAPORE , POSTCODE: 545025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800 - 3438999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/201811232025.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF2809R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TAY KAH SIN

Approximate Age

Injuries Sustain NECK & BACK

Injured person in which vehicle? SLE352R

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

Accident Sketch Plan

IMPORTANT

NOTES TO READ

1. Please print accurately the details of the accident to speed up the claims process.
2. Your Name must be supplied for the **Purpose** stated under the **Subscribed Driver**.
3. Data received provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts from other insurers is considered to **invalidate your Policy**.
4. The report is a copy of the form to be submitted to the insurance companies to use in settlement of policy benefits on the part of the insureds involved.
5. **See below** on how to refer to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of this report as the source and to copies of this report being made available aforesaid.
8. Consents under the Personal Data Protection Act (PDPA)

police, and, where appropriate, agree and consent that:

- (a) my insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the regulatory authorities of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) settling and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/FIN No.:

Police Report

Report No. 120161123202	
Station No. 801-02 SINGAPORE	
Report of a Traffic Accident	
Police Report Made	Vide Report No.
Station Diary No.	34
Address: APT BLK 288C COMPASSVALE LINK 804-17 SINGAPORE	
Contact No.	Mobile: 85777643
Home/Office	
Email:	
SINGAPORE CITIZEN	
Age	Date of Birth: 04/02/1965
Type of Informant	
Language	Institution / School Name:
Driving Licence Information	Date of Expiry:
Class: 2	
Type of Accident	Time
Conveyed by Ambulance	Drive
Drive	Date/Time of Accident: 22/11/2018 10:20
Type of Location	
2-LANE 2-WAY ROAD EXPRESSWAY	
Road Surface	Road Spec. / Limit
Dry	
Traffic Control	Tram/Youne
Any one conveyed by Ambulance	No
Vehicle	No. of Passengers
NISSAN	0
MAZDA	1
Use of Pedestrian Crossing: NA	

Police Report

SINGAPORE
POLICE FORCE

T/20181123/2025

2 of 3

Report No. T/20181123/2025

Place of Origin
Singapore
Square 001-02 SINGAPORE
1341-343 8090

CONTINUATION OF REPORT

NAME	LOW QI MING	ID No.	S02327771
Vehicle	GBF2890R (Lorry)	Contact No.	98798637
Class of Licence	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Discharge	NIL	Degree of Injury	NIL
Medical Leave	NIL		
NAME	TAY CHENG YEW	ID No.	S8504545H
Vehicle	SLE352R (Car)	Contact No.	85777643
Class of Licence	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Discharge	NIL	Degree of Injury	NIL
Medical Leave	NIL		

Description

On 11/11/2018 at about 1030hrs, I was driving my rental vehicle SLE352R along KPE before the intersection of KPE and KPE. My sister S02327771, H/p: 93392602 was seated at the front left passenger seat. My sister was seated and slowly moving. I was in stationary mode when suddenly there was an impact on the rear of my vehicle. I got off my vehicle to make a check and realised that it was a lady who had fallen onto the rear of my vehicle.

I then called my sister to make a check on her. My sister told me that her neck is in pain. I then called an ambulance and my sister was conveyed to General Hospital for medical attention. The Police had arrived shortly after and I was given a reference report with regards to the incident. I was not given any reference report.

2018-11-2

Police Report

Report No. T20181121-2

2018-11-21

CONTINUATION OF REPORT

02 SINGAPORE

11/20/2018

Who provide sketch plan

Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have a copy, please fax a copy to 65474865 stating the report number as reference.

Signature of Reporting The Report:

Signature Of Informant

Date/Time
2011/2018/10:21

Classification Of Case

Classification Of Case

NAME WIN CHENG DANIEL

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Nov 2018		06 Dec 2018 13:30 Edit Adj Rpt	S\$3,750.00 Edit Estimates	S\$3,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	PERFECTION GENERAL SERVICES PTE LTD, Co. Reg. No.: A200917507M								
Main Claimant:	ROSET LIMOUSINE SERVICES PTE LTD, Co. Reg. No.: 200406722Z								
Vehicle Reg. No.:	SLE352R	Date of Loss:	22/11/2018 11:00 - :59 [28 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D05500C02	Policy/Cover Note No.:	DMCVSN3066141801 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBF2809R	Policy No. (Claimant):	SD18V12322/VPZ/R00						
		Excess:	S\$0.00						
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 17/12/2018]								
Driver/Custodian (Insured):	LOW QI MING (26 / Male), NRIC: S92327771, Tel: +6596798837								
Adj Asg. Remarks:	NO EST, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLE352R (SNM18D05500C02)**
[GBF2809R]
TP
ROSET LIMOUSINE SERVICES PTE LTD
Nov 22 2018 11:00AM
[PERFECTION GENERAL SERVICES PTE LTD]
Teamwork Garage Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		☒	
No	Finalized On	National Assessment Centre Services (Ubi)				Thumbnail	Print		
1	23/11/18 13:51	Accident Statement				Load HTM			
Photos/Images						3 per page		☒	
No	Finalized On	National Assessment Centre Services (Ubi)				Thumbnail	Print		
1	23/11/18 13:48	Accident Photo [Linked Accident Report Documents]				Load JPG	☒		
2	23/11/18 13:48	Accident Photo [Linked Accident Report Documents]				Load JPG	☒		
3	23/11/18 13:48	Accident Photo [Linked Accident Report Documents]				Load JPG	☒		
4	23/11/18 13:48	Accident Photo [Linked Accident Report Documents]				Load JPG	☒		
5	23/11/18 13:48	Accident Photo [Linked Accident Report Documents]				Load JPG	☒		
6	23/11/18 13:48	Accident Photo [Linked Accident Report Documents]				Load JPG	☒		
7	23/11/18 13:48	Accident Photo [Linked Accident Report Documents]				Load JPG	☒		
8	23/11/18 13:48	Accident Photo [Linked Accident Report Documents]				Load JPG	☒		
9	23/11/18 13:48	Accident Photo [Linked Accident Report Documents]				Load JPG	☒		
10	23/11/18 13:48	Accident Photo [Linked Accident Report Documents]				Load JPG	☒		
11	23/11/18 13:48	Accident Photo [Linked Accident Report Documents]				Load JPG	☒		
12	23/11/18 13:48	Accident Photo [Linked Accident Report Documents]				Load JPG	☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print		
1	29/01/19 09:52	Rear View Left				Load JPG	☒		
2	29/01/19 09:52	Rear View Right				Load JPG	☒		
3	29/01/19 09:52	General View				Load JPG	☒		
4	29/01/19 09:52	General View				Load JPG	☒		
5	29/01/19 09:52	General View				Load JPG	☒		
6	29/01/19 09:52	General View				Load JPG	☒		
7	29/01/19 09:52	General View				Load JPG	☒		
8	29/01/19 09:52	General View				Load JPG	☒		
9	29/01/19 09:52	General View				Load JPG	☒		
10	29/01/19 09:52	General View				Load JPG	☒		
11	29/01/19 09:52	General View				Load JPG	☒		
12	29/01/19 09:52	General View				Load JPG	☒		
13	29/01/19 09:52	General View				Load JPG	☒		
14	29/01/19 09:52	General View				Load JPG	☒		
15	29/01/19 09:52	General View				Load JPG	☒		
16	29/01/19 09:52	General View				Load JPG	☒		
17	29/01/19 09:52	General View				Load JPG	☒		

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
				☒
18	29/01/19 09:52	General View	 Load JPG	☒
19	29/01/19 09:52	General View	 Load JPG	☒
20	29/01/19 09:52	General View	 Load JPG	☒
21	29/01/19 09:52	General View	 Load JPG	☒
22	29/01/19 09:52	General View	 Load JPG	☒
23	29/01/19 09:52	General View	 Load JPG	☒
24	29/01/19 09:52	General View	 Load JPG	☒
25	29/01/19 09:52	General View	 Load JPG	☒
26	29/01/19 09:52	General View	 Load JPG	☒
27	29/01/19 09:52	General View	 Load JPG	☒
28	29/01/19 09:52	General View	 Load JPG	☒
29	29/01/19 09:52	General View	 Load JPG	☒
30	29/01/19 09:52	General View	 Load JPG	☒
31	29/01/19 09:52	General View	 Load JPG	☒
32	29/01/19 09:52	General View	 Load JPG	☒
33	29/01/19 09:52	General View	 Load JPG	☒
34	29/01/19 09:52	General View	 Load JPG	☒
35	29/01/19 09:52	General View	 Load JPG	☒
36	29/01/19 09:52	General View	 Load JPG	☒
37	29/01/19 09:52	Odometer Reading	 Load JPG	☒
38	29/01/19 09:52	Chassis Number	 Load JPG	☒
39	29/01/19 09:52	Reinspection Photo	 Load JPG	☒
40	29/01/19 09:52	Reinspection Photo	 Load JPG	☒
41	29/01/19 09:52	Reinspection Photo	 Load JPG	☒
42	29/01/19 09:52	Reinspection Photo	 Load JPG	☒
43	29/01/19 09:52	Reinspection Photo	 Load JPG	☒
44	29/01/19 09:52	Reinspection Photo	 Load JPG	☒
45	29/01/19 09:52	Reinspection Photo	 Load JPG	☒
46	29/01/19 09:53	Reinspection Photo	 Load JPG	☒
47	29/01/19 09:53	Reinspection Photo	 Load JPG	☒
48	29/01/19 09:53	Reinspection Photo	 Load JPG	☒
49	29/01/19 09:53	Reinspection Photo	 Load JPG	☒
50	29/01/19 09:53	Reinspection Photo	 Load JPG	☒
51	29/01/19 09:53	Reinspection Photo	 Load JPG	☒
52	29/01/19 09:53	Reinspection Photo	 Load JPG	☒
53	29/01/19 09:53	Reinspection Photo	 Load JPG	☒
54	29/01/19 09:53	Reinspection Photo	 Load JPG	☒
55	29/01/19 09:53	Reinspection Photo	 Load JPG	☒
56	29/01/19 09:53	Reinspection Photo	 Load JPG	☒
57	29/01/19 09:53	Reinspection Photo	 Load JPG	☒
58	29/01/19 09:53	Reinspection Photo	 Load JPG	☒
59	29/01/19 09:53	Reinspection Photo	 Load JPG	☒
60	29/01/19 09:53	Reinspection Photo	 Load JPG	☒
61	29/01/19 09:53	Reinspection Photo	 Load JPG	☒
62	29/01/19 09:53	Reinspection Photo	 Load JPG	☒
63	29/01/19 09:53	Reinspection Photo	Load JPG	☒
64	29/01/19 09:53	Reinspection Photo	Load JPG	☒
65	29/01/19 09:53	Reinspection Photo	Load JPG	☒
66	29/01/19 09:53	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☐
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
67	29/01/19 09:53	Reinspection Photo		☒
68	29/01/19 09:53	Reinspection Photo		☒
69	29/01/19 09:53	Reinspection Photo		☒
70	29/01/19 09:53	Reinspection Photo		☒
71	29/01/19 09:53	Reinspection Photo		☒
72	29/01/19 09:53	Reinspection Photo		☒
73	29/01/19 09:53	Reinspection Photo		☒
74	29/01/19 09:53	Reinspection Photo		☒
75	29/01/19 09:53	Finishing Photo		☒
76	29/01/19 09:53	Finishing Photo		☒
77	29/01/19 09:53	Finishing Photo		☒
78	29/01/19 09:53	Finishing Photo		☒
79	29/01/19 09:53	Finishing Photo		☒
80	29/01/19 09:53	Finishing Photo		☒
81	29/01/19 09:53	Finishing Photo		☒
82	29/01/19 09:53	Finishing Photo		☒
83	29/01/19 09:53	Finishing Photo		☒
84	29/01/19 09:53	Finishing Photo		☒
85	29/01/19 09:53	Finishing Photo		☒
86	29/01/19 09:53	Finishing Photo		☒
87	29/01/19 09:53	Finishing Photo		☒
88	29/01/19 09:53	Finishing Photo		☒
89	29/01/19 09:53	Finishing Photo		☒
90	29/01/19 09:53	Finishing Photo		☒
91	29/01/19 09:53	Finishing Photo		☒
92	29/01/19 09:53	Finishing Photo		☒
Documentation			1 per page	☐
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/12/18 13:30	PRS		☐
2	06/12/18 13:30	OI GIA		☐
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	23/11/18 13:49	Accident Sketch Plan [Linked Accident Report Documents]		☒
2	23/11/18 13:49	Accident Sketch Plan [Linked Accident Report Documents]		☒
3	23/11/18 13:49	Police Report [Linked Accident Report Documents]		☒
4	23/11/18 13:49	Police Report [Linked Accident Report Documents]		☒
5	23/11/18 13:49	Police Report [Linked Accident Report Documents]		☒

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	23/11/18 13:51	Accident Statement		☐
Photos/Images			3 per page	☐
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	23/11/18 13:48	Accident Photo		☒
2	23/11/18 13:48	Accident Photo		☒
3	23/11/18 13:48	Accident Photo		☒

Assessment Reports				1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
4	23/11/18 13:48	Accident Photo		Load JPG	☒
5	23/11/18 13:48	Accident Photo		Load JPG	☒
6	23/11/18 13:48	Accident Photo		Load JPG	☒
7	23/11/18 13:48	Accident Photo		Load JPG	☒
8	23/11/18 13:48	Accident Photo		Load JPG	☒
9	23/11/18 13:48	Accident Photo		Load JPG	☒
10	23/11/18 13:48	Accident Photo		Load JPG	☒
11	23/11/18 13:48	Accident Photo		Load JPG	☒
12	23/11/18 13:48	Accident Photo		Load JPG	☒

Documentation				1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	23/11/18 13:49	Accident Sketch Plan		Load JPG	☒
2	23/11/18 13:49	Accident Sketch Plan		Load JPG	☒
3	23/11/18 13:49	Police Report		Load JPG	☒
4	23/11/18 13:49	Police Report		Load JPG	☒
5	23/11/18 13:49	Police Report		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118021485/DQD3Q2

Date: 20/02/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3066141801

Claimant Vehicle
No: SLE352RInsured Vehicle
No: GBF2809R

Date of Loss: 22/11/2018

Nature of Claim: TP

Claim
No: SNM18D05500C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLE352R

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A)

Engine No: 3A92UDH3333

Reg. Date: 04/07/2016 (Man. Year: 2016)

Chassis No: MMBSTA13AHH001576

Colour: Grey

Odometer: 156574 km

Engine Capacity: 1193 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15

Rear Tyre Size: 185/55 R15

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,101.90	3,177.70	924.20	22.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,710.00	1,550.00	1,160.00	42.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,811.90	4,727.70	2,084.20	30.60
Approved Total (Overridden) (S\$)		3,750.00		
(S\$)	6,811.90	3,750.00	3,061.90	44.95
+ GST 7.00/7.00% (S\$)	476.83	262.50	214.33	44.95
Nett Amount (S\$)	7,288.73	4,012.50	3,276.23	44.95

INSPECTION

Date of Assignment: 06/12/2018

Date Inspected: 28/11/2018 Inspected At:

Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi Industrial
Park
Singapore 408934

Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Feb 2019)	
Parts:	N/A	mitsubishi attrage 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE352R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	705.00 FL	*705.00 FL
2	1		*REAR BUMPER TOW COVER	Not fitted	36.00 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER	Serviceable	36.00 FL	*- FL
4	2		*REAR BUMPER REFLECTOR	Serviceable	44.00 FL	*- FL
5	1		*END PANEL	Dented	503.00 FL	*503.00 FL
6	1		*END PANEL KEYLESS SENSOR	Not Necessary	105.00 FL	*- FL
7	1		*END PANEL TOP GARNISH	Mtg Deformed	75.00 FL	*75.00 FL
8	2		*REAR TAILLAMP	O/S Cracked / N/S Mtg Cracked	476.00 FL	*476.00 FL
9	1		*BOOTLID	Bent	928.00 FL	*928.00 FL
10	1		*BOOTLID WEATHERSTRIP	Deformed	168.00 FL	*168.00 FL
11	1		*BOOTLID EMBLEM	Necessary	51.00 FL	*51.00 FL
12	1		*BOOTLID EMBLEM -ATTRAGE	Necessary	42.00 FL	*42.00 FL
13	1		*BOOTLID EMBLEM -MIVEC	Necessary	49.00 FL	*49.00 FL
14	1		*BOOTLID LOCK	Bent	256.00 FL	*256.00 FL
15	1		*BOOTLID STRIKER	Repair	40.00 FL	*- FL
16	2		*BOOTLID HINGE	Not Necessary	192.00 FL	*- FL
17	1		*SPARE TYRE TOP BOARD	Not Necessary	185.00 FL	*- FL
18	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
19	1		*SET REAR REVERSE SENSOR	Damaged	400.00 FS	*220.00 FS
20	1		*JOINT SEALANT	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,491.00	3,503.00
- List Item Discount on L Items 10.00/10.00% (S\$)	389.10	325.30
Total Parts (S\$)	4,101.90	3,177.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	REMOVE AND REFIT REAR LINING ,TRIM AND GARNISH	New	200.00	80.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	40.00
4	REMOVE AND STRAIGHTEN REAR EXHAUST	New	150.00	0.00
5	TRANSFER PARTS ,ATTACHMENT FROM OLD BOOTLID TO NEW	New	200.00	60.00
6	PANEL BEATING ON AFFECTED AREAS	New	1,000.00	700.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	800.00	600.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	40.00
Gross Labour Cost (\$\$)			2,710.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >