

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 849H

MAKE :

MODEL : HYUNDAI i40

DATE 26/11/2018 14:40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 553.00
	Rear Bumper Reinforcement ?			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs			\$ 22.00
	Rear Bumper Bracket ?		\$ 35.60	\$ 71.20
	Rear Bumper Sponge ?			\$ 103.50
	Rear Bumper Under Cover			\$ 228.00
	SUB TOTAL			\$ 1,566.70
	LESS 20%			\$ 313.34
	DISCOUNTED TOTAL			\$ 1,253.36
	Rear Bumper Rubber Mat			\$ 50.00 Nett
	Rear Bumper Advertisement Logo			\$ 50.00 Nett
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00 Nett
	Rear Bumper Reverse Sensor X			\$ 135.70 Nett
				\$ 435.70
	Labour Charge			
	Panel Beating			\$ 350.00 ²⁰⁰
	Spray Painting Charge			\$ 250.00 ²⁰⁰
	Wiring Charge			\$ 30.00 X
	Remove/Refix Reverse Sensor			\$ 80.00 30
	TOTAL LABOUR			\$ 710.00
	ESTIMATE TOTAL			\$ 2,399.06
<i>Kahni 10/11/18</i> <i>27/11/18 1100 hrs</i> <i>2 Pys</i> <i>PIP</i> <i>Before P-4 photo</i> Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK/kahni

PbyP

Like

CHINA