

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

26-Nov-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1859 S

1 pc	Rear bumper	\$	696.00
1 pc	Rear bumper lower cover	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00
1 pc	Rear bumper reflector - o/s	\$	46.00
			<hr/>
			\$ 1,006.00
Less 10%			\$ 100.60
			<hr/>
			\$ 905.40

S/NETT

1 set	Rear bumper clips	\$	48.00
1 set	Reverse sensor	\$	280.00 200
1 pc	Rear bumper top protector	\$	80.00 50
Sundry			\$ 50.00 X
To dismantle / replace reverse sensor to new bumper and reset to the same			\$ 120.00 30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.			\$ 180.00 X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc.			\$ 650.00 200
To putty and spray painting on rear bumper, end panel			\$ 180.00 180
To apply rustproofing on the repaired and replaced panels.			\$ 150.00 X
			<hr/>
			\$ 3,013.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display during resurvey
- Parts price are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin 10/11/18
27/11/18 1030hr
2 Pys
L/S
After Reps pht