



Vfix Auto Pte Ltd
60 Kaki Bukit Ave 6 Ark@KB
Singapore 417892
Email : contact@vfixauto.com.sg
Tel : 6448 9268 Fax: 6445 2368
UEN / GST Reg No. : 201830761R

EQ INSURANCE CO LTD
5 MAXWELL ROAD
#17-00 TOWER BK / MND COMPLEX
SINGAPORE 069110

ESTIMATE

DATE : 27/11/2018
ACC DATE : 24/11/2018
REF NO : VFIX - TP20180564
POLICY NO :

ATTN TO : MOTOR CLAIM DEPT
RE : VEHICLE NO : PA8423R TOYOYA XZB59R

DESCRIPTIONS	AMOUNT S\$
1 1 FRONT BUMPER <i>BT</i>	1,435.10
2 1 HEADLAMP RH <i>BR</i>	985.80
3 1 HEADLAMP PANEL RH <i>?</i>	125.00
4 1 FOG LAMP RH <i>?</i>	325.80
5 1 FOG LAMP COVER RH <i>cut</i>	148.80
	\$ 3,020.50
	<i>06/12/18</i> less 25%
	\$ 755.13
	\$ 2,265.37

Resurvey after repair

SPECIAL NETT ITEM	UNIT PRICE	AMOUNT S\$
1 2 HEADLAMP CLIP <i>new</i>	8.50	\$ 17.00 SN

LABOUR & MISCELLANEOUS:	AMOUNT S\$
1 To remove, replace damaged parts apply hot works straighten headlamp panel where necessary. replace new parts	<i>700</i> 1,000.00
2 To spray paint replaced/repared body panels inclusive of preparatory works and painting materials	<i>700</i> 800.00
3 To conduct headlamp headlamp alignments	30.00
	\$ 1,830.00

GRAND TOTAL : \$ 4,112.37

SINGAPORE DOLLARS : FOUR THOUSAND, ONE HUNDRED TWELVE & CENTS THIRTY SEVEN ONLY

Vfix Auto Pte Ltd

