

Signature

Paran

REF:

NS/INC18021512/R1td3sr

ASSIGNMENT

From:

Date:

26/11/18

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHB 5717C

at Workshop m/s

SMRT

of

1 kaki Bkt Ave 6 #01-58

Insured:

SHD 2364X

Policy No.

5068045737-04 19/10/18-

Claims No.

WT/1020937-002

Sum Insured

Excess:

(Client's Record)

Make of Veh:

Zhi yang @ 9101 7563

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

(up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHB 5717C

Yr Regn: 2017 / 04

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA PRIUS 1.8A

C.C.

1798

Colour:

Maroon

A/C:

Insured / Std / NI / NA

Sp. Reading

-

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKBFU 3035-72967

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F:

PS/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Wagtlake

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

22/11/18

D.O.I.

26/11/18

Survey held at

SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Fnt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SHB 5717C - NS/INC18007245/Sr bna

DUA: 18/4/18

11/18/2018

SHD 2364X - CS/FC5 7024113/R1td3sr

DUA: 16/12/17

WMC

part by part \$2236.87 (red: 4247.53) 650%

SHD 2364X

Date/Time, File Pass to?

☐

: Preli. Report

1) 8/2 Typist

☒

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation

) 3 + RS \$

) Photos

) Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

TP

Lump Sum / (B): (\$

2236.87

Denise Tay (LKKAUTO)

From: mtreg <mtreg@income.com.sg>
Sent: Friday, 8 February 2019 12:05 PM
To: Denise Tay (LKKAUTO)
Subject: FW: REQUEST CLAIM NUMBER

Hi,

All claims created.

With Regards

Samsia
Senior Admin Assistant,
Motor Insurance
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers



*'With effect from 1 Mar 2019, we will be discontinuing mailbox, mtreg@income.com.sg.
Please forward all motor claims related correspondences to mtcl@income.com.sg so that we can attend to it accordingly.'*

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Friday, 8 February 2019 9:57 AM
To: mtreg <mtreg@income.com.sg>
Subject: REQUEST CLAIM NUMBER

TP Claims against NTUC Income: Follow-Through Survey

Date : 8/2/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1020988-002	SMRT Taxis	SHB 5717C	SHD 2364X	22/11/2018	07:25	6,484.40	2236.87
2	MT/1020457-002	SMRT Taxis	SHC 4510H	SGE2857Y	17/11/2018	19:50	9,484.30	1551.85

Claim received from LKK Auto

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="22/11/2018 18:01"/>
Vehicle No.(For Motor)	<input type="text" value="SHD2364X"/>	Certificate Number	<input type="text"/>
<input type="button" value="Search"/>			

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5068045737-04		PRIME CAR RENTAL & TAXI SERVICES PTE. LTD.	199606293Z	GFT	Third Party, Fire & Theft	SHD2364X	SHD2364X	09/10/2018	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/11/2018 11:04
Date Of Accident	22/11/2018 07:25
Exact Location Of Accident	AIRPORT BOULEVARD TOWARDS CITY OUTSIDE T3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5717C
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	
Driver	
Name of Driver	LEOW LOONG CHONG
NRIC No	S7636617I
Date Of Birth	07/11/1976
Occupation	OUTDOOR
Date Of Driving Pass	09/09/2003
Driving Experience	15 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	174
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	AFTER RAIN
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG AIRPORT BOULEVARD AT THE RIGHT LANE WHEN THE TAXI SHD2364X FROM THE LEFT LANE ABRUPTLY CUT INTO MY LANE AND COLLIDED ONTO THE LEFT FRONT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SHD2364X
Vehicle Make/Model/Colour	PRIME
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	KOH KOK PHENG
NRIC/Passport Number	S6938985F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Leow Boon Chong
 22/11/2018
 1105 hrs.


22/11/2018

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



A-SHR 5717C
B-SHO 2364X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Date & Time: 7/11/2018 1105hrs.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SHB5717C
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Scheme:	Taxi (Company)
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Chassis No.:	JTDKB3FU303572967
Propellant:	Petrol-Electric
Engine No.:	2ZRS098118
Motor No.:	1NMS098118
Engine Capacity:	1798 cc
Power Rating:	53.0 kW
Maximum Power Output:	90.0 kW (120 bhp)
Maximum Laden Weight:	1790 kg
Unladen Weight:	1375 kg
Year Of Manufacture:	2017
Original Registration Date:	12 Oct 2017
Lifespan Expiry Date:	11 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
PQP Paid:	\$34,052.00
COE Expiry Date:	11 Oct 2025
Road Tax Expiry Date:	11 Apr 2019
PARF Eligibility Expiry Date:	11 Oct 2025
Inspection Due Date:	11 Oct 2019
Intended Transfer Date:	08 Feb 2019
CO2 Emission:	87.00 (g/km)
CEV/VES Rebate Utilised	\$27,610.00
Amount:	
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 11 Apr 2019. You may renew the road tax from 12 Jan 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 11 Apr 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 12 Apr 2019 to 11 Oct 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	510.00	-	510.00
Total Amount Payable:			535.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

[OK](#)
[Print](#)



Case Details

Case Reference Number : TAX/11/18/2098
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB5717C

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-4652-ID
 Assigned By : Kok Wah Wong

Insurance Company Name : NTUC Income Insurance Co-operative Ltd
 Accident Date and Time : 21/11/2018 11:25 PM
 Vehicle Age(In Months) : 13

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace
				<i>sub</i>									
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0	Not Give
				<i>XAN</i>									
One Time Key In	Main			LAMP ASSY, FOG, LH	1	910.20	910.20	10.00	819.18	Replace	0	0	Not Give
				<i>XAN</i>									
One Time Key In	Main			FENDER SUB-ASSY, FR, LH	1	933.10	933.10	25.00	699.83	Replace	1	699.83	Replace
				<i>HA</i>									
One Time Key In	Main			LINER, FR FENDER, LH	1	194.30	194.30	25.00	145.73	Replace	1	145.73	Replace
				<i>BE</i>									
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67	Replace
				<i>nu</i>					39.63				
One Time Key In	Main			WHEEL, DISC FRONT	1	1,555.10	1,555.10	25.00	1,166.32	Replace	1	0	Repair
				<i>Repair</i>									
Total Spare Part Cost									3,304.08		Surveyor Total	1,256.86	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	0	
Final Spare Part Cost									3,304.08		Final Sur Total	1,256.86	

Labour's Cost Detail

6484.40

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR FRONT LH PORTION	845.00	400	
Total:		845.00	400.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY FRONT BUMPER	378.00	200	
2	TO RESPRAY FRONT FENDER LH	378.00	200	
3	TO RESPRAY RIM	180.00	50	
Total:		936.00	450.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	Xnn
2	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40	
3	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	
4	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30	
5	TO WASH AND VACUUM	60.00	0	Xnn
Total:		480.00	130.00	


Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,304.08	1,256.86
Total Labour Cost	845.00	400.00
Total Spray Painting	936.00	450.00
Other	480.00	130.00
Overall Total	5,565.08	2,236.86
Lump Sum Repair Option		

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Lump Sum Total	0.00	2,236.86
Surveyor Approved Amount		2,236.86
No of Repair Days*	5	4
Remarks		resurvey before paint / part by part
Surveyor Name		Rasul
Signature		
Survey Date	26/11/2018	<input type="button" value="Save"/> <input type="button" value="Clear"/>

Section A - Accident Details

Registration Number	SHB5717C
Case Reference Number	TAX/11/18/2098
Registration Date	12/10/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	LEOW LOONG CHONG (LIAO LONGZHANG)
Type of Accident	Side Swipe
Accident Date and Time	22/11/2018 7:25 AM
Accident Reported Date and Time	22/11/2018 11:05 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24098862
Special Instruction to ARC, if any	PRIME /NTUC - LKK
Prepared Date and Time	23/11/2018 1:49 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$400.00
Total Spray Cost	\$936.00	\$450.00
Total Spare Part Cost	\$3,304.08	\$1,256.87
Total Other Cost	\$460.00	\$130.00
TOTAL COST	\$5,565.08	\$2,236.87 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	23/11/2018 4:29 PM	26/11/2018 4:37 PM
Signature		
Remarks		resurvey before paint / part by part

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1812-0030	Invoice Number	
Quotation Date	04.12.2018	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$845.00	\$400.00
Total Labour	\$845.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
Total Spray Painting & Panel Beating	\$936.00	\$450.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$480.00	\$130.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119479 62	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace
		52116470 50	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Not Given X
		81220470 20	LAMP ASSY, FOG, LH	0.00	\$910.20	0.00	\$0.00	Replace	Not Given X
		53802471 00	FENDER SUB-ASSY, FR, LH	1.00	\$933.10	25.00	\$699.83	Replace	Replace
		53876471 10	LINER, FR FENDER, LH	1.00	\$194.30	25.00	\$145.73	Replace	Replace
		75374471 40	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace
		42611-47450	WHEEL, DISC FRONT	1.00	\$1,555.10	100.00	\$0.00	Replace	Repair
Total					\$4,223.40		\$1,256.87		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1256.87
+ 400.00
+ 580.00
2236.87



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18021512/R1td3s2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 08-02-2019



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 2364X	Veh. Inspected	SHB 5717C
Policy No.	5068045737-04	Coverage (\$)	0.00
Claim No.	MT/1020988-002	Excess (\$)	0.00
Assign From		Assign Date	26/11/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS 1.8A	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU303572967	Colour	MAROON
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	WEST LAKE	5 mm
L/H Front Tyre	195/65R15	WEST LAKE	5 mm
R/H Rear Tyre	195/65R15	WEST LAKE	5 mm
L/H Rear Tyre	195/65R15	WEST LAKE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/11/2018	Inspection Date	26/11/2018
Survey held at	1 KAKI BUKIT AVE 6 #01-58 SINGAPORE 417883		
Repairer	SMRT AUTOMOTIVE SERVICES PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5717C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER, FR BUMPER (DISC 25%)	SCRATCHED	495.50	371.63
1	FENDER SUB-ASSY, FR, LH (DISC 25%)	BENT	933.10	699.83
1	LINER, FR FENDER, LH (DISC 25%)	DEFORMED	194.30	145.73
1	EMBLEM, SIDE PANEL (HYBRID) (DISC 25%)	NECESSARY	52.90	39.68
1	SUPPORT FR BUMPER LH	NOT NECESSARY	82.30	-
1	LAMP ASSY, FOG, LH	NOT NECESSARY	910.20	-
1	WHEEL, DISC FRONT	TO REPAIR SEE LABOUR	1,555.10	-
			4,223.40	1,256.87
LABOUR				
	PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF WHEEL, DISC FRONT.		845.00	400.00
	SPRAY PAINT.		936.00	450.00
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	80.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	40.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.		120.00	60.00
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)		120.00	30.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,261.00	980.00
GRAND TOTAL			6,484.40	2,236.87
RECOMMENDED COST OF REPAIRS (CONFIRMED)				2,236.87

Report Ref No. NS/INC18021512/R1td3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.