



Section A - Accident Details

Registration Number	SHC4497M
Case Reference Number	TAX/11/18/2097
Registration Date	20/8/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	CHUA SOON HENG VINCENT
Type of Accident	Side Swipe
Accident Date and Time	22/11/2018 8:30 AM
Accident Reported Date and Time	22/11/2018 10:43 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24098879
Special Instruction to ARC, if any	TSS
Prepared Date and Time	23/11/2018 7:14 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Diagram

Section B - Summary of Repair Estimates
Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$400.00
Total Spray Cost	\$1,854.00	\$700.00
Total Spare Part Cost	\$7,104.08	\$2,005.65
Total Other Cost	\$608.44	(\$405.65)
TOTAL COST	\$10,242.52	\$2,700.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	5.0
Prepared / Adjusted By	Kim Ming Chin	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	21/01/2019 11:10 AM	26/11/2018 4:23 PM
Signature		
Remarks	Initial estimate = 6 days Request number of days to extend 1 day	lump sum repair resurvey after paint

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1901-0496	Invoice Number	
Quotation Date	24.01.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$676.00	\$400.00
Total Labour	\$676.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO REPSRAY FRONT HOOD	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$100.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY FRONT WHEEL HOUSE RH	\$180.00	\$0.00
TO RESPRAY RIM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,854.00	\$700.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$684.09)
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$148.44	\$148.44
Total Other Costs	\$608.44	(\$405.65)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace ✓
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace ✓
		52115-47040	BUMPER SUPPORT F/RH	1.00	\$76.40	25.00	\$57.30	Replace	Replace ✓
		52611-47080	BUMPER ENERGY	0.00	\$78.80	0.00	\$0.00	Replace	Check X
		52021-47023	BUMPER REINFORCEME	0.00	\$498.40	0.00	\$0.00	Replace	Check X
		57013-47030	ARM SUB-ASSY, FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Check X
		53102-47020	BUMPER GRILLE SUB-	0.00	\$311.10	0.00	\$0.00	Replace	Check X
		81511-47050	LENS & BODY, FR TURN RH	1.00	\$511.80	10.00	\$460.62	Replace	Replace ✓

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 24/01/2019

User ID : PohSuan

	81519-47060	BRACKET, FR TURN	0.00	\$58.20	0.00	\$0.00	Replace	Check	X
	81519-47060	BRACKET, FR TURN UPPER	0.00	\$24.40	0.00	\$0.00	Replace	Check	X
	81519-47050	BRACKET, FR TURN LOWER	0.00	\$26.00	0.00	\$0.00	Replace	Check	X
	76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Check	X
	52618-47050	BUMPER FRT ABSORBER	0.00	\$127.70	0.00	\$0.00	Replace	Check	X
	53301-47060	HOOD PANEL	1.00	\$748.10	100.00	\$0.00	Replace	Repair	R
	53201-47902	SUPPORT SUB-ASSY	1.00	\$1,460.40	100.00	\$0.00	Replace	Repair	R
	81130-47500	HEAD LAMP RH	1.00	\$945.20	10.00	\$850.68	Replace	Replace	/
	85315-47140	WIPER WASHER JAR	0.00	\$180.10	0.00	\$0.00	Replace	Check	X
	53801-47050	FENDER FRT/RH	1.00	\$723.40	100.00	\$0.00	Replace	Repair	R
	75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	/
	53875-47030	FENDER LINER FRT/RH	1.00	\$171.70	25.00	\$128.78	Replace	Replace	/
	53851-47040	FENDER LINER PAD, FR	1.00	\$49.30	100.00	\$0.00	Replace	Repair	R
	53701-47050	FENDER APRON SUB FRT/RH	0.00	\$637.80	0.00	\$0.00	Replace	Not Given	X
	42611-47140(Frt)	WHEEL DISC. FRONT	0.00	\$1,484.20	0.00	\$0.00	Replace	Not Given	X
Total				\$9,038.51		\$1,909.89			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52618-47050	BUMPER FRT ABSORBER	1.00	\$127.70	25.00	\$95.78	Replace	Replace
Total					127.70		95.78		

$$\begin{array}{r}
 2005.67 \\
 + 400.00 \\
 + 978.44 \\
 \hline
 3384.11 \\
 - 202 \\
 \hline
 2707.29 \\
 \hline
 \text{Us \$2700/-}
 \end{array}$$